## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/2016/SZ/ | 5 | 8

Dated: 17/10/16

## FIRE SAFETY CERTIFICATE

Certified that the The Trillion Motel Pvt. Ltd., KH No.-218/3/2, 218/3/3, 219/1, 220, 222/2, 223/1 M. G. Road, Village Sultanpur, New Delhi, comprised of Basement, Ground floor & First Floor only 14 guest rooms has already been issued FSC by this department vide letter F6/DFS/MS/EH/2013/SZ/1208 Dated 14/11/2013. The premises was re-inspected by the officer concerned of this department on 06/10/2016in the presence of Mr. Naveen Jha & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Group A "Residential Building" with effect 1 2016 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 1.7. 1.5 ... at New Delhi by.

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

Copy to:-

1. The Dy. Health Officer, MCD, South Zone, Green Park, New Delhi.

2. Authorized Signatory, The Trillion Motel Pvt. Ltd., KH No.-218/3/2, 218/3/3, 219/1, 220, 222/2, 223/1 M. G. Road, Village Sultanpur, New Delhi

## Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.

6. The Basement Shall be used as per BBL-1983 only.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

**INSPECTION REPORT** 1. Name & address of the building: The Trillion Motel Pvt. Ltd., KH No.-218/3/2, 218/3/3, 219/1, 220, 222/2, 223/1 M. G. Road, Village Sultanpur, New Delhi : Group A "Residential" (Motel) Building [basement+GF+1st F] 2. Type of Occupancy 3. Type of Case : Renewal : F6/DFS/MS/EH/2013/SZ/1208 Dated 14/11/2013 4. Details of Previous NOC 5. Fire Safety directives letter No : F6/MS/DFS/GH/2001/261 Dated 12/02/2001 : 06/10/2016 6. Date of inspection : A.K. Malik. 7. Name of Inspecting Officer 8. Name and designation of officers : Mr. Naveen Jha From the building side : 2005 Year of Construction : Nil Dated 23/09/16 (outdoor diary no. 9868 dated 27/09/16) 10. Applicant's letter No. Provided at site Remarks Minimum Standards on fire prevention **Old NOC** S. MR/NMR (15-12-2010)No and fire safety U/R 33 Requirement 1. Access to building Accessible 30m MR Road width  $2 \times 5.33 \text{m} + 3.69 \text{m}$ MR Adequate Gate width 6m -NA--NA-Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases MR Required 2 Nos Upper Floors 4 Nos MR Required Basements b. Width of staircases MR(old case) 1.07m & 1.28m 1.25m Upper Floor 2 x 1.25m + 2 x 1.70m MR(old case) 1.25m Basements c. Protection of exits MR Provided Required Fire check door -NA--NA--NA-Pressurization MR 1 No Required d. No. of continuous staircases to terrace NA 1.8m NA Width of Corridor Provided(Final Exit) MR 1m Door Size 3. Compartmentation MR Required Provided Fire check door MR Provided Sealing of electrical shafts Required Fire Rating of shaft door -NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA--NA-4. **Smoke Management System** M.V.S. provided MR 30 ACPH Basements Natural ventilation -NA-12 ACPH Upper floors Fire Extinguishers 5. MR Total 24 No's Total numbers Portable Fire ABC-14 No's, MR Types Extinguishers  $W.Co_2-10 No's$ , IS marking -NA-Yes First-Aid Hose Reels 6. MR Hose Reels 2 No's Total numbers on each floor Provided MR Length of hose reel hose Provided MR Nozzle diameter Automatic fire detection and alarming system 7. MR Smoke & Heat Type of detectors Required Location of Main Panel -NA--NA-Fire Pump House Location of Repeater Panel -NA--NA-**Entrance Lobby** Alternate source of power MR Required Provided

The Trillion Motel Pvt. Ltd., M. G. Road, Village Sultanpur, New Delni

10 4-	Itomatia Sprinklar System	30, 30, 30, 30, 30, 30, 30, 30, 30, 30,		
10. Au	<ul><li>Itomatic Sprinkler System</li><li>Basement</li></ul>	Required	Provided	MR
	Ground Floor	Required	Provided	MR
	<ul> <li>Sprinkler above false ceiling</li> </ul>	Required	Provided	MR
11. Int	ternal Hydrants	1		
	Size of riser/down-comer	Required	100mm	MR
	<ul> <li>Number of hydrants per floor</li> </ul>	Required	2 Nos	MR
	Hose Box	Required	2 Nos	MR
12. Ya	rd Hydrants			71
	Total number of hydrants	Required	6 No's provided	MR
	Hose Box	Required	6 No's provided	MR
13. Pu	mping Arrangements			
	Ground Level			
	<ul><li>Discharge of main Pump</li></ul>	Required	2280 LPM	MR
	Head of Main pump	Required	60m	MR
	Number of main pumps	Required	One	MR
	> Jockey Pump out put	Required	180 LPM	MR
	Jockey pump head	Required	60m	MR
	Standby Pump out put	Required	2280 LPM	-NA-
	<ul><li>Standby Pump Head</li></ul>	Required	60m	-NA-
	<ul><li>Auto Starting/Manual Stopping</li></ul>	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level		4.2	
	<ul><li>Discharge of pump</li></ul>	Required	900 LPM	MR
	Head of the pump	Required	56m	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14. Ca	ptive Water Storage for fire fighting			
	Underground tank capacity	1,00,000 Lts	1,00,000 Lts	MR
	> Draw-off connection	Required	Provided	MR
	> Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	<ul> <li>Overhead Tank capacity</li> </ul>	20,000 Lts	20,000 Lts	MR
15. Ex	it Signage.	Required	Provided	MR
16. Pr	ovision of Lifts.		*	
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	<ul> <li>Pressurization of Lift lobby</li> </ul>	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	Provided	-NA-
	<ul> <li>Fireman's Grounding Switch</li> </ul>	-NA-	Provided	-NA-
	• Lift Signage	-NA-	Provided	-NA-
17. Sta	andby nawar supply	Required	Provided	MR
	andby power supply efuge Area.	Required	Tiovided	IVIIX
10. Ke	> Total Area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19. Fin	re Control Room	1111	2.12.2	1111
	Detector System Panel	-NA-	-NA-	-NA-
	Flow Switch Panel	-NA-	-NA-	-NA-
			-NA-	-NA-
	PA System Panel  Pattern backura	-NA-		
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	-NA-
20. Sp	Building Floor Plans      pecial Fire Protection System for Protection	1		-NA-

The fire protection systems provided in the building were tested, checked and found functional at

- N/16-

The Trillion Motel Pvt. Ltd., M. G. Road, Village Sultanpur, New Delhi

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

Dy. CFO (FPW)

330 Cfo J2

1314 FTB. M. Seed Wy

Si's FT. is putup for Sig. please.

00(SD

CRO(52)

miscell We 17/x