FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. f6 D68 ms/ Cinema (2016/1804

Dated: 22/12/16

## FIRE SAFETY CERTIFICATE

Certified that the M2K Cinema Audi -1,2&3 (M2K Entertainment Pvt Ltd), located at Third Floor Plot no 4, Road no. 44, community center, Pitampura, New Delhi – 34 in a building comprised B1+B2 +Ground + 03 Upper Floors was issued FSC vide Letter F6/DFS/MS/2015/1074 dated 22/05/2015. FSC to the Mall is issued vide Letter no-F6/DFS/MS/CINEMA/2016/WZ/139 Dated- 20/01/2016 The premises was re inspected by the officers concerned of this department on 19-12-2016 in the presence of Mr. Parbhaker (Sr. Manager Cinema) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly Building" Group D with effect from 2-2-11-16 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .. 2.2.1.2.1.6..... at New Delhi by.

(Atul Garg) Chief Fire Officer, Delhi Fire Service

## Copy to:

1. Sh Arun Gupta SDM (HQ-I)/Kanjhawala, District North West Kanjhawala, Delhi

2. Sh Parbhaker(Sr. Manager), M2K Entertainment Pvt Ltd, Plot no 4, Road no. 44, community center, Pitampura, New Delhi.

3. DY. Health officer NDMC, Sec-5, Rohini Zone, Rohini Delhi-85.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. Basement shall be used as per building bye laws.

7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

9. All the doors, Exits and internal roads must be kept free from any obstruction.

- 1. Name & address of the building: M2K Cinema Hall, Audi -1,2&3 (M2K Entertainment Pvt Ltd) 3<sup>rd</sup> Floor, Plot no 4,Road no. 44, community center, Pitampura, New Delhi
- 2. Type of Occupancy

; Assembly

- 3. Type of Case: Renewal and reopening of Audi -2 After alteration of seats
- 4. Details of previous NOC : **F6/DFS/MS/2015/1074 dated 22/05/2015.(For cinema)** F6/DFS/MS/CINEMA/2016/WZ/139 Dated- 20/01/2016(For Mall)
- 5. Fire Safety directives Letter No.: Letter No. F6/DFS/MS/BP/1611 Date 21-07-2003( For Mall)

6. Date of inspection

: 19-12-2016

7. Name of the Inspecting Officer: ADO (WP)

8. Name and designation of Officer

from the building side

: Mr. Parbhaker, (Sr. Manager Cinema)

9. Year of Construction

: 2004-05

10. Applicant's letter No. :F-11,DC/NW/CINEMA/2016/1343 Dated15/12/16

	10. Applicant's letter No	). :F-11,DC/N	W/CINEMA/2016/1343	Dated15/12/16			
S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirement	Provided at site	Remarks MR/NMR			
1.	Access of building	uilding					
	<ul> <li>Road width</li> </ul>	09mtrs	24mtr.	MR			
	<ul> <li>Gate width</li> </ul>	5 mtr	5m Provided	MR			
	<ul> <li>Width of internal road</li> </ul>	6 m	Provided(Old case)	) MR			
2.	Number, width, Type & Arrang	& Arrangements of exits Common with Mall					
	a. Number of staircases						
	<ul> <li>Upper floors</li> </ul>	2	4 provided	MR			
	<ul> <li>Basements</li> </ul>	NA	NA	NA			
	b. Width of staircases						
	<ul> <li>Upper floors</li> </ul>	2x1.5mtrs	2x1.42m&2x1.68n	n MR(Old case)			
	<ul> <li>Basements</li> </ul>	NA	NA	NA			
	D						
	c. Protection of exits	Required	Provided By Mall	MR			
	Fire check door	NA	NA	NA			
	<ul><li>Pressurization</li><li>d. No of continuous</li></ul>	02	Provided	MR			
	staircase to terrace	Oldansa	Duoridad Dr. Mall	MD			
	e. Width Of Corridor	Old case Audi-1=3Exits	Provided By Mall	MR			
	f. Door Size	Audi-2=4 Evite	Audi-1=2x1.54m &1x1.45	1			
	1. 2001 5120	The state of the s	Audi 2=2x151m & 2x1.59m Audi 3=2x1.49m & 1x1.6m				
3.	Compartmentation		Add 5 2/1.47/11 & 1/1.011	old case			
	Fire check door	Required	Provided By Mall	MR			
	<ul> <li>Sealing of electrical</li> </ul>	Required	Provided By Mall	MR			
	shafts						
	<ul> <li>Fire Rating of shaft</li> </ul>	Required	Provided By Mall	MR			
	door						
	Water Curtain	Required	Provided By Mall	MR			
	Fire Dampers	Required	Provided By Mall	MR			
4.	Smoke managements System						

	Total numbers	12	M' W 1 00 G			
	Total numbers	12	Main Hal=03 (Each Projector room =4	Audi)	MR	
			El S. Station=2			
	Types	ABC,CO2 typ	e AC Room=3			
	IS marking	ISI marked	Provided		MR	
(	First – Aid Hose Reels		Provided		MR	
	Total numbers on	1	1 Duovid-1/ 1	1 10		
	each floor	1	1 Provided (each	Audı)	MR	
	<ul> <li>Length of hose reel</li> </ul>	30 m	Provided		MR	
	hose		Trovided		IVIK	
	Nozzle diameter	5 mm	Provided	Provided		
7	The detection and			Provided MR		
	• Type of detectors	Required	Provided By Mall	MR		
	<ul> <li>Location of Main Panel</li> </ul>	Ground floor	Provided By Mall	MR		
	<ul> <li>Location of Repeater</li> </ul>	Each floor	Provided Dr. Mall	) (D		
	Panel	Eden 11001	Provided By Mall	MR		
	<ul> <li>Alternate source of</li> </ul>	Required	Provided By Mall	MR		
	power	Required	Provided By Mall	MR		
_	Hooters' Location	Required	Provided By Mall	MR		
8.	MOEFA	Required	Provided	MR		
9.	Tradition Dystelli	Required	Provided	MR		
10	Sprinkler System					
	Basements	Required	Provided	NR		
	• Upper Floor	Required	Provided	MR		
	• Sprinkler above false ceiling	Required	Provided	MR		
11						
	Size of riser/down-	150 mm	Provided	3 m		
	comer	130 mm	Flovided	MR		
	<ul> <li>No. of hydrants per</li> </ul>	3	Provided 3at each floor	MR		
	floor		& 1 in each Audi	1,11		
12.	Hose Box	3	Provided	MR		
12.	Yard Hydrants					
	<ul><li>Total no. of hydrants</li><li>Hose Box</li></ul>	Required	Provided By Mall	MR	0	
13.	Pumping Arrangements	Required	Provided By Mall	MR		
10.	Ground Level				»	
	Discharge of main pum	2850LPM	Provided De M 11	3.50		
	Head of main pump	60 mtr	Provided By Mall Provided By Mall	MR		
	Number of main pumps	s 1	Provided By Mall	MR MR		
	Jockey pump out put	180 lpm	Provided By Mall	MR		
	Jockey pump head	60 m	Provided By Mall	MR		
	Standby Pump out put	2850lpm	Provided By Mall	MR		
	Standby Pump Head Auto Staring/Manual	60 mtr	Provided By Mall	MR		
	Auto Staring/Manual stopping	Required	Provided By Mall	MR		
	> Pump House Access	D				
	• Terrace level	Required	Provided	MR		
	Discharge of pump	900lpm	Described Described			
	Head of the pump	40m	Provided By Mall	MR		
	Power supply	Required	Provided By Mall Provided By Mall	MR		
13.77	Auto starting of pump	Required	Provided By Mall	MR MR		
14.	Captive water Storage for fire f	ighting		IVIK		
	<ul> <li>Under ground tank</li> </ul>	1,00,00 litres	Provided	MR		
	capacity					
	<ul><li>Draw of connection</li><li>Fire service inlet</li></ul>	Required	Provided	MR	an todor with	
	Fire service inlet	Required	Provided	MD		

	Provision of Lifts Lift is of ca			
16.		Required	Provided By Mall	MR
	Shaft > Pressurization of lift	Required	Provided By Mall	MR
	lobby  Communication in lift	Required	Provided By Mall	MR
	Car  Fireman's Grounding  Switch	Required	Provided By Mall	MR
	> Lift Signage	Required	Provided By Mall	MR
17.	Standby power supply	Required	Provided By Mall	MR
18.	Refuge Area			NIA
10.	> Total area	NA	NA	NA
	> Location	NA	NA	NA
20.	Fire control room  Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	Required Required Required Required Required NA	Provided By Mall NA	MR MR MR MR MR NA
	special Risks, if any;			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no.

**F6/DFS/MS/2015/1074 dated 22/05/2015** renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note ;- The Audi -2 is being reopened after alteration of seat as per plan submitted vide letter no SDM/SV/Verification/2015/20863 dated 29/02/2016.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name Udas Vir big

Name

Designation ADO/WP

Designation

Dolla production 16

21/12/16

cho mestosalal

1- 6 Pine.