GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2016/ 1833

Dated: 23.12.2016

FIRE SAFETY CERTIFICATE

Issued 23.12.2016 at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011,23412225

n: - 011-2341222

Copy to: -

1 The Joint. C.P.(Lic.), Police Station, Defence colony, 1st floor, New Delhi.

2. M/s Iqbal Guest House 1193, Churiwala, Jama Masjid, Delhi-06.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to it expiry

GIN

INSPECTION REPORT

1.Name & address of the building:- M/s Iqbal Guest House 1193, Churiwala, Jama Masjid, Delhi-110006.

2. Type of occupancy:- Residential Group A-1 (Ground+2 upper floors)

Ground floor (commercial use), 1st floor (reception+ 07 guest rooms), 2nd floor (08 guest rooms) & terrace (open area & water tank) Total 15 guest rooms

3. Type of case:- Renewal

4. Details of previous FSC: - No. F6/DFS/MS/GH/2013/NDZ/968 dated

25/09/2013.

5. Fire safety directives No.- N/A

6. Date of inspection: 06/12/16

7. Name of the inspecting officer:- A. D.O. Mehmood

8. Name & designation of officer

From the building side:- Sh. Mohammed Waseem

9. Year of construction:- 1995

10. Applicant's letter No:- 3876/Jt. C.P./Lic(H) dated - 10/11/2016

Old case

				Old case		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (Existing Fire Safety Measures)	Provided at site	Remarks MR/NMR		
1.	Access to Building		8	8		
	1) Road width	N/A	05 mtr. approx.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases		8			
	1. Upper floors	01 No	01 No.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase		,			
	1. Upper floors	1.25 mtr.	1.25 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits					
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	01 No.	01 No.	MR		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1 mtr.	1 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	N/A	N/A		



10/N

5.	Fire Extinguishers					
	1) Total numbers	0637				
	2) Types	06 Nos.	06 Nos.	MR		
	3) ISI marking	ABC & CO2	ABC & CO2	MR		
6.	First-Aid Hose Reel	Required	Provided	MR		
0.						
	1)Total number of each floor	01 No.	Provided	MR		
	2) Length of hose reel hose	30 m	30 m	MR		
7.	3) Nozzle diameter	5 mm	5 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
	MOEFA	N/A	N/A	N/A		
	Public Address System	Required	Provided			
0.	Automatic Sprinkler System	1	TTOVICCO	MR		
	1) Basement	N/A	N/A	NT/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
4	ceiling	7.03.530070	IVA	N/A		
1.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	27/1		
	2) Number of hydrants per	N/A		N/A		
	floor	14/11	N/A	N/A		
	3) Hose box	N/A	DI/A			
2.	Yard Hydrants	11//1	N/A	N/A		
	1) Total number of hydrants	N/A	27/4			
	2) Hose box	N/A	N/A	N/A		
3.	Pumping Arrangement	IV/A	N/A	N/A		
	1) Ground level	NT/A				
	a) Discharge of main	N/A	N/A	N/A		
	pump	N/A	N/A	N/A		
	b) Head of main pump	27/4	1 2			
	c) Number of main pump	N/A	N/A	N/A		
	Thain pains	N/A	N/A	N/A		
	parip out put	N/A	N/A	N/A		
) perilip fiedd	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping			11111		
	2) Terrace level					
	a) Discharge of pump	225 LPM	225 LPM	MR		
	b) Head of pump	40 mtr.	40 mtr.			
	c) Power supply	Required	Provided Provided	MR		
·	d) Auto starting of pump	N/A	N/A	MR		
	Captive Water Storage for Fire I	71 -1-4	11/11	N/A		

21

	1) Under ground tank	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	2500 ltrs.	2500 ltrs.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.		*		
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for Protection of special Risk, if any:				

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/GH/2013/NDZ/968 dated 25/09/2013, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

D.O. (Central)

Assistant Divisional Officer

8/12/16

Carn2