GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DF5/ans/EH/2017/52/364

Dated: 14/03/17

FIRE SAFETY CERTIFICATE

Issued on.....1.4.1.3........2017 at New Delhi by

(Vipin Kental)

Chief Fire Officer

T.No.011-23412225

Copy to:- 1. Joint C.P. Licensing, 1st Floor, Police Station, Defence Colony, New Delhi.

2. M/s Sky High (A Unit of Alkanet Hospitality P Ltd) locted at C-306A and C-307, Third Floor, Ansal Plaza Shopping Arcades at Hudco Place at Pinjra Pole, Andrewsganj, New Delhi.

Conditions for the validity of fire safety certificate are as under:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate, six month prior to its expiry.

		INSPECTION REPORT	111 - 11-11 D.14 N.1 - 4 - 1	at C 2004 and C		
1		M/s Sky High (A Unit of Alkanet Hospitality P Ltd) located at C-306A and C-307, Third Floor, Ansal Plaza Shopping Arcades at Hudco Place at Pinjra Pole, Andrewsganj, New Delhi.				
0						
2	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Two tier basements, Ground Mezzanine plus three upper floors. But				
3	Building comprised of	restaurant is at third floor only.				
4	1,700 0. 00.00	New/Renewal (Now it is in new name)				
5		No. F6/MS/DFS/EH/2013/212, Dated 25.04.2013.				
6	The salety and dives lotter ive	Nil.				
7	Bate of mepodition	22.02.2017.				
8	Name of the inspecting Officers :	DO A.K.Malik & ADO Vedpal				
9	Traine and designation	Sh. Ramesh, Steward.				
10	from the building side Year of construction	1997-1999				
10	Tour or correct or the state of	Nil, dated 23.01.2017.				
11	/ tppilodite o to train		Provided at site	Remarks		
NO.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements /Existing Fire Protection System as per Old NOC	Provided at site	MR / NMR		
1	Access to building			IMP		
	1) Road width	Required	12m	MR MR		
	Gate width Width of internal road	Required Required	Provided as per approved plans	MR(old case)		
2	Number, width Type & arrangemen	nt of exits	^			
	a. Number of staircases		CONT the restaurant	MR		
	1. Upper floors	02Nos.	02Nos near the restaurant			
	2. basements	N/A	N/A	N/A		
	b. Width of staircase		1.50 0.1.10	MD(ald acce)		
	1. Upper floors	Required	1.50m & 1.46m	MR(old case)		
	2. basements	N/A	N/A	N/A		
	c. Protection of exits			1 2		
	1. Fire check door	Required	Provided	MR		
	2. Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase to terrace	Required	04Nos(One in A Block, One in B Block & Two in C Block)	MR(old case)		
	e. Width of corridor	1.5m	1.5m	MR		
	f. Door size	Required 02 Nos.	Provided 02Nos. (1m each	MR(old case)		
3	Compartmentation.			MD		
	1. Fire check door	Required	Provided	MR		
	2. Sealing of electrical shafts	Required	Provided	MR		
	3. Fire Rating of shaft door	Required	Provided	MR N/A		
	4. water curtain	N/A	N/A			
	5. Fire dampers	N/A	N/A	N/A		
4	Smoke Management system.	00 /		TN1/0		
	Basement	30 a/c per hour 12 a/c per hour	N/A Exhaust Fans Provided	N/A MR		
	Upper floors			Title Control		
5	Fire Extinguishers	O6Nos	06 Nos.Provided	MR		
	total numbers	_06Nos ABC, CO2, WCO2	ABC, CO2, Water CO2,	MR		
	Types	ISI	Provided	MR		
	ISI marking		mon for entire mall building)	LIVILY		
6	First-Aid Hose Reels. Total numbers on each floor	02nos.(Near restaurant)	02nos (Near restaurant)	MR		
	Length of Hose reel hose	30 Mtr	30 Mtr Provided	MR		
	Nozzle Diameter	5mm	5 MM Provided	MR		





	Automatic fire detection and Type of detectors			
	location of Main Panel	Smoke & Heat Ground Floor	Smoke & Heat	MR
		The state of the s	Ground Floor	MR
	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
8	hooter's location MOEFA	Required	All Areas	MR
		Required	Provided	MR
9	Public Address System.	Required	Provided	,
10	Automatic Sprinkler System.	(Fire fighting system is c	ommon for entire mall building	MR
	basement upper floors	INA	N/A	N/A
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants	N/A	N/Δ	1111
	Size of riser/down-corner	(Fire fighting system is co	ommon for entire mall building	3)
	Number of Hydrants per floor	130 11111	150mm Provided	MR
		02nos. (Near restaurant)	02nos (Near restaurant).	MR
15	hose Box	02nos. (Near restaurant)	02nos. (Near restaurant)	MR
12	Yard Hydrants.		ommon for entire mall building) Ivii'
	total number of hydrants	08 Nos	08 Nos. Provided	
12	house box	08 Nos	0.0 1.1	MR
13	Pumping arrangements (Fire fi	ghting system is common fo	or entire mall building)	MR
			- Sunding)	
	a. Discharge of main Pump	Required	4050 LPM Provided	MR
	b.Head of main pump c.Number of main pumps	Required	90m	MR
	d.jockey pump out put	Required	02nos.	MR
	e jockey pump head	Required	450LPM	MR
	f. Standby Pump output	Required	90m	MR
	g.Stanby Pump head	Required Required	8100 LPM Provided	MR
	h.Auto Starting/Manual stopping	Required	90m	MR
	pump house access	Required	Provided Provided	MR
	2.Terrace level		Ti-Tovided	MR
	a. Discharge of pump	N/A	N.A.	INI A
	b. head of the pump	N/A	N.A.	N.A.
	c. Power supply d. Auto starting of pump	N/A	N.A.	N.A.
		N/A	N.A.	N.A.
	Captive water storage for fire fighting	(Fire fighting system is com	nmon for entire mall building)	
	Underground tank capacity			5
	a. Draw-off connection	450000 ltr	4,50,000 Ltr Provided	MR
	b. fire service inlet	Required Required	Provided	MR
	c. Access to tank	Required	Provided	MR
	d. Over head tank Capacity	20,000 Itr	Provided	MR
			20,000 ltrs on AB Block & 30000 ltrs on C Block	MR
E	Exit Signage.	Required	Provided	MR
F	Provision of lifts.			
	a. Pressurization of lift shaft	N/A	INI/A	
c d	. Pressurization of lift lobby	N/A	N/A N/A	N/A
	Communication in lift car	Required	Provided	N/A
	Fireman's grounding switch	Required	Provided	MR
~	. Lift signage	Required	Provided	MR MR
е	tandby power supply	Required	DG Set Provided	7
e S			1 - 3 Ook 1 TOVIGED	MR
e S R	Refuge Area.			
e S R to	otal area	N/A	N/A	INI/A
S R to	otal area	N/A	N/A N/A	N/A
e S R to	otal area ocation ire control room (Fire fighting so	N/A stem is common for entire	NI/A	N/A N/A
e S R to lo	otal area ocation ire control room (Fire fighting sy Detector system Panel	N/A ystem is common for entire Required	N/A mall building) Provided	N/A
e S R to lo	ocation ire control room (Fire fighting sy Detector system Panel Flow switch Panel	N/A /stem is common for entire Required N/A	N/A mall building) Provided N/A	
e S R to lo	otal area ocation ire control room (Fire fighting sy Detector system Panel	N/A ystem is common for entire Required	N/A mall building) Provided N/A	N/A MR

20 Special Fire Protection systems for protection of special risks, if any:

CO2 & ABC Type Fire Extingushers Provided near Electric Panel=MR

The fire protection systems provided in the building were checked and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/MS/DFS/EH/2013/212, dated 25.04.2013 renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for kind consideration please

Signature of the inspecting officer

Name: A.K.Malik

Designation: D.O. (SD)

Signature of the inspecting officer

Name: Vedpal

Designation: ADO(SJ)

Dero(S2)

Please Rup with FSC of

leed ful done. File

File is resubmitted

8/8/19

ADO (S)

DO (SD)