## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F6/DFS/MS/EH/2017/SZ/ 🔾 🥱

Dated: 22/03/17

## FIRE SAFETY CERTIFICATE

Certified that M/s Moti Mahal Delux-II Restaurant located at ground floor of M-30, Greater Kailash-I, New Delhi-110048, was granted FSC by this department vide letter No. F.6/DFS/MS/EH/2014/SZ/216 dated 11/02/2014. The premises was re-inspected by the officer concerned of this department on 02.03.2017 in the presence of Mr. Alam Singh (Manager) of the restaurant and observed that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" (Restaurant) as above with effect from 22 of [7] for a period of Three years in accordance with rule 36 unless renewed under rile 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22 3 (7 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

1. The Joint C.P. (Lic.), First Floor, PS Defence Colony, New Delhi-110049

2. The DHO (Central Zone), South MCD, Health Deptt, Lajpat Nagar, New Delhi-24

3. The Manager, M/s Moti Mahal Delux-II Restaurant, M-30, Greater Kailash-I, New Delhi-110048

## Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working condition at all time. Any lapse rendering the fire safety or means of evacuation facilities non-functional shall be the responsibility of the management.
- Sanctioning authority may verify any deviation with construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null & void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drill be conducted at regular interval and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

		CTION REPORT				
1	Name & Address of the Building	M/s Moti Mahal Delux-II Restaurant, M-30,				
		Greater Kailash-I, New Delhi-110048				
2	Type of Occupancy	Assembly Building "Group-D" Restaurant				
3	Building Comprised of	Ground floor only				
4	Type of Case	Renewal				
5	Details of Previous NOC		/2014/SZ/216 Dated 11/0			
6	Fire Safety Directives Letter No		I/356-359 dated22.03.200	)5		
7	Date of Inspection	02.03.2017	End to read the first			
8	Name of the Inspecting Officers	ADO R.N. Singh				
9	Name & Designation of Officers from the building side	Mr. Alam Singh (Manager)				
10	Year of construction	2005				
11	Applicant letter No.	Nil dated 23.01.2017, ODD No. 910 dated 25.01.17				
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC 29/03/2006 Requirements	Provided at Site	Remarks MR/NMI		
1	Access to Building.					
	Road width	Required	9 mtr	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of exits					
	a. Number of Staircase	3 = 13 MV				
	Upper floors	N/A	N/A	N/A		
	Basement floor	N/A	N/A	N/A		
	b. Width of Staircase	X				
	Upper floors	N/A	N/A	N/A		
	Basement floor	N/A	N/A	N/A		
	c. Protection of exits					
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase to terrace	N/A	N/A	N/A		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	Required	1.30, 0.80 & 1.10 mtr (Final Exit)	MR (old case		
3	Compartmentation.					
	Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	N/A	N/A	· N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.	New Arthurst Control		1250		
	Basement	N/A	N/A	N/A		
	Upper floors	Required	Exhaust fan provided	MR		
5.	Fire Extinguishers.					
	Total numbers	05 No's		MR		
	• Types	ISI marked	ABC-04, Co2-01	MR		
	ISI Marking		Provided	MR		
6.	First Aid Hose Reels.	-,	*			
0.	Total numbers on each floor.	Hose-reel 01 provided in Restt.		MR		
	Length of hose-reel hose.	11000 1001	30 m	MR		
	Longin of host-teel host.					

Renewal

Moti Mahal Delux II Restt, GK-I, New Delhi-48

7 4	Automatic fire detection & clarming and	La la caracteria de la		
	Automatic fire detection & alarming system  Type of detectors	N/A	NI/A	DI/A
	Location of Main Panel	N/A N/A	N/A N/A	N/A
		N/A		N/A
	Location of Repeater Panel     Alternate source of reviews	N/A N/A	N/A N/A	N/A
	<ul> <li>Alternate source of power</li> <li>Hooter's location</li> </ul>	N/A		N/A
8. 1	Hooter's location  MOEFA		N/A	N/A
	Public Address System	Required	Provided	MR
	Automatic Sprinkler System	N/A	N/A	N/A
10.	Basement	N/A	N/A	DT/A
	• Upper floors	Required	Provided Provided	N/A
		N/A		MR
11.	Sprinkler above false ceiling     Internal Hydrants.	N/A	N/A	N/A
11. 1	Size of Riser/Down-comer	N/A	NIA	27/4
		N/A N/A	N/A	N/A
50 /	Transcer of Hydrant per 11001		N/A	N/A
12. Y	Hose box.  Yard Hydrants.	N/A	N/A	N/A
14.		NI/A	NT/A	37/4
313	<ul> <li>Total number of hydrants.</li> <li>2 Hose box</li> </ul>	N/A	N/A	N/A
13. F	Z. IROSO OOA.	N/A	N/A	N/A
13.	Pumping arrangements.			
	• Ground Level	27/4		
	Discharge of main pump.	N/A	N/A	N/A
,	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.  Jockey Pump head.	N/A	N/A	N/A
	<ul><li>Jockey Pump head.</li><li>Standby Pump output.</li></ul>	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	> Auto Starting / Manual Stopping.	N/A	N/A	N/A
	> Access to pump house	N/A	N/A	N/A
	Terrace Level	N/A	N/A	N/A
		D. C. J.	450 I D) 4	3.60
(2)	<ul><li>Discharge of pump.</li><li>Head of pump.</li></ul>	Required	450 LPM	MR
90%	Power supply.	Required	• 40 mtr	MR
	> Auto starting of pump.	Required	Provided	MR
14. C	Captive water storage for Fire Fighting.	Required	Provided	MR
	Underground tank capacity.	N/A	N/A	NI/A
1	> Draw-off connection.	N/A	N/A N/A	N/A
	Fire Service Inlet.	N/A N/A	N/A N/A	N/A
	> Access to tank.	N/A	N/A N/A	N/A N/A
	- i data a la companya da la company	2,500 Ltr	Provided	MR
15. E	xit Signage.	Required	Provided	MR
	rovision of Lifts.	Required	Tiovided	IVIK
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
N. I	• Lift signage.	N/A	N/A	N/A
17 St	tandby Power Supply	Required	Provided •	
	lefuge Area	Required	riovided	MR
111	Total area	N/A	N/A	N/A
2.00	• Location	N/A		
enewal	Location		N/A  IX II Restt, GK-I, New De	N/A

19.	Fire Control Room.			
	Detector System Panel.	N/A		N/A
	Flow Switch Panel.	N/A		N/A
	PA system Panel.	N/A	-	N/A
	Battery backup     Building floor plan	N/A N/A		N/A N/A

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2014/SZ/216 Dated 11/02/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

hum 3/2/17

Signature of the Inspecting Officer
Name : R.N. Singh

Designation: ADO

Renewal

Moti Mahal Delux II Restt, GK-1, New Delhi-48

Div. Officer (SD)

dr. cocos

725/02-82

15/3

Cho Csy

m-stell

16/3.