## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. 76/08/ans/84/2017/32/462

Dated: 28/03/17

## FIRE SAFETY CERTIFICATE

Certified that M/s "Lodi The Garden Restaurant" located at Lodhi Road, Opposite Mausam Bhawan, New Delhi-110003, comprised of ground plus one upper floor only, owned/occupied by M/s Lodi The Garden Restaurant was granted FSC by this department vide letter No. F6/DFS/MS/EH/2014/SZ/451, dated 04-04-2014. The premises was re-inspected by the officer concerned of this department on 21-03-2017 in the presence of Sh. Sunil Kumar, Manager and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "D-Assembly" Restaurant with effect from ...281.031...2017 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 28./.03./....2017 at New Delhi by.

(Vipin Kental)

**Chief Fire Officer** 

T.No.011-23412225

Copy to:- 1.The Dy. Health Officer, Health Deptt.South MCD, Green Park, New Delhi.

2. M/s Lodi The Garden Restaurant located at Lodhi Road, Opposite Mausam Bhawan, New Delhi-110003.

## Conditions for the validity of fire safety certificate are as under:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. The employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All fire fighting equipments shall be maintained in perfect working condition all time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate, six month prior to its expiry.

## N/12 **INSPECTION REPORT** 1. Name & address of the building : M/s Lodi The Garden Restaurant located at Lodhi Road, Opposite Mausam Bhawan, New Delhi-110003. 2. Building is comprised of : Ground plus one upper floor. 3. Type of Occupancy : Group-D, Assembly Building (Eating House). 4. Type of Case : Old Case 5. Details of Previous NOC : No.F.6/DFS/MS/EH/2014/SZ/451, dated-04.04.14. 6. Fire Safety direction letter No : Circular No.718, dated 4.4.2005. 7. Date of Inspection : 21.03.2017. 8. Name of the Inspecting Officers : Vedpal (ADO) 9. Name and designation of Officer from the building side : Sh. Sunil Kumar, Manager. 10. Year of Construction : Not Known. 11. Applicant's letter No : No. Nil, dated 03.03.17. S.No Minimum Standards on fire Requirements as Provided at Remarks prevention and fire safety per Initial NOC Site (08.09.2005)1 Access to building Road width Accessible 15m MR Gate width N.A. N.A. N.A. Width of internal road N.A. N.A. N.A. 2 Number, Width, Type and Arrangement of Exits. a. Number of Staircases Upper Floor 02nos. 02nos. MR Basement N.A. N.A. N.A. B. Width of Staircases Upper Floor Required 1.20m, 90cm MR(old case) Basement N.A. N.A. N.A. c. Protection of exits N.A. N.A. N.A. Fire check door N.A. N.A. N.A. Pressurization N.A. N.A. N.A. e. No. of continuous staircases to N.A. N.A. N.A. terrace g. Width of Corridor N.A. N.A. N.A. h. Door Size Required 1.15m & 1m MR(old case) 02nos (Final exit) 3 Compartmentation Fire check door N.A. N.A. N.A. Sealing of electrical shafts N.A. N.A. N.A. Fire rating of shaft door N.A. N.A. N.A. Water curtain N.A. N.A. N.A. Fire Dampers N.A. N.A. N.A. 4 Smoke Management System. Basement N.A. N.A. N.A.

12 a/c per hour

Required

CO MICO

Exhaust

10 nos.

CO O ADO

MR

MR

fans

Upper floor

Types

Fire Extinguisher Total numbers

5.

8. Name of the Inspecting Officers : Vedpal (ADO) 9. Name and designation of Officer from the building side : Sh. Sunil Kumar, Manager. 10. Year of Construction : Not Known. 11. Applicant's letter No : No. Nil, dated 03.03.17. S.No Minimum Standards on fire Requirements as Provided at Remarks prevention and fire safety per Initial NOC Site (08.09.2005)1 Access to building 15m MR Road width Accessible Gate width N.A. N.A. N.A. Width of internal road N.A. N.A. N.A. 2 Number, Width, Type and Arrangement of Exits. a. Number of Staircases Upper Floor 02nos. 02nos. MR Basement N.A. N.A. N.A. B. Width of Staircases Upper Floor Required 1.20m, 90cm MR(old case) Basement N.A. N.A. N.A. c. Protection of exits N.A. N.A. N.A. Fire check door N.A. N.A. N.A. Pressurization N.A. N.A. N.A. e. No. of continuous staircases to N.A. N.A. N.A. terrace g. Width of Corridor N.A. N.A. N.A. h. Door Size Required 1.15m & 1m MR(old case) 02nos (Final exit) 3 Compartmentation Fire check door N.A. N.A. N.A. Sealing of electrical shafts N.A. N.A. N.A. Fire rating of shaft door N.A. N.A. N.A. Water curtain N.A. N.A. N.A. Fire Dampers N.A. N.A. N.A. 4 Smoke Management System. Basement N.A. N.A. N.A. Upper floor 12 a/c per hour Exhaust MR fans 5. Fire Extinguisher Total numbers Required 10 nos. MR CO<sub>2</sub>, WCO<sub>2</sub> & Types CO<sub>2</sub> & ABC MR DCP IS marking ISI marked ISI marked MR First-aid-Hose Reels. 6 Total numbers on each floor 01no. 01no. MR Length of hose reel hose 30m. 30m. MR Nozzle diameter 5mm 5mm MR Vul

: Circular No.718, dated 4.4.2005.

: 21.03.2017.

6. Fire Safety direction letter No

7. Date of Inspection

M/s Lodi The Garden Restaurant located at Lodhi Road, Opposite Mausam Bhawan

7	M/s Lodi The Garden Restaurant loca		d, Opposite Mausam Bha	wan.			
7	Automatic fire detection and alarming system.						
	Type of detectors	N.A.	N.A.	N.A.			
	Location of main panel	N.A.	N.A.	N.A.			
	Location of repeater panel	N.A.	N.A.	N.A.			
	Alternate source of power Hooters	N.A.	N.A.	N.A.			
	(	N.A.	N.A.	N.A.			
3	MOEFA	Required	Provided	MR			
9	Public address System.	N.A.	N.A.	N.A.			
10	Automatic Sprinkler System.						
	Basement	N.A.	N.A.	N.A.			
	upper floor	Required	Provided	MR			
	sprinkler above false ceiling	N.A.	N.A.	N.A.			
11	Internal Hydrants						
	size of riser/down-comer	N.A.	N.A.	N.A.			
	Number of hydrants per floor	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
12	Yard Hydrants.						
	Total number of hydrants	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
13	Pumping Arrangements.						
	Ground Level	N.A.	N.A.	N.A.			
	Discharge of main Pump	N.A.	N.A.	N.A.			
	Head of Main Pump	N.A.	N.A.	N.A.			
	Number of main pumps	N.A.	N.A.	N.A.			
	Jockey pump out put	N.A.	N.A.	N.A.			
	Jockey pump head	N.A.	N.A.	N.A.			
	Standby pump out put	N.A.	N.A.	N.A.			
	Standby pump Head	N.A.	N.A.	N.A.			
	Auto Starting /Manual	N.A.	N.A.	N.A.			
	stopping						
	Pump House Access	N.A.	N.A.	N.A.			
	Terrace Level	Required	Provided	MR			
	Discharge of pump	Boosting	450LPM	MR			
	Head of the Pump	N.A.	35m	MR			
	Power supply	Required	Provided *	MR			
	> Auto Starting of pump	N.A.	Provided	N.A.			
4.4							
14	Captive Water Storage for Fire Fighting.						
	On ground tank capacity	N.A.	N.A.	N.A.			
	Draw-off connection	N.A.	N.A.	N.A.			
	Fire service inlet	N.A.	N.A.	N.A.			
	Access to tank	N.A.	N.A.	N.A.			
7	Overhead Tank capacity	5000Ltrs.	5000Litrs	MR			
5	Exit Signage.	Required	Provided	MR			
6	Provision of Lifts.						
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.			
	Pressurization of Lift lobby	N.A.	N.A.	N.A.			
	Communication in lift car	N.A.	N.A.	N.A.			
	Firemen's grounding switch	N.A.	N.A.	N.A.			

9	i ubile address System.	IV.A.	IV.A.	N.A.			
10	Automatic Sprinkler System.						
	Basement	N.A.	N.A.	N.A.			
	upper floor	Required	Provided	MR			
	sprinkler above false ceiling	N.A.	N.A.	N.A.			
11	Internal Hydrants						
	size of riser/down-comer	N.A.	N.A.	N.A.			
	Number of hydrants per floor	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
12	Yard Hydrants.						
	Total number of hydrants	N.A.	N.A.	N.A.			
	Hose Box	N.A.	N.A.	N.A.			
13	Pumping Arrangements.						
	Ground Level	N.A.	N.A.	N.A.			
	Discharge of main Pump	N.A.	N.A.	N.A.			
	Head of Main Pump	N.A.	N.A.	N.A.			
	Number of main pumps	N.A.	N.A.	N.A.			
	Jockey pump out put	N.A.	N.A.	N.A.			
	Jockey pump head	N.A.	N.A.	N.A.			
	Standby pump out put	N.A.	N.A.	N.A.			
	Standby pump Head	N.A.	N.A.	N.A.			
	Auto Starting /Manual stopping	N.A.	N.A.	N.A.			
	Pump House Access	N.A.	N.A.	N.A.			
	Terrace Level	Required	Provided	MR			
	Discharge of pump	Boosting	450LPM	MR			
	Head of the Pump	N.A.	35m	MR			
	Power supply	Required	Provided *	MR			
	Auto Starting of pump	N.A.					
14	Captive Water Storage for Fire Fig	ahtina					
	On ground tank capacity	N.A.	N.A.	N.A.			
	Draw-off connection	N.A.	N.A.	N.A.			
	Fire service inlet	N.A.	N.A.	N.A.			
	Access to tank	N.A.	N.A.	N.A.			
	Overhead Tank capacity	5000Ltrs.	5000Litrs	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.			
	Pressurization of Lift lobby	N.A.	N.A.	N.A.			
	Communication in lift car	N.A.	N.A.	N.A.			
	Firemen's grounding switch	N.A.	N.A.	N.A.			
	Lift Signage	N.A.	N.A.	N.A.			
17	Standby power supply	Required	Provided 50Kva	MR			
	Standby power supply	required	Generator set	IVIT			
18	Refuge Area.						
10	Total area	N.A.	N.A.	N.A.			
	Location	N.A.	N.A.	N.A.			
	Loodion	IV.A.	IV.A.	IV.A.			

M/s Lodi The Garden Restaurant located at Lodhi Road, Opposite Mausam Bhawan.

19	Fire Control Room					
	Detector system panel	N.A.	N.A.	N.A.		
	Flow switch panel	N.A.	N.A.	N.A.		
	PA system panel	N.A.	N.A.	N.A.		
	Batter backup	N.A.	N.A.	N.A.		
	Building Floor Plans	N.A.	N.A.	N.A.		
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	N.A.	N.A.		

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection. In view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules the FSC issued vide letter No.F.6/DFS/MS/EH/2014/SZ/451, dated 04.04.2014, renewal under rule 37 of the Delhi Fire Service Rule 2010 is recommended.

Accordingly DFA is put up for your approval and signature please.

Signature of the Inspecting Officer

Name: Vedpal

Designation: ADO(S.J.)

Dr clo(S2)