## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/2017/SZ/ 477

Dated: 12/5/17

## **FIRE SAFETY CERTIFICATE**

Certified that the The Ocean Pearl Retreat Motel, located at KH No. 83, 84, 85, 90, 91/1-2, 101, 102, Chatterpur Mandir Road, Village-Satbari, Mehrauli, New Delhi, comprised of **Basement and Ground floor** has already been issued FSC by this department vide letter F6/DFS/MS/Motel/2014/SZ/488 dated 16/04/2014. The premises was re-inspected by the officer concerned of this department on 26/04/2017 in the presence of **Mr. Ramesh Parida** (**Chief Engineer**) & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy **Group A "Residential Building"** with effect 2017 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on. 121.51.7..at New Delhi by.

(Vipin Kental) Chief Fire Officer Ph:-011-23412235

000

Copy to:-

- 1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049
- 2. Executive Engineer (Bldg.), SDMC, Civic Center, Minto Road, New Delhi-110002
- 3. Sh. Ajay Melhotra, General Manager, The Ocean Pearl Retreat Motel, located at KH No. 83, 84, 85, 90, 91/1-2, 101, 102, Chatterpur Mandir Road, Village-Satbari, Mehrauli, New Delhi

## Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1191 The Ocean Pearl Retreat Motel, KH No. 83, 84, 85, 90, 91/1-2, 101, 102, Chatterpur Mandir Road, Village-Satbari, Mehrauli, New Delhi INSPECTION REPORT Name & address of the building: The Ocean Pearl Retreat Motel, KH No. 83, 84, 85, 90, 91/1-2, 101, 102, Chatterpur Mandir Road, Village-Satbari, Mehrauli, New Delhi : Group A "Residential" (Motel) Building [Basement + GF] Type of Occupancy 3. Type of Case : Renewal : F6/DFS/MS/Motel/2014/SZ/488 Dated 16/04/2014 4. Details of Previous NOC : F6/MS/DFS/BP/GH/2003/1500 Dated 04/07/2003 5. Fire \$afety directives letter No : 26/04/2017 6. Date of inspection 7. Name of Inspecting Officer : A.K. Malik. 8. Name and designation of officers : Mr. Ramesh Parida (Chief Engineer) From the building side : 2005 9. Year of Construction : 496/Joint C. P. Lic. (H)/New Delhi dated 20/02/17 & applicant 10. Applicant's letter No. letter no. Nil dated Nil, outdoor diary no. 4518 dated 13/04/2017 Provided at site Remarks **Old NOC** Minimum Standards on fire prevention S. MR/NMR (26-03-2008)No and fire safety U/R 33 Requirement 1. Access to building MR 30m Accessible Road width 5m x 2 Nos MR Adequate Gate width -NA--NA--NA-Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases -NA--NA--NA-Upper Floors Provided MR 8 Nos Basements b. Width of staircases -NA--NA--NA-Upper Floor MR 1.5m 1.25m Basements Protection of exits MR Provided Required Fire check door -NA--NA--NA-Pressurization MR Three Required No. of continuous staircases to terrace Provided MR 1.25m Width of Corridor e. MR 1m (Final Exit) 1m Door Size Compartmentation 3. MR Provided 1.25m Fire check door MR Provided Required Sealing of electrical shafts -NA-Fire Rating of shaft door -NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA--NA-4. **Smoke Management System** MR Provided 30 ACPH Basements Natural ventilation MR 12 ACPH Upper floors Fire Extinguishers 5. MR Total 40 No's Portable Fire Total numbers ABC/W.Co<sub>2</sub>/Co<sub>2</sub>-MR Extinguishers Types 15/15/10No's MR Yes ISI Marked IS marking First-Aid Hose Reels 6. 6 No's in basement MR Total numbers on each floor & 5 No's at GF Hose Reels 30m MR Length of hose reel hose MR 5mm Nozzle diameter Automatic fire detection and alarming system 7. MR Smoke & Heat Required Type of detectors MD

idad in bagan

The	Location of Repeater Panel	Required	All Floors	MR
	Alternate source of power		we do to as if he is	100
ad at 1	Hooters' Location	The Production of Edit	1.01 S-1. 8	
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Ground Floor	Required	Provided	MR
44	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants	D 1	100	MD
	Size of riser/down-comer	Required Required	100mm 6 Nos at basement	MR MR
	<ul> <li>Number of hydrants per floor</li> </ul>	Required	& 5 Nos at GF	IVIK
	Hose Box	Required	6 Nos at basement & 5 Nos at GF	MR
12.	Yard Hydrants			
	<ul> <li>Total number of hydrants</li> </ul>	Required	19 No's	MR
	Hose Box	Required	19No's	MR
13.	Pumping Arrangements			
- A.	Ground Level		1600 777	
	Discharge of main Pump	Required	1620 LPM	MR
	Head of Main pump	Required	70m	MR
	Number of main pumps	Required	One	MR
	Jockey Pump out put	Required	180 LPM	MR
	Jockey pump head	Required	70m	MR
	Standby Pump out put	Required	1620 LPM	MR
	Standby Pump Head	Required	70m	MR
-	Auto Starting/Manual Stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level	A series		
	Discharge of pump	Required	900 LPM	MR
	Head of the pump	Required	40m	MR
	<ul><li>Power Supply</li><li>Auto Starting of pump</li></ul>	Required	Provided	MR
	Auto Starting of pump	Required	Provided	NMR
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	1,00,000 Lts	1,00,000 Lts	MR
- 7	<ul><li>Draw-off connection</li><li>Fire service inlet</li></ul>	Required	Provided	MR
1	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	Required	Provided	MR
U	Overhead Tank capacity	Required	Provided	MR
15.	Exit Signage.	10,000 Lts	Provided Provided	MR MR
16.	Provision of Lifts.	Required	Provided	IVIK
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
100	Pressurization of Lift lobby	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	-NA-
	Fireman's Grounding Switch	-NA-	Provided	-NA-
	• Lift Signage			
17.		-NA-	-NA- Provided	-NA-
18.	Standby power supply Refuge Area.	Required	rrovided	MR
10.	Total Area	-NA-	-NA-	-NA-
	> Location	-NA-	-NA-	-NA-
19.	Fire Control Room	-11/1-	-INA-	-11/1-
44	Detector System Panel     -NA-     -NA-     -NA-			
123	Flow Switch Panel	-NA-	-NA-	-NA-
	TIOW DWITCH Lanci	-11/1-	-11/1-	-1N/A-

The Ocean Pearl Retreat Motel, KH No. 83, 84, 85, 90, 91/1-2, 101, 102, Chatterpur Mandir Road, Village-Satbari, Mehrauli, New Delhi

Building Floor Plans -NA- -NA- -NA
9. Special Fire Protection System for Protection of special Risks, if any: -NA-

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. The shortcomings communicated vide letter no F6/DFS/MS/Motel/2017/SZ/733 dated 22/03/2017 found complied.

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

Dy. CFO (SZ)

2824

Dogson

(1) FTM-

(11) Information of short commés & 18800 of FSC renewed now may be sent to DOMA also.

00F852

Sarp