GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/EH/2017/ 802

Dated: 06.06.2017

FIRE SAFETY CERTIFICATE

Certified that the Minar Restaurant located at L-11, Connaught Place, New Delhi-110001 comprised of Ground + 2 upper floor, Restaurant is running at ground & mezzanine floor only was granted FSC by this department vide letter No.F6/DFS/MS/EH/2013/550 dated 12/07/13 The premises was re-inspected by the officer concerned of this department on 18/05/17 in the presence of Mr. Amit Chopra (Proprietor) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D (Restaurant) with effect from - Delhi Fire Service of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, mentioned below.

Issued <u>66.66.2017</u> at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph-011-23412225

Copy to:- (1) North Delhi Municipal Council, Civic Centre, JLN Marg, New Delhi.

> (2) The Manager, Minar Restaurant,L-11,Connaught Place, New Delhi-110001.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

N-12

INSPECTION REPORT

1. Name & address of the building: Minar Restaurant, L-11, Connaught Place, New

Delhi-110001. 2. Type of occupancy:-

Group - D Assembly Building

Ground + 2 upper floor but restaurant is running on ground & mezzanine floor only.

3. Type of case:-Renewal

4. Details of previous NOC:-No. F6/DFS/MS/EH/2013/550 dated

12/07/13.

5. Fire safety directives No.-

N/A 6. Date of inspection:-

18/05/17 7. Name of the inspecting officer:-

Dy. CFO Sunil Chowdhary, D.O. Gurmukh Singh & A.D.O. Manoj Kumar Sharma.

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

Sh. Amit Chopra (Prop.)

Old Heritage Nil dated 24/04/17

S.No.	Minimum Ctar 1 1 C			Old Case
	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement / Existing Fire Safety Measures		e Remarks MR/NMR
1.	Access to Building			
	1) Road width	6 mtr.	6 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Ar	rangement of Ex	rits	IN/A
	A. Number of staircases			
	1. Upper floors	02 no.	02 no.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase		- 1111	IVA
	1. Upper floors (mezz. floor)	.75 mtr &. 85 mtr	.75 mtr. & 90 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			IVA
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1.5 mtr.	.90 mtr. & 1.69 mtr.	MR
	Compartmentation	· y • · · · · · · · · ·		
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System			11/11
	1) Basements	30 a/c per	N/A	N/A

	2) Unper floors (Co. 1.3	hour		1 1
	2) Upper floors (Ground fl.	I	r Exhaust fan	MR
5.	Fire Extinguial	hour		1411
	Fire Extinguishers 1) Total numbers	. 17 6. 1		
	2) Types	10 Nos.	10 Nos.	MR
	3) ISI marking	ABC & C	CO2 ABC & CO2	MR
6.	5) 1SI marking	Required	Provided	MR
0.	First-Aid Hose Reel	IVIIX		
	1) Total number of eachfloo	01	MR	
	2) Length of hose reel hose	30 m	30 m	MR
7.	3) Nozzle diameter	5 mm	-	
/•	Automatic Fire Detection	& Alarming S	System	MR
	1) Type of detectors	N/A	N/A	DI/A
	2) Location of main panel	N/A	N/A	N/A
- 7-	3) Location of repeater panel	1 NI/A	N/A	N/A
	4) Alternate source of nower	· N/A	N/A	N/A
0	3) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	N/A
9.	Public Address System	NIA		MR
10.	Automatic Sprinkler System	n	N/A	N/A
	1) Basement	N/A	NT/A	
	2) Upper floors	Required	N/A	N/A
	3) Sprinkler above false	N/A	Provided	MR
	ceiling	IVA	N/A	N/A
11.	Internal Hydrants	1	A CONTRACTOR	
	1) Size of riser/down-comer	N/A		
-	2) Number of hydrants per		N/A	N/A
	floor	N/A	N/A	N/A
	3) Hose box	NI/A		
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants			
	2) Hose box		N/A	N/A
3.	Pumping Arrangement	N/A	N/A	N/A
	1) Ground level			
	7 5214 10 101		8	
	, see of main	N/A	N/A	N/A
	pump b) He le c	*		IVA
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
1	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A		N/A
	stopping	IVA	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 7 77	
	b) Head of pump		450 LPM	MR
	c) Power supply	30 mtr.	30 mtr.	MR
All	, suppry	Required	Provided	MR

w

	d) Auto starting of pump	Required	Provided	MR			
14.							
	1) Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	Required	Provided	MR			
	c) Access to tank	Required	Provided	MR			
	d) Over head tank capacity	5,000 ltrs.	5,000 ltrs.	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
	a) Pressurization of lift shaft	N/A	N/A	N/A			
	b) Pressurization of lift lobby	N/A	N/A	N/A			
	c) Communication in lift car	N/A	N/A	N/A			
	d) Fireman's switch	N/A	N/A	N/A			
	e) Lift signage	N/A	N/A	N/A			
17.	Stand by Power Supply	Required	Provided	MR			
18.	Refuge Area	N/A	N/A	N/A			
	Total area location	N/A	N/A	N/A			
19.	Fire Control Room	N/A	N/A	N/A			
	a) Detector system panel	N/A	N/A	N/A			
	b) Flow switch panel	N/A	N/A	N/A			
	c) PA system panel	N/A	N/A	N/A			
	d) Battery backup	N/A	N/A	N/A			
	e) Building floor plan	N/A	N/A	N/A			
20.	Special Fire Protection Syste Risk, if any:	N/A					

The fire protection system provided in the restaurant were tested, checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/ DFS/MS/EH/2013/550 dated 12/07/13, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Sunil Chowdhary Dy. C.F.O.

Gurmukh Singh
Divisional Officer

Manoj Kumar Sharma Assistant Divisional Officer