## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2017/ 888

Dated :----21/26/17

## FIRE SAFETY CERTIFICATE

Issued -- 21/06/17---- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011-23412225

Copy to: -

The Joint. C.P.(Lic.), Police Station, Defence colony, 1<sup>st</sup> floor, New Delhi.

2. The Manager, Taj & Brothers Guest House 750, Motor Market, Jama Masjid, Delhi-110006.

. Conditions:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.

3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to it expiry

-14/15-

## INSPECTION REPORT

1. Name & address of the building:- Taj & Brothers Guest House located at 750,

Motor Market, Jama Masjid, Delhi

2. Type of occupancy:-

Residential Group A-1 (Ground + 2 upper floors), Ground floor (commercial use), 1<sup>st</sup> floor (reception + 06 guest rooms + 29 private rooms), 2<sup>nd</sup> floor (05 guest rooms + 27 private rooms for owner residence)

Total 11 guest rooms

3. Type of case:-

Renewal

4. Details of previous FSC: -

No. F6/DFS/MS/GH/2013/589

dated 12/02/2013.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

10/12/16

7. Name of the inspecting officer:-8. Name & designation of officer

A. D.O. Mehmood

From the building side:-

Shri Faroog (manager) 1966

9. Year of construction:-10. Applicant's letter No:-

3920/joint C.P./Lic.(H), dated - 10/11/2016

Old case

	•			Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (Existing Fire Safety Measures)	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	18 mtr.	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrar	ngement of Exits		
2.	A. Number of staircases			
	1. Upper floors	02 No	02 No.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.80 mtr., 0.91 to 1.02 mtr	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
2	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1.0 mtr.	1.0 mtr.	MR
	Compartmentation	1 2.00 2222		
3.	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts		N/A	N/A
	2) Sealing of electrical share	7 1/7 2		- 8

- H/16-

	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	DT/A		
	5) Fire Dampers	N/A	N/A	N/A N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural	N/A		
5.	Fire Extinguishers					
	1) Total numbers	07 Nos.	07 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel	1		*		
	1)Total number of each floor	01 No.	01 No.	MR		
	2) Length of hose reel hose	30 m	30 m	MR		
	3) Nozzle diameter	5 mm	5 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
3.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling		2	1 1/12		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	į.		1		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants					
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump		000 HATHAUST 50000			
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping		- 11.5	11/11		

ald

		17/19				
	2) Terrace level					
	a) Discharge of pump	225 LPM	Provided	MR		
	b) Head of pump	30 mtr.	Provided	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pump	Required	Provided	MR		
14.	Captive Water Storage for Fire Fighting					
	1) Under ground tank	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	2500 ltrs.	2500 ltrs.	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.		Tiovided	IVIK		
	a) Pressurization of lift shaft	N/A	37/4			
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A N/A	N/A	N/A		
7.	Stand by Power Supply		N/A	N/A		
8.	Refuge Area	Required	Provided	MR		
0.		N/A	N/A	NA		
	Total area location	N/A	N/A	N/A		
9.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel •	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A			
	d) Battery backup	N/A	N/A	N/A N/A		
	e) Building floor plan	N/A	N/A	N/A		
0.	Special Fire Protection System any:	for Protection of	special Risk, if	N/A		

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/GH/2013/589 dated 12/02/2013, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

D.O. (Central) Liver see is in possession of hic Assistant Divisional Officer

Dycho (NOZ)