GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2017/ MD2/1055

Dated: 19/1/17

FIRE SAFETY CERTIFICATE

Issued on at New Delhi by.

(Sunil Chowdhary)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

1. The Joint. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi

2. The Licensee,
G.S. Guest House,
908 & 937, Mantola, Gali Mandir Wali, Main Bazar, Pahar Ganj, New Delhi.

Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1.Name & address of the building:-G.S. Guest House,908 & 937, Mantola, Gali

Mandir Wali, Main Bazar, Pahar Gani, New

Delhi.

2. Type of occupancy:-Residential Group A-1 Ground + 4 upper

Floor (15 guest rooms) ground floor Rec. + 03 guest rooms, 1st to 3rd floor 04 guest rooms at each floor,

4th floor – servant rooms

3. Type of case:-Renewal.

4. Details of previous FSC:-F6/DFS/MS/GH/2014/NDZ/1146

dated 30/11/14

5. Fire safety directives No.-

N/A 22/06/17

6. Date of inspection:-

7. Name of the inspecting officer:-

D.O. Gurmukh Singh

8. Name & designation of officer From the building side:-

Mr. Chandan (Manager).

9. Year of construction:-

2013.

10. Applicant's letter No:-

Nil. dated 09/05/17

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety measures	Provided at site	Remarks MR/NMR
1.	Access to Building	measures	The state of the s	120
	1) Road width	N/A	4 mtr.	100
	2) Gate width	N/A	N/A	MR
	3) Width of internal road	N/A	NI/A	N/A
2.	Number, Width Type & Arra	ngement of Evita	IN/A	N/A
	A. Number of staircases	Engement of Laits		
	1. Upper floors	01 No.	01 No.	MD
	2. Basements	N/A	N/A	MR
	B. Width of staircase		IVA	N/A
1	1. Upper floors	150 cms.	150 cms.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits	1	14/11	IN/A
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
24	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
	Compartmentation		47. 64-75.	
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	3 7 1 1	N/A

4.	Smoke Management System			
	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers	12 Merri	Ivaturai	IVIIC
	1) Total numbers	08 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC &CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	required	Tiovided	IVIIX
	1)Total number at each	N/A	N/A	N/A
	floor	11/12	14/21	IVA
	2) Length of hose reel hose	N/A	N/A	N/A
	3) Nozzle diameter	N/A	N/A	N/A
7.	Automatic Fire Detection & A		14/11	14/21
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	11/11	11/11	IVA
1 11	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling		1771	14/21
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor			11/21
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		1242	11/21
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			11/11
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump	1071	IVA	IV/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	and the second s	N/A	N/A N/A
	d) Jockey pump out put	N/A	N/A	N/A N/A
	e) Jockey pump head	N/A	N/A	N/A N/A
	f) Stand by pump output	N/A	N/A	N/A
1	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A N/A
	stopping	11/11	IV/A	IN/A
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A N/A	
	-) or paintp	11/21	IN/A	N/A

	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for Fire Fighting					
	1) Under ground tank capacity	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	N/A	N/A	N/A		
15.	Exit Signage.	N/A	N/A	N/A		
16.	Provision of Lifts.	P 1				
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	N/A	N/A	N/A		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A		
20.	Special Fire Protection System any:	n for Protection	on of special Risk, if	N/A		

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/2014/NDZ/146 dated 30/11/2014, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

Gurmukh Singh Divisional Officer

There is allay in despressing.

of file . Pl note

(.F.b. M.SCEM, F.7/10).

MED MAY W.