GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2017/ MD2 1064

Dated: 15/2/17---

FIRE SAFETY CERTIFICATE

Issued ------at New Delhi by.

(Sunil Chowdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

The Addl. C.P.(Lic.), Police Station, Defence colony, 1st floor, New Delhi.

2. M/s Gulistan Guest House, 3861, Khirki Taffazul Hussain, Jama Masjid, Delhi-110006

Conditions:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.

2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.

3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

. This fire safety certificate may not be treated in any case for regularization of

unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to it

expiry

INSPECTION REPORT

1. Name & address of the building:- M/s Gulistan Guest House, 3861, Khirki Taffazul

Hussain, Jama Masjid, Delhi-110006.

Residential Group A-1, G + 4 (Guest house is at Ground floor to 3^{rd} floor, 07 rooms, 4^{th} floor is staff 2. Type of occupancy:-

rooms

3. Type of case:-Renewal

4. Details of previous FSC: -No. F6/DFS/MS/GH/2014/NDZ/939 dated

N/A

30/07/2014.

5. Fire safety directives No.-

6. Date of inspection:-22/06/17

7. Name of the inspecting officer:-A. D.O. Mehmood

8. Name & designation of officer

From the building side:-Sh. Mohd. Shoeb Azmi (Manager)

9. Year of construction:-1972

10. Applicant's letter No:-1143/Addl. C.P./Lic(H) dated - 07/06/2017

				Old case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (Existing Fire Safety Measures)	Provided at site (PSS)	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	03 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2	Number, Width Type & Arran	gement of Exits	0, 0, 0, 0		
	A. Number of staircases				
	1. Upper floors	01 No	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
1	B. Width of staircase				
	1. Upper floors	80 cms.	86 to 88cms.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01 No	01 No.	MR	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1 mtr.	1 mtr.	MR	
3.	Compartmentation	A LINE OF THE CO.			
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	12 ACPH	N/A	N/A	
5.	Fire Extinguishers		Bus III Busile		

	2	3
,		

	1) Total numbers			1
	2) Types	08 Nos.	08 Nos.	MR
		ABC & CO	O2 ABC & CO2	MR
6.	3) ISI marking	Required	Provided	MR A
0.	First-Aid Hose Reel			MIK
3	1)Total number of each	N/A	01 no. at 1 st	N/A
	floor		floor	IN/A
	2) Length of hose reel hose	N/A	30 m	NI/A
7	3) Nozzle diameter	N/A	_	N/A
7.	Automatic Fire Detection &	Alarming Syst	em	N/A
	1) Type of detectors	N/A		
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA		N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	Required	Provided	MR
Trenton	1) Basement			3
		N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
11.	ceiling			IN/A
11.	Internal Hydrants		·	
	1) Size of riser/down-comer	N/A	N/A	27/1
	2) Number of hydrants per	N/A	N/A	N/A
	floor	164	IN/A	N/A
	3) Hose box	N/A	NT/A	
2.	Yard Hydrants	11/21	N/A	N/A
	1) Total number of hydrants	N/A	77/4	
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement	IN/A	N/A	N/A
	1) Ground level	27/4		
	a) Discharge of main	N/A	N/A	N/A
		N/A	N/A	N/A
	b) Head of main nump			
	pully	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping		IVA	N/A
	2) Terrace level	N/A	01 no.	271
	a) Discharge of pump	N/A		N/A
	biboliarge of bullil	- 1/ L L	225 LPM	N/A
	b) Head of pump	N/A		
	b) Head of pump	N/A	40 mtr.	N/A
	b) Head of pump c) Power supply	N/A	40 mtr. Provided	N/A N/A
	b) Head of pump c) Power supply d) Auto starting of pump	N/A	40 mtr.	
	b) Head of pump c) Power supply d) Auto starting of pump Captive Water Storage for Fire F	N/A	40 mtr. Provided	N/A

-

	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	N/A	2500 ltrs.	N/A
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	Provided	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/GH/2014/939 dated 30/07/2014, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

Assistant Divisional Officer

C.F.P. M. Scell 14/8.
F. J. Letter is part up for sign.