## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO.F6/DFS/MS/School/2017/SZ/ / 7 6 5

Dated: 8/12/17

## FIRE SAFETY CERTIFICATE

Certified that the Shokeen International School located at Chhawla, New Delhi-110071, having two blocks namely Old block & Primary block, comprised of ground plus one upper floor & Admn. Block ground floor with small basement was office vide letter this Safety Certificate by Fire granted F6/DFS/MS/School/2014/SZ/592 dated 9.5.2014 for Old block. The said school building was inspected by the officer concerned of this department on 25.11.2017 in presence of Smt. Kusum Rathore (Principal) and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Directorate of Education, Govt. of NCT of Delhi, and that the building is fit for occupancy class B "Educational building" for Old & Primary block with effect from. @./١٤٠٠.... for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on ...... 8. 1.7.... at New Delhi by

( Vipin Kental)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. Director (Education) GNCT of Delhi, Old Secretariat, New Delhi.

2. Principal, Shokeen International School located at Chhawla, New Delhi-110071.

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

sso Dwales

				<b>INSPECTION RE</b>	PORT			
	1	Name 8	address of the building	SHOKEEN INTERNATIONAL SCHOOL, Chaawla , New Delhi-110071.				
	2	Type of	Occupancy	Educational Building "B"				
	3	_		Renewal G+1 Addition of New Block				
	4	Details	of previous NOC	No.F6/DFS/MS/School/2014/SZ/592 dated 9.5.2014			1.4	
	-	Circ cof	An alimenting at the Al					
	5	Fire safety directives letter No  Date of inspection		Edu. Circular. No. F.16/Estate/CC/Fire Safety/2011/3298 dated 01.03.2011.				
6 Date of in			·	25.11.2017				
	7	Name o	f the inspecting Officers :	ADO S.P. Bhardwaj				
	8	from the	nd designation of officers building side	Smt. Kusum Rathore (Principal).				
	9	Year of	construction	2004, 2016				
	10		t's letter No.	SIS/02/17/71 Dated 25.10.2017 namely C wing (G+		namely Old v	ed of Two Blocks  Old wing & Primary  1) & Admn. Block (GF	
	S. NO.	and fire	n Standards on fire prevention safety U/R 33	DOE CIR. Dated 1.3.2011/ letter dated 9.5.2014	Provide	ed at site	Remarks MR / NMR	
-	1	Access	to building	·				
		1) Road		6 Mtrs.	5 Mtrs.		MR being old case	
		2) Gate v		₱5 Mtrs.	4.8 Mtrs.		MR	
L	2		of internal road	N/A	N/A		N/A	
$\vdash$		number,	width Type & arrangement of	exits			1.07.	
		a. Numb	er of staircases					
		1. Upper		2 Nos. each wing	2 Nos. each wi	ng	MR	
		2. basem <b>b. Width</b>	ents of staircase	N/A	N/A		N/A	
	- 4	1. Upper	f <mark>loors</mark>	1.50 & 75 Mtrs. each wing	200,150 & 190	0,160 Cms.	MR	
		2. basem	ents	N/A	N/A			
		1	tion of exits	110/74			N/A	
	- 1	1. Fire ch		N/A	N/A	· · · · · · · · · · · · · · · · · · ·	N/A	
		2. Pressu	rization	N/A	N/A		N/A	
		d. No.	of continuous staircase to		Provided		N/A MR	
		terrace					IVIIX	
		e. Width o	of corridor	1.50 Mtrs.	3.40, 190 & 360	Cms.	MR	
		f. Door siz		1 Mtr.	120 & 110 Cms	S.	MR	
		1. Fire che	nentation.	NI/A				
		_ ^ ^		N/A	N/A		N/A	
				N/A	N/A		N/A	
		4. water c		N/A	N/A		N/A	
		5. Fire dar		N/A	N/A		N/A	
				N/A	N/A		N/A	
		Smoke Management system.			INVA			
				N/A	N/A		N/A	
		ipper floor			Natural Ventilation	on	MR	
		Fire Extinguishers total numbers						
	7	ypes		11 NOS. COZ OK	Provided		MR	
					CO2 & ABC		MR	
	18	SI marking		SI Marked	Provided		MR	

NI	111
10	111

6	First-Aid Hose Reels.	111			
0	total numbers on each floor	N/A	Described to 0.0 D.D	1	
	Length of Hose reel hose		Provided in O & P Block	N/A	
	Nozzle Diameter	N/A	30 m	N/A	
7		N/A	5 mm	N/A	
-	Automatic fire detection and alarming system  Type of detectors  N/A  N/A				
	location of Main Panel	N/A	N/A	N/A	
		N/A	N/A	N/A	
	location of Repeater panel	N/A	N/A	N/A	
	Alternate source of power hooter's location	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9		N/A	N/A	N/A	
10	Public Address System.	N/A	Provided	N/A	
10	Automatic Sprinkler System.	DI/A			
	basement	N/A	N/A	N/A	
	upper floors	N/A	N/A	N/A	
44	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
	Size of riser/down-corner	N/A	N/A	N/A	
	Number of Hydrants per floor	N/A	N/A	N/A	
42	hose Box	N/A	N/A	N/A	
12	Yard Hydrants.	1.00			
	total number of hydrants	N/A	N/A	N/A	
40	hose box	N/A	N/A	N/A	
13	Pumping arrangements			1	
	1. Ground level				
	a. Discharge of main Pump	N/A	N/A	N/A	
	b.Head of main pump	N/A	N/A	N/A	
	c.Number of main pumps	N/A	N/A	N/A	
	d.jockey pump out put	N/A	N/A	N/A	
	e.jockey pump head	N/A	N/A	N/A	
	f. Standby Pump output	N/A	N/A	N/A	
	g.Stanby Pump head	N/A	N/A	N/A	
	h.Auto Starting/Manual stopping	N/A	N/A	N/A	
	pump house access	N/A	N/A	N/A	
	2.Terrace level	NICA			
	a. Discharge of pump	N/A	220 LPM each block	N/A	
	b. head of the pump	N/A	40 m	N/A	
	c. Power supply	N/A	Provided	N/A	
	d. Auto starting of pump	N/A	N/A	N/A	
14	Captive water storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	a. Draw-off connection	N/A	N/A	N/A	
	b. fire service inlet	N/A	N/A	N/A	
	c.Access to tank	N/A	N/A	N/A	
	Over head tank Capacity	N/A	2500 Lts. each block	N/A	
15	Exit Signage.	N/A	Provided Provided	N/A	
16	Provision of lifts.		Ti Tovidou	IN//A	
	a. Pressurization of lift shaft	N/A	N/A	N/A	
	b. pressurization of lift lobby	N/A	N/A	N/A	
	c. communication in lift car	N/A	N/A	N/A	
	d. Fireman's grounding switch	N/A	N/A		
	e. Lift signage	N/A	IN/A	N/A	

A			- N	1/12				
17	Standby power	ersupply	N/A	N/A	N/A			
18	Refuge Area.			Not Requi	red			
	total area							
	location	1						
19	Fire control ro	oom						
	a. detector sys	tem Panel	N/A	N/A	N/A			
	b. Flow switch	Panel	N/A	N/A	N/A			
	c. PA system F		N/A	N/A	N/A			
	d. Batter backı	-	N/A	N/A	N/A			
4	e. Building floo		N/A	N/A	N/A			
20	Special Fire P	Special Fire Protection systems for protection of special risks, if any: ABC Fire Extinguisher provided nea						
	electric Meter	MR MR						
The fire pr	otection system	s provided in the build	ling were checked a	and found functional at the	time of inspection			
Shortcomi	ngs vide letter n	o. F6/DFS/MS/Schoo	1/2017/SZ/1697 date	ed 6.7.2017 found rectified	d.			
Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required DOE CIR. Dated 1.3.2011, FSC issued vide letter no.F6/DFS/MS/School/2014/SZ/592 dated 9.5.2014 for Old recommended for issuance of FSC for Old block & Primary block.  Accordingly DFA is put up for approval and signature please.								
				Sue	1			
					271117			
HE STATE				S.P. Bna	rawaj			
				ADO (Dw	varka)			
mals w	J. 40	30/11/	17					
50/11/2017		(Q)						
Tall Sales File		Lepy						
6/12/0	312	70)						
	C	6572) N	FT.	M. 1/12				
		F		p for Signal	- M			
		Cfns24			South			
					Sour			
	manufacture of the second				011117			