GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2018/ 93

Dated : 01.01. 2018

FIRE SAFETY CERTIFICATE

Issued -2/21. 2018 -- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: - 011-23412225

Copy to: -

1 The Joint Commissioner of Police (Lic.), 1st Floor, Police Station, Defence Colony, New Delhi.

2 The Manager, M/s. Prince Hotel 751, Church Mission Road, Fatehpuri, Delhi. Conditions:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry"

-N'34-

INSPECTION REPORT

1. Name & address of the building:- M/s Prince Hotel 751, Church Mission

Road, Fatehpuri, Delhi.

2. Type of occupancy:-Residential Group A-1 (Ground+ 03 Upper Floors) Total 22 guest rooms

3. Type of case:-Renewal

4. Details of previous FSC: -No. F6/DFS/MS/GH/NDZ/2015/1501 dated 18/08/2015.

5. Fire safety directives No.-N/A 6. Date of inspection:-16/12/17

7. Name of the inspecting officer:-D.O. Gurmukh Singh.

8. Name & designation of officer From the building side:-

Shri Mukesh Kumar Gupta (prop.) 9. Year of construction:-1980 10. Applicant's letter No:-

2902-03/Addl. C.P./Lic.(H)Dated 06/10/17

S.No.	3.6		Old Case				
	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement (Existing)	Provided at site	Remarks MR/NMF			
1.	Access to Building						
	1) Road width	N/A	30 mtr.	MD			
	2) Gate width	N/A	N/A	MR N/A			
- Andrews	3) Width of internal road	N/A	NI/A				
2.	Number, Width Type & Arra	angement of Exits	11/11	N/A			
	A. Number of staircases						
	1. Upper floors	01 No	01 No.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase			IVA			
	1. Upper floors	0.80 mtr	0.82 mtr. to 1.20 mtr	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits			1 11 12 1			
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization D. No. of continuous	N/A	N/A	N/A			
	staircase to terrace	N/A	N/A	N/A			
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	N/A	N/A	N/A			
	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
	Smoke Management System	N/A	N/A	N/A			
	1) Recoments						
	2) Upper floors	N/A N/A	N/A	N/A			
	Fire Extinguishers	IN/A	N/A	N/A			

	1) T + 1			7		
	1) Total numbers	05 Nos.	08 Nos.	MR		
	2) Types	ABC & CO2	ABC & C02	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1)Total number of each	01 No.	01 No.	MR		
	floor					
	2) Length of hose reel hose	30 mm	30 mm.	MR		
	3) Nozzle diameter	5 mm	5 mm.	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System	1 === 10.2200	Tiovided	IVIIC		
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A	N/A		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling	1771	IVA	IN/A		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	DT/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	IV/A	IN/A	N/A		
	3) Hose box	N/A	N/A	DT/A		
12.	Yard Hydrants	IN/A	IN/A	N/A		
12.	1) Total number of hydrants	N/A	DT/A	NT/A		
	2) Hose box		N/A	N/A		
13.		N/A	N/A	N/A		
13.	Pumping Arrangement	2.7/				
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump					
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping	a	/			
*.	2) Terrace level	4.				
· ·	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 Mtr.	30 Mtr.	MR		
	c) Power supply	N/A	N/A	N/A		
	d) Auto starting of pump	Required	Provided	MR		
		required	TIOVIUCU	IVII		
14.	Captive Water Storage for Fire	Fighting				

	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5,000 Ltrs.	5,000 Ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		11011404	IVII
	a) Pressurization of lift shaft	N/A	N/A	N/A
-	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
9.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
0.	Special Fire Protection System for Protection of special Risk, if any:			

The licensee have converted guest rooms at 1st floor in stores and 3rd floor staff rooms in guest rooms.

The fire protection system provided in the guest house were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/DFS/MS/2012/GH/NDZ/1501 dated 18/08/2015, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended

> Gurmukh Singh Divisional Officer

CF.P- m.scell FT.M.

FT litter is put up for high