

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS; DELHI FIRE SERVICE, NEW DELHI-110001.

No.F6/DFS/MS/2018/SZ/ 95


Dated: 16/01/18

FIRE SAFETY CERTIFICATE

Certified that the Discotheque in the name and style of Y-Knot (A unit of Vinayak Solution) situated at 1st floor, Plot No.4, Hotel Radisson Blu, Sector-13, Dwarka, New Delhi owned/ occupied by Y-Knot (A unit of Vinayak Solution) was issued Fire Safety Certificate in the name of A State of Music (A unit of Focus Hospitality Pvt. Ltd) vide this department letter No. F.6/DFS/MS/2014/SZ/1865 dated 15.07.2014. The said premises was re-inspected by the officers concerned of this department on 24.12.2017 in presence of Sh. Deepesh Gupta (Manager) and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service, 2010 and that the building is fit for occupancy class D 'Assembly' building (Discotheque), with effect from 16/01/18. For a period of **Three** years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service, 2010, subject to conditions printed overleaf.

Issued on 16/01/18 At New Delhi by


(Vipin Kental)

 Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police, Office of the Additional Commissioner of Police, Licensing Unit, 1st floor, Police Station Defence colony, New Delhi.
2. Sh. Kishori Lal Sharma, R/O RZ-226-B/2, Puran Nagar, Palam Colony, New Delhi-110077.

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.

4125

INSPECTION REPORT

1	Name & address of the building	M/S Y-Knots (A unit of Vinayak Solution) Situated at First floor, Radisson Blu Hotel Plot No.4, Sector-13, Dwarka, New Delhi.		
2	Type of Occupancy	Assembly		
3	Type of case	Renewal		
4	Details of previous NOC	F6/DFS/MS/2014/SZ/865 dated 15.7.2014 in the name & style of A state of Music (A unit of Focus Hospitality Pvt.Ltd.)		
5	Fire safety directives letter No	Nil		
6	Date of inspection	24.12.2017		
7	Name of the inspecting Officers :	M K Chattopadhyay (DO SW), S.P.Bhardwaj (ADO Dwarka)		
8	Name and designation of officers from the building side	Sh.Deepesh Gupta (Manager)		
9	Year of construction	2010		
10	Applicant's letter No.	20465-471/Jt.C.P.(Amst.) Dated.20.5.2014		Discotheque at 1st Floor
		Building Having ground plus ten upper floor with three tier basements		
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement/ letter dated 15.7.2014	Provided at site	Remarks MR / NMR
1	Access to building			
	1) Road width	9 Mtrs.	provided	M/R
	2) Gate width	5 Mtrs.	provided	M/R
	3) Width of internal road	6 Mtrs.	provided	M/R
2	Number, width Type & arrangement of exits			
	a. Number of staircases			
	1. Upper floors	2	2	M/R
	2. basements	8+7+2 Ramps (for Radisson hotel)	provided	MR
	b. Width of staircase			
	1. Upper floors	1.5 Mtrs.each	provided	M/R
	2. basements	1.5 mts & 1.0 mts (for radission hotel)	provided	MR
	c. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	M/R
	d. No. of continuous staircase to terrace	8 Nos.(for radission hotel)	provided	M/R
	e. Width of corridor	2 Mtrs.	2 Mtrs.	M/R
	f. Door size	old case	2 Mtrs.& 1.6 Mtrs.	M/R being old case
3	Compartmentation.			
	1. Fire check door	N/A	N/A	N/A
	2. Sealing of electrical shafts	Required	Provided	M/R
	3. Fire Rating of shaft door	N/A	N/A	N/A
	4. water curtain	N/A	N/A	N/A
	5. Fire dampers	Required	Provided	M/R

4				
	basement	Required in basement (for radosson hotel).	provided	M/R
	upper floors	Required	Provided	M/R
5	Fire Extinguishers			
	total numbers	5 Nos. CO2 & ABC	5 Nos.	M/R
	Types	ISI Marked	provided	M/R
	ISI marking		Provided	M/R
6	First-Aid Hose Reels.	Connected with Hotel's Main systems		
	total numbers on each floor	Required (1)	Provided	M/R
	Length of Hose reel hose	30 Mtrs.	30 Mtrs.	M/R
	Nozzle Diameter	5 mm	5 mm	M/R
7	Automatic fire detection and alarming system	Connected with Hotel's main system		
	Type of detectors	Heat & Smoke	Heat & Smoke	M/R
	location of Main Panel	Required	Time office area	M/R
	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	Required	UPS	M/R
	hooter's location	Corridor	Provided	M/R
8	MOEFA	Required	Provided	M/R
9	Public Address System.	Required	Provided	Floor
10	Automatic Sprinkler System.			
	basement	Required for hotel	Provided	M/R
	upper floors	Required	Provided	M/R
	sprinkler above false ceiling	Required	Provided	M/R
11	Internal Hydrants			
	Size of riser/down-corner	150mm for hotel	150 mm	M/R
	Number of Hydrants per floor	1 No.	Provided	M/R
	hose Box	Required	Provided	M/R
12	Yard Hydrants.			
	total number of hydrants	N/A	N/A	N/A
	hose box	N/A	N/A	N/A
13	Pumping arrangements	Connected with Hotel's Main systems		
	1. Ground level			
	a. Discharge of main Pump	2850 Lpm. for hotel	2850 Lpm.	M/R
	b. Head of main pump	120 Mtrs.	120 Mtrs.	M/R
	c. Number of main pumps	Two	Two	M/R
	d. jockey pump out put	220 Lpm. for hotel	220 Lpm.	M/R
	e. jockey pump head	90 Mtrs.	90 Mtrs.	M/R
	f. Standby Pump output	2850 Lpm. for hotel	2850 Mtrs.	M/R
	g. Stanby Pump head	90 Mtrs.	90 Mtrs.	M/R
	h. Auto Starting/Manual stopping	Required	Auto Mode	M/R
	pump house access	Required	Provided	M/R
	2. Terrace level			
	a. Discharge of pump	900 Lpm. for hotel	900Lpm.	M/R
	b. head of the pump	40 Mtrs.	40 Mtrs.	M/R
	c. Power supply	Required	D.G. Set.	M/R
	d. Auto starting of pump	Required for hotel	Provided	M/R

427

14	Captive water storage for fire fighting			
	1. Underground tank capacity	2 Lac Ltrs.for hotel	2 Lac Ltrs.	M/R
	a. Draw-off connection	Required for hotel	Provided	M/R
	b. fire service inlet	Required for hotel	Provided	M/R
	c. Access to tank	Required for hotel	Provided	M/R
	Over head tank Capacity	20000 Lts.for hotel	20000 Lts.	M/R
15	Exit Signage.	Required	Provided	M/R
16	Provision of lifts.			
	a. Pressurization of lift shaft	Required for hotel	Provided	M/R
	b. pressurization of lift lobby	Required for hotel	Provided	M/R
	c. communication in lift car	Required for hotel	Provided	M/R
	d. Fireman's grounding switch	Required for hotel	Provided	M/R
	e. Lift signage	Required for hotel	Provided	M/R
17	Standby power supply	Required for hotel	DG Set	M/R
18	Refuge Area.	N/A		
	total area	Required for hotel	Terrace 130 Sq. M	M/R
	location	6th & 10th floor	6th & 10th floor	M/R
19	Fire control room	Connected with Hotel,s Main systems		
	a. detector system Panel	Required for hotel	Provided	M/R
	b. Flow switch Panel	Required	Provided	M/R
	c. PA system Panel	Required	Provided	M/R
	d. Batter backup	Required	Provided	M/R
	e. Building floor plans	Required	Provided	M/R
20	Protection of special risks:	Required	CO2 Fire Exting.	MR

The fire protection systems provided in the building were checked and found functional at the time of inspection. Keeping in view deemed compliance of the minimum standards on fire prevention & fire safety requirements as per letter dated 15.7.2014 , fire safety certificate is recommended. Accordingly DFA is put up for approval and signature please.

[Signature]
8/11/18

M K Chattopadhyay DO (SW)

[Signature]
24/11/17

S P Bhardwaj ADO (Dwarka)

937/00/SW
9/1/2018

[Signature]
9/1

CFO (S2)

M.S. cell

FT/10.
[Signature]
11/1



1530/cfo se
11/1/16/1

FT is put up for signature please

cfo s2

[Signature]
12/1/18