## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2018/SZ/ 257

Dated: 15 02 18

## FIRE SAFETY CERTIFICATE

Certified that M/s McDonald's Restaurant (M/s Connaught Plaza Restaurants Pvt. Ltd) located at 2, Community Centre, Saket, New Delhi-110017 comprised of Basement, Ground plus three upper floors. The restaurant running at ground and first floor with 80 seat covers was issued FSC by this department vide letter No. F6/DFS/MS/EH/2015/SZ/370 dated 16/03/2015. The restaurant premises was re-inspected by the officer concerned of this department on 01/02/2018 in presence of Mr. Rajat, Manager of the restaurant and observed that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Assembly, Group-D" (Restaurant) as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15 0 18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

- 1. The DHO (South Zone), South MCD, Public Health Deptt., Green Park, New Delhi-110016
- 2. Auth. Signatory, M/s McDonald's Restt, 2, Community Centre, Saket, New Delhi-110017

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		ON REPORT	D	it-:	
1	Name & Address of the Building	M/s McDonald's Restaurant at 2, Community			
		Centre, Saket, New Delhi-110017			
and the second		(M/s Connaught Plaza Restaurant Pvt. Ltd)			
2	Type of Occupancy	Assembly 'Group-	D' (Restaurant)		
3	Building comprised of	Basement, Ground plus three upper floors.			
	Type of Case	Renewal			
4	Details of Previous NOC	F.6/DFS/MS/EH/2015/SZ/370 Dated 16-03-2015			
5	Fire Safety Directives Letter No	Nil			
6		01-02-2018			
7	Date of Inspection  Name of the Inspecting Officers	R.N. Singh, ADO (BCP)			
8	Name & Designation of Officers	Mr. Rajat (Manager)			
9	Name & Designation of Officers				
	from the building side Year of construction	1986 Restt runn	ing at ground & 1st floo	r of the bldg	
10		Nil dated 27-10-2017			
11	Applicant letter No.  Minimum standards on Fire Prevention	Old NOC Provided at Site Rema		Remarks	
S. No		requirement		MR/NMR	
	and Fire Safety U/R 33	requirement			
1	Access to Building.	Required	06 mtr	MR	
	Road width	N/A	N/A	N/A	
	Gate width	N/A	N/A	N/A	
	Width of internal road	IN/A	1471		
2	Number, width, type & arrangement of exits				
	a. Number of Staircase	D : 1	2 Nos	MR	
	<ul> <li>Upper floors</li> </ul>	Required		MR	
	Basement floor	Required	2 Nos	IVIIC	
	b. Width of Staircase			MD (ald aggs)	
	Upper floors	Required		MR (old case)	
	Basement floor	Required	1.25 & 0.65m	MR (old case	
	c. Protection of exits		· · · · · · · · · · · · · · · · · · ·	77/4	
	Fire check door	N/A	N/A	N/A	
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A	
	d. No. of continuous staircase to terrace	Required	One	MR	
	******* C -13	N/A	N/A	N/A	
	f. Door size	Required	1.5m	MR	
2	Compartmentation.	-			
3	- 1 1 1	N/A	N/A	N/A	
	<ul><li>Fire check door.</li><li>Sealing of electrical shafts.</li></ul>	N/A	N/A	N/A	
		N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
NAME OF TAXABLE PARTY.	Water curtain	N/A	N/A	N/A	
	Fire dampers.	14/11			
4.	Smoke Management system.	30 ACPH	N/A	N/A	
	Basement		Exhaust fans Provid	ed MR	
	<ul> <li>Upper floors</li> </ul>	12 ACPH	Exhaust fails i fovid	CG THE	
5.	Fire Extinguishers.			3.573	
	Total numbers		08 No's	MR	
	• Types	ISI marked	ABC-04, Co2-04	MR	
	ISI Marking		Provided	MR	
-	First Aid Hose-reels.	a realization			
6.		*	One	MR	
	Total numbers on each floor.	Hose-reel	30 m	MR	
	<ul> <li>Length of hose-reel hose.</li> </ul>	11050 1001	5 mm	MR	
	Nozzle Diameter		J 111111	I IVII	

M/s McDonalds Restaurant at 2, Community Centre, Saket, New Delhi

7	Automatic fire detection & alarming system.			
	Type of detectors	N/A	N/A	N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper floors	Required	Provided	MR
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
11.	Internal Hydrants.			
	Size of Riser/Down-comer	N/A	N/A	N/A
	Number of Hydrant per floor	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12.	Yard Hydrants.			1
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			- 1124
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting / Manual Stopping.	N/A	N/A	N/A
	Terrace Level	16 1		
	Discharge of pump.	450 & 180 LPM	450 & 180 LPM	MR
	➤ Head of pump.	35 mtr	35 mtr each	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.			
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 ltrs	5,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
- = -	<ul> <li>Pressurization of lift shaft.</li> </ul>	N/A	N/A	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	<ul> <li>Communication in lift car.</li> </ul>	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	<ul> <li>Lift signage.</li> </ul>	N/A	N/A	N/A
-	Standby Power Supply	Required	Provided	MR
-	Standby Power Supply Refuge Area			MR
17 18.	Standby Power Supply	Required N/A	Provided N/A	MR N/A

M/s McDonalds Restaurant at 2, Community Centre, Saket, New Delhi

19.	Fire Control Room.			
	<ul><li>Detector System Panel.</li><li>Flow Switch Panel.</li></ul>	N/A	N/A	N/A
		N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	D 1 1	N/A	N/A	N/A
	Battery backup     Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any :			-

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/DFS/MS/EH2015/SZ/370 dated 16/03/2015, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: R.N. Singh

Designation: ADO (BCP)

M/s McDonalds Restaurant at 2, Community Centre, Saket, New Delhi

DO (SD) Julash 2/218