## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

**NEW DELHI- 110001** Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2018/SZ/ So4

24/4/<sub>18</sub>

## FIRE SAFETY CERTIFICATE

Certified that M/s Social & Tinur Restaurants (A unit of Epiphany Hospitality Pvt. Ltd) located at 1<sup>st</sup> & 2<sup>nd</sup> Floor of 9-A, 12 & T-12A, Hauz Khas Village, New Delhi-110016 comprised of Ground + Three Upper Floors. The restaurant running at 1<sup>st</sup> & 2<sup>nd</sup> floor only was issued FSC by this department vide letter No. F.6/DFS/MS/EH/2015/SZ/164 dated 05/02/2015. The restaurant premises was re-inspected by the officer concerned of this department on 05/02/2018 in the presence of Mr. Arun Rana (Manager) of the restaurant and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class 'Assembly' Group—D (Restaurant) as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions mentioned below.

Issued on 94/4/8 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

Kale

- 1. Sh. Satyajit Dhingra, M/s Social & Tinur Restaurant (A unit of Epiphany Hospitality Pvt. Ltd.) at 9-A, 12 & T-12A, Hauz Khas Village, New Delhi-110016
- 2. The DHO, South MCD, Public Health Deptt., South Zone, Green Park, New Delhi-110016

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept unlocked & free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	IV/						
		INSPECTION REPORT					
1	Name & Address of the Building	M/s Social & Tinur Restaurant, 1 <sup>st</sup> & 2 <sup>nd</sup> Floor, 9-A, 12 & T-12A, Hauz Khas Village, New Delhi-16					
		9-A, 12 & 1-12A, Hauz Knas Vinage, New Denni-10					
		(A Unit of Epiphany Hospitality Pvt. Ltd) Assembly "Group-D" (Restaurant)					
2	Type of Occupancy	Ground + 03 upper floors					
3	Building Comprised of	Renewal					
4	Type of Case	F.6/DFS/MS/EH/2015/SZ/164 Dated 05-02-2015					
5	Details of Previous NOC						
6	Fire Safety Directives Letter No	Nil 05-02-2018					
7	Date of Inspection	R.N. Singh, ADO (BCP)					
8	Name of the Inspecting Officers	Mr. Arun Rana (Manager)					
9	Name & Designation of Officers	Mr. Arun Kana (Manager)					
	from the building side	1980 Restt running at 1 <sup>st</sup> & 2 <sup>nd</sup> floor of the bldg.					
10	Year of construction	Nil dated 12-01-2018, ODD No. 668					
11	Applicant letter No.	Old NOC & Provided at Site Remarks					
S. No	Minimum standards on Fire Prevention and	Circular- 200		Linking at 21cc	MR/NMR		
	Fire Safety U/R 33	requirement		out of the state o	2.440		
	D TE	16dan cmen					
1	Access to Building.	6 mtr	4.	5m + 1.5m footpath	MR		
	Road width	V 1116	-		(old case		
		N/A		N/A	N/A		
	Gate width	N/A		N/A	N/A		
	Width of internal road	N/A					
2	Number, width, type & arrangement of exits						
	a. Number of Staircase			GF to terrace- 01 No	MR		
	Upper floors	Required		st to 2 <sup>nd</sup> floor- 02 No	(Old case		
	10	N/A		N/A	N/A		
	Basement floor	14/15					
	b. Width of Staircase		GI	to terrace- 0.94m	MR		
	Upper floors	Required	1st to 2	nd floor- 0.80 & 0.92m	(Old case		
	Basement floor	N/A		N/A	N/A		
	The Address of the second						
	Protection of exits     Fire check door	N/A	annual from	N/A	N/A		
	Pressurization	N/A		N/A	N/A		
		Required		One	MR		
	THE LAB CONTRACTOR	N/A		N/A	N/A		
	f. Door size	Two exit	S	1.15m & 0.90m	MR		
-	Compartmentation.		accessor and accessor accessor and accessor and accessor and accessor and accessor accessor and accessor accessor and accessor accessor accessor and accessor				
3		N/A		N/A	N/A		
4.		N/A	-	N/A	N/A		
	Sealing of electrical shafts.  Signature of shaft door.	N/A		N/A	N/A		
	Fire rating of shaft door.	N/A		N/A	N/A		
	Water curtain	N/A		N/A	N/A		
	Fire dampers.	14/21					
	Smoke Management system.	30 ACPI	1	N/A	N/A		
	Basement	12 ACPI	The same of the same of	Exhaust fans provided	MR		
	Upper floors	12 ACFR		Principal and be a comme			
5.	Fire Extinguishers.			18 No's	MR		
	Total numbers	101 1		ABC, Co2, Form	MR		
	Types	ISI marked		Provided	MR		
	ISI Marking			rrovided	IVII		
6.	First Aid Hose Reels.				MR		
	Total numbers on each floor.			One	MR		
	<ul> <li>Length of hose-reel hose.</li> </ul>	Hose-reels		30m			
	Nozzle Diameter	9-A, 12 & T-12A, Ha		5mm	MR		

M's Social & Tinur Restt at 1st & 2nd Floor, 9-A, 12 & T-12A, Hauz Khas Village, New Delh

7	Automatic fire detection & alarming system			The same of the sa
/	Type of detectors	Required	Smoke type	MR
	Location of Main Panel	Required	Near Entrance	MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
104	Basement	N/A	N/A	N/A
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
X A +	Size of Riser/Down-comer	Required	100 mm	MR
	Number of Hydrant per floor	Required	One	MR
	Hose box.	Required	One	MR
12.	Yard Hydrants.	1104 011 00		
1.40	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	1471	1	- 1111
13.	Ground Level			
		N/A	N/A	N/A
	> Discharge of main pump.	N/A	N/A	N/A
	<ul><li>Head of main pump.</li><li>Number of main pumps.</li></ul>	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	> Auto Starting/Manual Stopping.	N/A	N/A	N/A
	> Access to pump house	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	450 & 180 LPM	MR
	<ul><li>Head of pump.</li></ul>	40m	40m	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fighting.	COLUMN TO COLUMN THE PROPERTY OF THE PROPERTY		
	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	Required	As above	MR
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	10,000 Ltr	10,000 Ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	A CONTRACTOR OF THE PARTY OF TH		
	Pressurization of lift shaft.	N/A	N/A	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area	And the second s	**	
	Total area	N/A	N/A	N/A
			N/A	N/A
	Location  M/s Social & Tinur Restt at 1 <sup>st</sup> & 2 <sup>nd</sup> Floor, 9-4	N/A		

M/s Social & Tinur Restt at 1st & 2nd Floor, 9-A, 12 & T-12A, Hauz Khas Village, New Delhi

19. Fire Control Room. N/A N/A N/A Detector System Panel. N/A N/A N/A Flow Switch Panel. N/A N/A N/A PA system Panel. N/A N/A N/A Battery backup N/A N/A Building floor plan N/A N/A N/A N/A Special Fire Protection System for the 20. Protection of special Risk, if any:

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DF\$/MS/EH/2015/SZ/164 Dated 05-02-2015, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

M/s Social & Tinur Restt at 1st & 2nd Floor, 9-A, 12 & T-12A, Hauz Khas Village, New Delhi

Fire avilable Evad widthfor his units is now Y. Son as measured day inspecting officer and I have my seservation for recommending the case for renewal of FSC conder Rule 37, however Competent authority make take decision.

footmoded for faulte consideration of same Principle my be fallowed in similar case lood + feotpalli

GoCH

As the fact path of road is at same, level and it is a case of renewal- case.

1241/CAOSZ.