GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI-110001

No. F.6/DFS/MS/EH/2018/SZ/ Dated: 10 07 18

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Barcelos (A Unit of Barcelos India) situated at Shop No-309, 2nd floor, DLF Place, Saket, New Delhi-110017, comprised of Basement, Ground plus two upper floors but the restaurant running at 2nd floor of the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 28/06/2018 in the presence of Mr. Balpreet Singh (Partner) and that the premises is fit for occupancy class 'Assembly' Group-D (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 07/18 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. The Addl. Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
- 2. M/s Barcelos Restaurant at Shop No-309, 2nd floor, DLF Place, Saket, New Delhi-110017

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

		INSPECTIO	N REPORT	(A XX : CDles India) at	
1	Nam	e & Address of the Building	M/s Barcelos Restt. (A Unit of Barcelos India) at Shop No. 309, 2 nd Floor, DLF Place, Saket, ND-17			
			Accombly 'Groun	a-D' (Restaurant)		
2	Туре	e of Occupancy	Assembly 'Group-D' (Restaurant) Basement, Ground + 02 upper floors.			
		ding comprised of	New			
	Туре	e of Case	F6/DFS/MS/EH/2012/3128 dated 25-08-2012 in f/o			
5	Deta	ils of Previous NOC	Jubilant Food Works Ltd (Dunkin Donuts)			
	E.	C. C. L. Directives Letter No.	No. F6/DFS/MS/EH/2005/718 dated 04-04-2005			
		Safety Directives Letter No	28-06-2018			
7	Date	e of Inspection ne of the Inspecting Officers	Mehmood, ADO (SJ)			
8	Nan	ne & Designation of Officers	Mr. Balpreet Singh (Partner)			
9		the building side				
10		r of construction	2005 Restt run	ning at 2 nd floor in DLF Place	Bldg.	
11		licant letter No.	Outdoor Diary N	No. 8742 dated 13-06-2018		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33		Circular Dt. 04-04-2005		Remarks MR/NMR	
	anu	The Salety Critics	requirements	1		
1	Acc	ess to Building.	F6/DFS/MS/201	15/SZ/Mall/SZ/1954 Dtd. 30	-10-2015	
1	1100	Road width	Restt located	As above	MR	
и,		• Gate width	at 2 nd floor in	As above	N/A	
		Width of internal road	DLF Place	As above	N/A	
2	Nı	imber, width, type & arrangement of 6	exits			
	a.	Number of Staircase	Provided &	& Maintained by DLF Mall	Mgmt.	
		 Upper floors 	2 Nos	Provided	MR	
		Basement floor	N/A	As above	N/A	
	b.	Width of Staircase		& Maintained by DLF Mall	Mgmt.	
	0.50.5	Upper floors	1.5 mtr	1.5 mtr each	MR	
		Basement floor	N/A	As above	N/A	
	c.	Protection of exits	Provided & Maintained by DLF Mall Mgmt.			
		Fire check door	N/A	As above	N/A	
		Pressurization	N/A	As above	N/A	
	d.	No. of continuous staircase to terrace	One	As above	MR	
	e.	Width of corridor		N/A	N/A MR	
	f.	Door size	02 exits (2)	m41m) 2m x 2 Nos		
3	Co	mpartmentation.		& Maintained by DLF Mall As above	N/A	
		 Fire check door. 	N/A	As above As above	N/A	
		 Sealing of electrical shafts. 	N/A	As above As above	N/A	
		Fire rating of shaft door.	N/A N/A	As above	N/A	
		Water curtain	N/A N/A	As above As above	N/A	
		Fire dampers.		& Maintained by DLF Mal		
		The second secon		N/A	N/A	
4.	Sn	noke Management system.	20 ACDU			
4.	Sn	Basement	30 ACPH			
		BasementUpper floors	30 ACPH 12 ACPH	Provided in kitchen	MR	
4. 5.		BasementUpper floorsre Extinguishers.	12 ACPH	Provided in kitchen	MR	
		BasementUpper floors	12 ACPH Required	Provided in kitchen 08 Nos	MR MR	
		BasementUpper floorsre Extinguishers.	12 ACPH Required ABC / CO2	Provided in kitchen 08 Nos ABC & Co2	MR MR MR	
		 Basement Upper floors re Extinguishers. Total numbers 	12 ACPH Required ABC / CO2 ISI marked	Provided in kitchen 08 Nos ABC & Co2 Provided	MR MR MR	
5.	Fi	 Basement Upper floors re Extinguishers. Total numbers Types ISI Marking 	12 ACPH Required ABC / CO2 ISI marked	Provided in kitchen 08 Nos ABC & Co2 Provided Maintained by DLF Mal	MR MR MR MR I Mgmt.	
	Fi	 Basement Upper floors re Extinguishers. Total numbers Types ISI Marking irst Aid Hose Reels. 	12 ACPH Required ABC / CO2 ISI marked	Provided in kitchen 08 Nos ABC & Co2 Provided	MR MR MR MR I Mgmt. MR	
5.	Fi	 Basement Upper floors re Extinguishers. Total numbers Types ISI Marking irst Aid Hose Reels. 	Required ABC / CO2 ISI marked Provided	Provided in kitchen 08 Nos ABC & Co2 Provided Maintained by DLF Mal	MR MR MR MR I Mgmt.	

M/s Barcelos Restt at Shop No-309, 2nd floor, DLF Place, Saket, New Delhi-110017

7	Automatic fire detection & alarming system.	Provided &	Maintained by DLF Mall	
	Type of detectors	Required	Smoke & Heat	MR
	Location of Main Panel	Required	Near Entrance	MR
	Location of Repeater Panel	N/A	N/A	MR
	Alternate source of power	Required	Provided	MR
	Hoofer's location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System	Provided &	Maintained by DLF Mal	l Mgmt.
100	Basement	N/A	As above	N/A
	Upper floors	N/A	Provided in Restt	N/A
	Sprinkler above false ceiling	N/A	As above	N/A
11.	Internal Hydrants.	Provided &	Maintained by DLF Mal	l Mgmt.
	Size of Riser/Down-comer	N/A	As above	N/A
	Number of Hydrant per floor	N/A	As above	N/A
	Hose box.	N/A	As above	N/A
12.	Yard Hydrants.		Maintained by DLF Mal	
14.	Total number of hydrants.	N/A	As above	N/A
	Hose box.	N/A	As above	N/A
12		13/23	115 45010	111.1
13.	Pumping arrangements. • Ground Level	Provided & Maintained by DLF Mall Mgmt.		
		N/A	4500 LPM	N/A
	Discharge of main pump.	N/A	70 mtr	N/A
	> Head of main pump.	N/A	Two	N/A
	Number of main pumps.	N/A	450 LPM	N/A
	Jockey Pump output.Jockey Pump head.	N/A	70 mtr	N/A
	> Standby Pump output.	N/A	4500 LPM	N/A
	> Standby Pump head.	N/A	70 mtr	N/A
	> Auto Starting / Manual Stopping.	N/A	Provided	N/A
	> Pump House Access	N/A	Provided	N/A
	Terrace Level	Provided & Maintained by DLF Mall Mgmt.		
	> Discharge of pump.	Required	As above	MR
	Head of pump.	Required	As above	MR
	> Power supply.	Required	As above	MR
	> Auto starting of pump.	Required	As above	MR
14.	Captive water storage for Fire Fighting.		Maintained by DLF Ma	
17.	Underground tank capacity.	N/A	1,50,000 Ltr	N/A
	Draw-off connection.	N/A	Provided	N/A
	Fire Service Inlet.	N/A	Provided	N/A
	Access to tank.	N/A	Provided	N/A
	Overhead tank capacity.	5,000 Ltr	20,000 Ltr	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		& Maintained by DLF Ma	Il Mgmt.
	Pressurization of lift shaft.	N/A	As above	N/A
	Pressurization of lift lobby.	N/A	As above	N/A
	Communication in lift car.	N/A	As above	N/A
	• Fireman's switch.	N/A	As above	N/A
	• Lift signage.	N/A	As above	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area	required	11011404	1711
10.	Total area	N/A	N/A	N/A
		N/A	N/A	N/A
	Location M/s Barcelos Restt at Shop No-309, 2 nd flo			IN/A

M/s Barcelos Restt at Shop No-309, 2nd floor, DLF Place, Saket, New Delhi-110017

19. Fire Control Room. Provided & Maintained by DLF Mall Mgmt.

	Protection of special Risk, if any:			
20.	Special Fire Protection System for the	N/A	As above	N/A
	Building floor plan	N/A	As above	N/A
	Battery backup	N/A	As above	N/A
•	PA system Panel.	N/A	As above	N/A
	Flow Switch Panel.	N/A	As above	N/A
	Detector System Panel.	N/A	As above	N/A

The Fire protection systems provided in the premises/building were test checked at random and found functional at the time of inspection. Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Barcelos Restt at Shop No-309, 2nd floor, DLF Place, Saket, New Delhi-110017

FSCof Mallis placed in partfile.

DO (8D)

F.F letter is pul up for signalius pl.

Cho

Mrscell 1972.