GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001 Dated: 18 16 118

No. F.6/DFS/MS/EH/SZ/2018/ 1416

FIRE SAFETY CERTIFICATE

Certified that the Diva Restaurant situated at M-8, Greater Kailash-II, M Block Market, New Delhi-110048, comprised of Basement, Ground & 3 Upper Floors but the restaurant is running on Ground & 1st floor only was issued FSC vide letter No. F6/DFS/MS/SZ/EH/2015/603 dated 23/04/2015. The premises was re-inspected by the officer concerned of this department on 08/06/2018 in the presence of Mr. Sanjeev (Manager) and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group-D Assembly "Eating House" Building with effect from 18 / 6 /2018 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 1876 118 at New Delhi by

(Vipin Kental) Chief Fire Officer Tel: 011-23412225 ble to

Copy to:-

- 1. Sh. Aman Jain (Authorized Signatory), Riga Foods, C-107. Okhla Industrial Area, Phase-I, New Delhi-110020
- 2. The Addl. C. P. (Lic). 1st Floor. P. S. Defence Colony, New Delhi-1100241.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1	INSPEC	CTION REPORT		
1.	Name & address of the building: Diva Restaur 110048	ant, M-8, Greater Ka	ilash-II, M Block Mark	et, New Delhi-
2.	m			
3.	T	embly Building [Buil	ding is B+G+3 upper	floors
4.	. Reflewal	Restaurant is ru	mning of C D P. 181 c	oor onlyl
5.	Fire Safety directives letter No: Nil	SZ/EH/2015/603 date	ed 23/04/2015	
0.	Date of inspection . 08/06/2019			3.
7.	Name of Inspecting Officer · A K Malik			
8.	Name and designation of officers			
	From the building side Mr. Saniogy (Managar)		
9.	Year of Construction · 1978	withing (1)		
10.	Applicant's letter No. : Outdoor diary	no. 7928 dated 28/0	15/2018	
5.1	vinimum Standards on fire prevention	2005 circular/Rule	Provided at site	Remarks
	and fire safety U/R 33	35(6) Requirement	O TACACCA LLE SILL	
1.	Access to building	•		MR/NMR
	recess to building			
	 Road width 	Accessible (4-5m)	Provided	1.00
	• Gate width ·	-NA-	-NA-	MR
	 Width of internal road 	-NA-	-NA-	-NA-
2.	Number, Width, Type & Arrangement (of Exits	1771	-18/4-
	a. Number of staircases		-	
	- Addition of staticases			
	• Upper Floors	Two exit	Provided Three	
	 Basements 	-NΛ-	The state of the s	MR
	b. Width of staircases		-NA-	-NA-
	 Upper Floor 	Required	1.1m 1.10.0	
	Basements	-NA-	1.1m, 1.1m,0.8m	MR
	c. Protection of exits	4.47.1	-NA-	-NA-
	• Fire check door	-NA-	N. C.	
	• Pressurization	-NA-	-NA-	-NA-
	d. No. of continuous staircases to terrace	-NA-	-NA-	-NA-
	e. Width of Corridor	-NA-	One .	-NA-
	f. Door Size		-NA-	-NA-
3.	Compartmentation	Two Exit	1.05m & 0.95m	MR (old case)
		<u>~</u>		
	Fire check door	-NA-	NA-	-NA-
	Sealing of electrical shafts	-NA-	-NA-	-NA-
	Fire Rating of shaft door	-NA-	-NA-	-NA-
	• Water Curtain	-NA-	-NA-	-NA-
4.	• Fire Dampers	-NA-	-NA-	-NA-
**	Smoke Management System			1
	Basements	-NA-	-NA-	-NA-
	• Upper floors	Exhaust Fan	Exhaust Fan	MR
5.	Fire Extinguishers			
	 Total numbers 	ISI	8 No's	MR
	• Types		ABC/CO ₂ /CO ₂ -4/4/-	MR
6	IS marking	Marked	Yes	MR
6.	First-Aid Hose Reels		1 00	TATIX
	Total numbers on each floor	Hose Reel	One at each level	MR
	I oneth a Cl		30m	-NA-
,	• Length of hose reel hose		5mm	-NA-
7.	Nozzle diameter Automatic fire detection and detecti			
	Automatic fire detection and alarming syst • Type of detectors		- L	
	. The or defectors	-NA-	NIA	374

	Location of Main Panel	-1\/\-	-1//\-	-IVA-
	• Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA- -NA-	-NA-
8.	Hooters' Location MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System	-1\A-	-1N/A-	-11/7-
10.		N. A.	NT A	NT A
	Basement	-NA-	-NA-	-NA-
	Ground & above Floor Grainly a shore Glassities	Required	Provided	MR
11.	• Sprinkler above false ceiling Internal Hydrants	-NA-	-NA-	-NA-
11.	Size of riser/down-comer	-NA-	-NA-	-NA-
	Number of hydrants per floor	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
12.	Yard Hydrants			1
	Total number of hydrants	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
13.	Pumping Arrangements	1		
	Ground Level			
	Discharge of main Pump	-NA-	-NA-	-NA-
	Head of Main pump	-NA-	-NA-	-NA-
	Number of main pumps	-NA-	-NA-	-NA-
	Jockey Pump out put	-NA-	-NA-	-NA-
	Jockey pump head	-NA-	-NA-	-NA-
	Standby Pump out put	-NA-	-NA-	-NA-
	> Standby Pump Head	-NA-	-NA-	-NA-
	Auto Starting/Manual	-NA-	-NA-	-NA-
	Stopping			
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	Flead of the pump	430 DFM	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	-NA-	Provided	-NA-
14.	Captive Water Storage for fire fighting			Name of the second seco
	Underground tank capacity	-NA-	-NA-	-NA-
	Draw-off connectionFire service inlet	-NA-	-NA-	-NA-
	Access to tank	-NA-	-NA-	-NA-
	Overhead Tank capacity	-NA-	-NA-	-NA-
15.	Exit Signage.	5,000 Lts. Required	Provided Provided	MR MR
		Required	riovided	IVIIV
16.	Provision of Lifts.			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	Pressurization of Lift lobby	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	-NA-
	Fireman's Grounding Switch	-NA-	-NA-	-NA-
	Lift Signage	-NA-	-NA-	-NA-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	1	1	
	> Total Area	-NA-	-ΝΛ-	-NA-
	> Location	-NA-	-NA-	-NA-
19.	Fire Control Room	1111	1 1/1 1/2	11/1
1).	THE COULT OF KOOM			
	Detector System Panel	-NA-	-NA-	-NA-

Diva Restaurant, M-8, Greater Kailash-II, M Block Market, New Delhi-110048 Flow Switch Panel -NA--NA-PA System Panel -NA-Battery backup -NA--NA--NA-**Building Floor Plans** -NA--NA--NA--NA--NA-20. Special Fire Protection System for Protection of special Risks, if any: -NAshortcomings communicated under rule F6/DFS/MS/SZ/2018/2258 dated 23/05/2018 found complied. The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection and it is recommended under rule 37(2) that FSC may be issued under rule 37(3) and accordingly Form "H" is put up in shape of DFA for approval. Signature of Inspecting Officer Name: A. K. Malik Designation: Divisional Officer M-scell FTM-F.T. is pullip In 6's please. 1513/cfosz. m. scell Ve 1876

-NA-