

No. F.6/DFS/MS/EH/SZ/2018/ /774

## FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name & style of Bo-Tai, situated at 6/4, Second Floor, Kalika Das Marg, Near Qutub Minar, Mehrauli, New Delhi Comprises of, Ground & Two Upper floors but the Restaurant is running on 2<sup>nd</sup> floor only was inspected by the officer concerned of this department on 06/06/2018 in the presence of Mr. Varun Duggal and found that the said restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group- D Assembly Building (Eating House)" with effect from 7-/-6-1--2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules. 2010.

Issued on 7/6/2018 at New Delhi by.

Chief Fire Officer Ph: 011-23412225

olc h

## Copy to:-

- 1. The Addl. C. P. (Lic.), 1st Floor, Defence Colony, New Delhi-110024 (Ref. 1537) 39/Addl.CP/Lic./EH/(DA-I)/New Delhi dated 05/04/2018}
- 2. Sh. Varun Duggal, M/s Bo-Tai Restaurant, 6/4, Second Floor, Kalika Das Marg, Near Qutub Minar, Mehrauli, New Delhi.

## Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first 2010. schedule of Delhi Fire Service Rules The form available http://delhi.gov.in/wps/wem/eonnect/doit\_fire/FIRE/Home/Forms
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL) 2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

**INSPECTION REPORT** 1. Name & address of the building: M/s Bo-Tai, 6/4, Second Floor, Kalika Das Marg, Near Qutub Minar, Mehrauli, New Delhi 2. Type of Occupancy : Assembly Building, Group-D, Eating House 3. Type of Case : New case [Building comprised of  $G + 1^{st} + 2^{nd}$  Floor (Restaurant is running at 2<sup>nd</sup> Floor Only)] 4. Fire Safety directives letter No : Approval of FPW at N/3 5. Date of inspection : 06/06/2018 6. Name of Inspecting Officer : A. K. Malik 7. Name and designation of officers from the building side : Mr. Raghuvender Singh (Manager) 8. Year of Construction : Not on file 9. Applicant's letter No. : outdoor diary no. S. No. | Minimum Standards on fire prevention dated 25/05/2018 Directive at Provided at Remarks and fire safety U/R 33 N/3 & 2005 site MR/NMR circular Requirement 1. Access to building Road width Required 6m MR Gate width -NA--NA--NA-Width of internal road -NA--NA-2. Number, Width, Type & Arrangement of Exits -NAa. Number of staircases Upper Floors 2 Nos Provided MR Basements -NA--NAb. Width of staircases -NA-Upper Floor 1.56m & 1.1m 1.56m & 1.01m Basements MR -NAc. Protection of exits -NA--NA-Fire check door -NA--NA-Pressurization -NA--NAd. No. of continuous staircases to terrace -NA--NA--NA--NAe. Width of Corridor -NA--NA--NAf. Door Size -NA-Two Exit 1.2m & 2m MR (2m & 1m)3. Compartmentation Fire check door -NA--NA-Sealing of electrical shafts -NA--NA--NA-Fire Rating of shaft door -NA--NA--NA--NA-Water Curtain -NA--NA--NA-Fire Dampers -NA--NA-4. Smoke Management System -NA-Basements -NA--NA--NA-Upper floors 12 ACPH Provided MR 5. Fire Extinguishers Total numbers 6 No's 7-No's Types MR ABC/ W. CO2/CO<sub>2</sub> 3/3/1 IS marking MR Required **First-Aid Hose Reels** 6. Provided MR Total numbers on each floor One Provided Length of hose reel hose MR 30m Provided Nozzle diameter MR

retomatic tire detection and alarming system ar, Mem dull, New Delhi Type of detectors -NA-Location of Main Panel -NA--NA--NA-Location of Repeater Panel -NA--NA--NA-Alternate source of power -N:A--NA--NA-Hooters' Location -NA--NA--NA-8. MOEFA -NA--NA-9. Required Public Address System Provided MR 10. -NA-Automatic Sprinkler System -NA--NA-Basement -NA-Ground & Upper Floors -NA--NA-Required Sprinkler above false ceiling Provided MR Internal Hydrants 11. -NA--NA--NA-Size of riser/down-comer Required Number of hydrants per floor 100mm MR One Hose Box Provided MR 12. One Yard Hydrants Provided MR Total number of hydrants -NA-Hose Box -NA--NA-13. **Pumping Arrangements** -NA--NA--NA- Ground Level Discharge of main Pump -NA-> Head of Main pump -NA--NA--NA-Number of main pumps -NA--NA--NA-> Jockey Pump out put -NA--NA--NA--NA-Jockey pump head -NA--NA-Standby Pump out put -NA--NA--NA-Standby Pump Head -NA--NA--NA-Auto Starting/Manual Stopping -NA--NA--NA--NA--NA-Terrace level Discharge of pump 450 & 225 LPM Head of the pump Provided MR 40m Power Supply Provided MR Required Auto Starting of pump Provided MR Required 14. Captive Water Storage for fire fighting Provided MR Underground tank capacity Draw-off connection -NA--NA--NA-Fire service inlet -NA--NA--NA- Access to tank -NA--NA--NA-Overhead Tank capacity -NA--NA--NA-15. 5,000 Lts. Exit Signage. Provided MR Required 16. Provision of Lifts. Provided MR Pressurization of Lift Shaft -NA-Pressurization of Lift lobby -NA--NA--NA-Communication In lift Car -NA--NA--NA--NA-Fireman's Grounding Switch -NA--NA--NA-Lift Signage -NA--NA-17. Standby power supply -NA--NA-Required 18. Provided Refuge Area. MR Total Area -NA-Location -NA--NA--NA-19. Fire Control Room -NA--NA-

M/s Bo Tai, 6/4, Second Floor, Kalika Das Marg, Near Qutub Minar, Mehrauli, New Delhi

	<ul><li>Flow Switch Panel</li><li>PA System Panel</li></ul>	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	<ul><li>Battery backup</li><li>Building Floor Plans</li></ul>	-NA-	-NA-	-NA-
	- Dunding 1 1001 1 lans	-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection of special Risks, if any:			-NA-

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection and it is recommended under Rule 35(3) that FSC may be issued under Rule 35(4), accordingly Form "H" is put up in shape of DFA for approval.

Signature of Inspecting Officer

Name: A. K. Malik Designation: DO (SD)

Dy. CFO (SZ)

CFO (Spr)

MSCELL WE Super Super plant

FT letter is put up far super plant

b