

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/DFS/MS/2018/WZ/1088


Dated: 16/5/2018

FIRE SAFETY CERTIFICATE

Certified that **Haldiram Products Pvt. Ltd.** at 5A, 6, 7 of "D" Mall, Sector-10, Rohini, Delhi-110085 comprised of **Ground + Mezzanine Floor only** owned / occupied by **Haldiram Products Pvt. Ltd** was granted NOC by this department vide letter no **F6/DFS/MS/2015/WZ/760 dated 13/05/2015**. The premise was re-inspected by the officers concerned of this department on **13/ 04 / 2018** in presence of **Sh. Ghanshyam Chaudhary (Manager)** and found that the building have deem complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and premises is fit for **Assembly Building Div- D-5** occupancy with effect from 16/5/2018 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of Delhi Fire Service Rules, 2010.

1. Means of escape shall not be kept locked or bolted from outside and shall be easily open able by guests in an event of emergency.
2. All employees shall be acquainted with the use and maintenance of all the fire fighting installation/equipments.
3. The fire suppression / protection arrangements provided in the restaurant are to minimize losses, if maintained in good working condition. These systems cannot give any guarantee that there will be no fire or losses in the event of one.
4. Any loss of life and property due to non-functional of fire safety arrangements and other installations shall be the responsibility of the licensee.
5. This report may not in any way be treated as regularization of unauthorized construction, if any.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [WWW.dfs.Delhigovt.nic.in](http://WWW.dfs.Delhigovt.nic.in)

Issued on 16/5/18 at New Delhi by

  
(Atul Garg)

Chief Fire Officer  
Ph: 011-23414250

Copy to:

1. The Dy Health Officer, North Delhi Municipal Corporation, Health Department, Rohini Zone, Sector-V, Rohini, Delhi-110085 for information.
2. The Authority Signatory Haldiram Products Pvt. Ltd. at 5A, 6, 7 of "D" Mall, Sector-10, Rohini, Delhi-110085

INSPECTION REPORT

Ground + Mezzanine Floor

1. Name & address of the building : Haldiram Products Pvt. Ltd. at 5A, 6, 7 of "D" Mall, Sector -10  
Rohini, Delhi-110085
2. Type of Occupancy : Restaurant Assembly building Sub Div- D-5
3. Type of Case : Renewal
4. Details of previous NOC : F6/DFS/MS/2015/WZ/760 dated 13/05/2015
5. Fire Safety directives letter No : nil
6. Date of inspection : 13/04/2018
7. Name of the Inspecting Officers : ADO (RN)
8. Name and designation of officers  
from the building side : Sh. Ghanshyam Chaudhary (Manager)
9. Year of Construction :
10. Applicant's letter No. : nil dated 22/03/2018

S. No	Minimum Standards on fire prevention and fire safety U/R 33	BBL & NBC Requirement	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	• Road width	12 mtr	Provided	M.R.
	• Gate width	----	No gate provided	----
	• Width of internal road	06 mtr	Provided	M/R
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	02 S/C 02 mtr	1.36 mtr , 02 mtr	M.R.
	• Basements	02 S/C 02 mtr	1.36 mtr , 02 mtr	M.R.
	b. Width of staircases			
	• Upper Floors	02 S/C 02 mtr	1.36 mtr , 02 mtr	M.R.
	• Basements	02 S/C 02 mtr	1.36 mtr , 02 mtr	M.R.
	c. Protection of exits			
	• Fire check door	Required	Provided	M/R
	• Pressurization			
	d. No. of continuous staircases to terrace	Required	Provided	M/R
	e. Width of Corridor	Required	Provided	M/R
	f. Door Size	1.50 mtr 2 mtr	Provided Provided	M/R M/R

✓

N/A

<b>3</b>	<b>Compartmentation.</b>			
	➤ Fire check door	Required	Provided	M/R
	➤ Sealing of electrical shafts	Required	Provided	M/R
	➤ Fire Rating of shaft door	Required	Provided	M/R
	➤ Water Curtain	N.A	N.A	N.A
	➤ Fire Dampers	N.A	N.A	N.A
<b>4</b>	<b>Smoke Management System.</b>			
	➤ Basements	30 a/c per hour	Provided	M.R.
	➤ Upper floors	12 a/c per hour	Provided	M.R.
<b>5</b>	<b>Fire Extinguishers</b>			
	➤ Total numbers	One @ 300 m <sup>2</sup>	5	M.R.
	➤ Types		ABC / CO2	M.R.
	➤ IS marking	ISI marked	yes	M.R.
<b>6</b>	<b>First-Aid Hose Reels.</b>			
	• Total numbers on each floor	one	Provided	M.R.
	• Length of hose reel hose	30mm	(One in common area)	M.R.
	• Nozzle diameter	5mm	Yes	M.R.
<b>7</b>	<b>Automatic fire detection and alarming system.</b>			
	➤ Type of detectors	Required	Provided in restaurant common with Mall	M.R.
	➤ Location of Main Panel	Required	Ground Floor	Already issued NOC of D mall
	➤ Location of Repeater Panel	Required	In side common area on GF	M/R
	➤ Alternate source of power	Required	Provided	M/R
	➤ Hooters' Location	Required	At strategic location	M/R
<b>8</b>	<b>MOEFA</b>	Required	Provided on mez. Floor and common area on GF	M.R
<b>9</b>	<b>Public Address System.</b>	Not Required	Provided	---
<b>10</b>	<b>Automatic Sprinkler System.</b>			
	➤ Basement	N/A	Provided with mall	N/A
	➤ Upper Floor	Required	Provided in restaurant & Mall	M.R
	➤ Sprinkler above false ceiling	Required	Provided on GF + Mez. Floor	M.R
<b>11</b>	<b>Internal Hydrants</b>			
	➤ Size of riser/down-comer	Not Required	Provided with mall	---
	➤ Number of hydrants per floor	Not Required	One in common area	---
	➤ Hose Box	Not Required	One in common area	---

12	<b>Yard Hydrants.</b>			
	➤ Total number of hydrants	Not Required	Two	---
	➤ Hose Box	N/A	yes	---
13	<b>Pumping Arrangements.</b>			
	• Ground Level			
	➤ Discharge of main Pump	4500 LPM	Common with mall	M.R.
	➤ Head of Main pump	70 M	Common with mall	M.R.
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	180 LPM	Common with mall	M.R.
	➤ Jockey pump head	70 M	Common with mall	M.R.
	➤ Standby Pump out put	4500 LPM	Common with mall	M.R.
	➤ Standby Pump Head	70 M	Common with mall	M.R.
	➤ Auto Starting/ Manual stopping	Required	Common with mall	M.R.
	➤ Pump House Access	Required	Common with mall	M.R.
	• Terrace level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14	<b>Captive Water Storage for fire fighting.</b>			
	• Underground tank capacity	1,50,000 ltr	Common with mall	M.R.
	➤ Draw-off connection	Required	Common with mall	M.R.
	➤ Fire service inlet	Required	Common with mall	M.R.
	➤ Access to tank	Required	Common with mall	M.R.
	• Overhead Tank capacity	10,000 ltr	Common with mall	M.R.
15	<b>Exit Signage.</b>	Required	Provided	MR
16	<b>Provision of Lifts.</b>			
	• Pressurization of Lift Shaft	N/A	Provided in mall	N/A
	• Pressurization of Lift lobby	N/A	Provided in mall	N/A
	• Communication In lift Car	N/A	Provided in mall	N/A
	• Fireman's Grounding Switch	N/A	Provided in mall	N/A
	• Lift Signage	N/A	Provided in mall	N/A

2/1/15

17	Standby power supply	Required	Provided in mall	M.R
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	Required	Common with mall	M.R
	• Flow Switch Panel	Required	Common with mall	M.R
	• PA System Panel	Required	Common with mall	M.R
	• Batter backup	Required	Common with mall	M.R
	• Building Floor Plans	Required	Common with mall	M.R
20	Special Fire Protection Systems for Protection of special Risks, if any:		No special risk seen at time of inspection	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2015/WZ/760 dated 13/05/2015 Renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

2/1/15

Signature of the Inspecting Officer

Name: Rajesh Kumar

Designation: Asstt. Divisional Officer

~~By CFO/WS 2~~  
 CFO West  
 2/05/18  
 715718  
 FT DLS

~~Asstt. Div. Officer~~ As approved, G.T. letter is put up for your signature pl.

~~CFO/WS 2~~  
 2/05/18  
 [Signature]

2/1/15