GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2018/W2/2/49

Dated: 19/9 /2018

FIRE SAFETY CERTIFICATE

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**

Issued on ../...... at New Delhi

Chief Fire Officer Ph:-011-23414250

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, G.D. Goenka Public School, (formerly known as Rose Wood Public School & Kings Valley School), Pkt-04, Sector-9, Rohini, Delhi-110085.

INSPECTION REPORT

1. Name & address of the building :G.D. Goenka Public School, (formerly known as Rose Wood Public School

&Kings Valley School), Pkt-04, Sector-9, Rohini, Delhi-110085.

2. Type of Occupancy

:Educational

3. Type of Case

:Renewal (Ground+03Upper Floor)

4. Details of previous NOC

:F-6/DFS/MS/School/2015/WZ/1425 dated 06.08.2015

5. Fire Safety directives letter No

: NBC Part-4

6. Date of inspection

: 31/08/2018

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Mrs. Anita Rana, Manager

9. Year of Construction

: 2005-2009

10. Applicant's letter No.

: GDGPS/2018/0181 dated 06/08/2018

	Minimum Standards on fire prevention and fire safety U/R 33	Director of Education letter dated 17.01.2005	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	6m	6 m	MR		
	Gate width	5m	5 m	MR		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits	its				
	a. Number of staircases					
	Upper Floors	02	02	MR		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper Floors	1.50m	1.42m &1.43m	MR(old case)		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
		NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	1 m	1.0m with door frame	MR(old case)		
	f. Door Size	3	- ,			
	Compartmentation.					
	Fire check door	NA	NA	NA		

	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft doorWater Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
1		NA	NA	NA		
+	Smoke Management System.					
	• Basements	30 a/c per hour	NA	NA		
	Upper floors	12 a/c per hour	Natural Ventilated	MR		
;	Fire Extinguishers					
	Total numbers	16 nos	20nos	MR		
	Types	ABC/Co2	ABC-20	MR		
	ISI marking	ISI Marked	Yes	MR		
	First-Aid Hose Reels.					
	Total numbers on each floor	02	02	MR		
	 Length of hose reel hose 	30m	30m	MR		
	Nozzle diameter	5mm	5mm			
	Automatic fire detection and alarming system. 5mm 5mm MR					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
	MOEFA	NA	NA	NA		
	Public Address System.	Required	Provided	MR		
	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
	Upper Floor	NA	NA NA	NA NA		
	Sprinkler above false ceiling	NA	NA	NA		
	Internal Hydrants					
	Size of riser/down-comer	100mm	Provided	MR		
	 Number of hydrants per floor 	Required	Provided			
	Hose Box	Required	Provided	MR		
	Yard Hydrants.	required	riovided	MR		
	Total number of hydrantsHose Box	NA	NA	NA		
	- HUSE BOX	NA	NA	NA		

	Ground Level	-		a _		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps					
	> Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	225lpm	2251pm	MR		
	> Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level	4501 8 220 lane	Provided	MR		
	Discharge of pump	450lpm& 220 lpm		MR		
	➤ Head of the pump	40m Required	40m Provided	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump					
	Captive Water Storage for fire fighting					
	Underground tank capacity	NA	Provided	NA		
	> Draw-off connection	NA	NA	NA		
	> Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	10,000 ltrs	10,000ltrs	MR		
-	Exit Signage.	Required	Provided	MR		
Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage					
		N/A	N/A	N/A		
	Standby power supply	N/A	N/A	N/A		
	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		

1

	 Detector System Panel 	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	• N/A .
	PA System Panel	N/A	N/A	N/A
	Batter backupBuilding Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular / NBC Part 4, the FSC issued vide letter of even no 1425 dated 06.08.2015 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer

Name:- Rajesh Kumar Designation:- ADO/RN

cto west

OUKN

As approved, F.f. fetter for your signalizer Pl

re in puling

14

C6142/A/10