GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2018/SZ/ 2-360

Dated: 1.7./1.0./18

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s **Kylin** (A Unit of First May Enterprises) situated in commercial area at Ground floor, Worldmark-2, Asset-8, Hospitality District, Aerocity, IGI Airport, New Delhi-110037, comprised of 03 tier Basement, Ground + 06 upper floors. The restaurant running at ground floor of the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 06/10/2018 in the presence of Mr. Ashwin Kumar (Manager) and that the premises is fit for occupancy class 'Assembly' Group-D (Restaurant) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/10/13 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. DHO, South MCD, Public Health Department, Najafgarh Zone, Dhansa Stand, Najafgarh, New Delhi-110043
- 2. Auth. Signatory, M/s Kylin (A U/o First May Enterprises), Ground Floor, Worldmark-2, Asset-8, Hospitality District, Aerocity, IGI Airport, New Delhi-110037

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

1	INSPECTIO	M/c VVI IN at Gro	aund floor Worldmark-2	Asset-8.		
1	Name & Address of the Building	M/s KYLIN at Ground floor, Worldmark-2, Asset-8, Hospitality Distt., Aerocity, IGI Airport, New Delhi. (A Unit of First May Enterprises)				
2	Type of Occupancy	Assembly 'Group	-D' (Eating House)			
3	Type of Occupancy Building comprised of	03 Basements, Mezzanine, Ground + 6 upper floors.				
4	Type of Case	New				
5	Details of Previous NOC	F.6/DFS/MS/Mixed/SZ/2018/209 Dt. 17-02-2018 (Bldg)				
6	Fire Safety Directives Letter No	F6/MS/DFS/BP/2011/152 dated 25/01/2011 (Bldg)				
7	Date of Inspection	06-10-2018				
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)				
9	Name & Designation of Officers					
,	from the building side	× ,				
10	Year of construction	2014 Eating House located at GF of the building				
11	Applicant letter No.	Outdoor Diary No. 12219 dated 28-08-2018				
S. No.	Minimum standards on Fire Prevention	UBBL/NBC-	Provided at Site	Remarks		
	and Fire Safety U/R 33	2016		MR/NMR		
		Requirement	0.34 1 1 1 1 1 1 1	1		
1	Access to Building.		& Maintained by Bldg N			
	Road width	Restt within	As above	MR		
	Gate width	Worldmark-2	As above	N/A		
	Width of internal road	Aerocity	As above	N/A		
2	Number, width, type & arrangement of exits					
	a. Number of Staircase		& Maintained by Bldg I	vigmt.		
	Upper floors	N/A	As above	N/A		
	Basement floor	N/A	As above	N/A		
	b. Width of Staircase	Provided	& Maintained by Bldg I			
	Upper floors	N/A	As above	N/A		
	Basement floor	N/A	As above	N/A		
	c. Protection of exits	Provided & Maintained by Bldg Mgmt.				
	Fire check door	N/A	As above	N/A		
	Pressurization	N/A	As above	N/A		
	d. No. of continuous staircase to terrace	Required	As above	MR		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	2m/1.35ms	2.4m, 2m & 1.5m	MR		
3	Compartmentation.		& Maintained by Bldg	Mgmt.		
	Fire check door.	N/A	As above	N/A		
	 Sealing of electrical shafts. 	N/A	As above	N/A		
	• Fire rating of shaft door.	N/A	As above	N/A		
	Water curtain	N/A	As above	N/A		
	• Fire dampers.	N/A	As above	N/A		
4.	Smoke Management system.	Provided & Maintained by Bldg Mgmt.				
	Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	Exhaust fans Provided	l MR		
5.	Fire Extinguishers.					
	Total numbers	06 Nos	Provided	MR		
	• Types	ABC / CO2	ABC & Co2	MR		
	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.	Control of the Contro	d & Maintained by Bldg	Mgmt.		
	Total numbers on each floor.	One	As above	MR		
	 Length of hose-reel hose. 	30m	As above	MR		
		5mm	As above	MR		
	Nozzle Diameter	Hospitality Distt., A	As above	TATIZ		

M/s KYLIN at Gd. floor, Worldmark-2, Asset-8, Hospitality Distt., Aerocity, IGI Airport, New Delhi

7 Autor	natic fire detection & alarming system.	Provided	& Maintained by Bldg	Mgmt.
•	Type of detectors	N/A	As above	N/A
	Location of Main Panel	N/A	As above	N/A
•	Location of Repeater Panel	N/A	As above	N/A
	Alternate source of power	N/A	As above	N/A
	Hooter's location	N/A	As above	N/A
8. MOI		Required	As above	MR
	ic Address System	N/A	As above	N/A
	matic Sprinkler System	Provided & Maintained by Bldg Mgmt.		
•	D. C.	N/A	As above	N/A
•	Upper floors	N/A	As above	N/A
•		N/A	As above	N/A
11. Inter	nal Hydrants.	Provided	& Maintained by Bldg	Mgmt.
•	Size of Riser/Down-comer	N/A	As above	N/A
•	Number of Hydrant per floor	N/A	As above	N/A
•	Hose box.	N/A	As above	N/A
12. Yard	l Hydrants.	Provided	& Maintained by Bldg	Mgmt.
•	Total number of hydrants.	N/A	As above	N/A
		N/A	As above	N/A
13. Pum	ping arrangements.			
	Ground Level	l Level Provided & Maintained by Bldg Mgmt.		
	Discharge of main pump.	N/A	2280 LPM	N/A
	Head of main pump.	N/A	105m	N/A
	Number of main pumps.	N/A	Two	N/A
	Jockey Pump output.	N/A	2 x 180 LPM	N/A
	Jockey Pump head.	N/A	105m	N/A
	Standby Pump output.	N/A	2280 LPM	N/A
	Standby Pump head.	N/A	105m	N/A
	Auto Starting/Manual Stopping.	N/A	Provided	N/A
	Pump House Access	N/A	Provided	N/A
• 7	Гerrace Level		& Maintained by Bldg	1
	Discharge of pump.	450 LPM	As above	MR
	Head of pump.	40 mtr	As above	MR
	Power supply.	Required	As above	MR
	Auto starting of pump.	Required	As above	MR
	tive water storage for Fire Fighting.		l & Maintained by Bldg	
• 1	Underground tank capacity.	N/A	1,00,000 Ltr	N/A
	> Draw-off connection.	N/A	As above	N/A
	Fire Service Inlet.	N/A	As above	; N/A
	Access to tank.	N/A	As above	N/A MR
	Overhead tank capacity.	10,000 Ltr Required	20,000 Ltr Provided	MR
	Signage. vision of Lifts.		1 & Maintained by Bldg	
10. Pro	• Pressurization of lift shaft.	N/A	As above	N/A
	5 1 1 2112 1 1 1	N/A N/A	As above As above	N/A
	6 1 1 1 110	N/A N/A	As above As above	N/A
		N/A	As above As above	N/A
		N/A	As above As above	N/A
and the same of th	Lift signage. adhy Power Supply		Provided	MR
	ndby Power Supply	Required		
18. Ref	uge Area	N/A	d & Maintained by Bldg N/A	N/A
	Total area		100 600 H2400	
	Location KVLIN at Gd. floor, Worldmark 2, Assat 8.	N/A	N/A	N/A

M/s KYLIN at Gd. floor, Worldmark-2, Asset-8, Hospitality Distt., Aerocity, IGI Airport, New Delhi

19.	Fire Control Room.	rol Room. Provided & Maintained by B		
	Detector System Panel.	N/A	As above	N/A
	• Flow Switch Panel.	N/A	As above	N/A
	PA system Panel.	N/A	As above	N/A
	Battery backup	N/A	As above	N/A
	Building floor plan	N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any:			

Total Covered Area = 227.64m² ÷ 1.5 = 151.76 pm

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection. Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting

Name: Mehmood Design: ADO (SJ)

M/s KYLIN at Gd. floor, Worldmark-2, Asset-8, Hospitality Distt., Aerocity, IGI Airport, New Delhi

A F.-7. Seller Pinning for
CROCET?