GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 2732

Dated: 19/12/18

FIRE SAFETY CERTIFICATE

Issued -- 19 112 -- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

@ c Man

Copy to:-

1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.

 The Manager, Makki Guest House at 3981-3982, Gali Khan Khana, Urdu Bazar, Jama Masjid, Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

	INSP	ECTION REPO	RT	*		
1.	Name & address of the building		st House at 3981-398	2, Gali Khan		
1.	Traine de didition of the order-8		ı Bazar, Jama Masjid			
2.	Type of occupancy:-		Sub Division-A-1			
	-31	Ground + 02 i	upper floor, total 17 gu	iest rooms		
		Ground floor	(reception + 04 guest re	ooms), 1 st floor		
	(07 guest rooms), 2 nd floor (06 guest rooms) floor (staff rooms)					
2	Type of case:-	Renewal	oms)			
	V 1	7/576 dated				
4.	Details of previous FSC:- No. F6/DFS/MS/GH/2015/NDZ/576 dated 21/04/15.					
5.	Fire safety directives No	N/A				
	Date of inspection:-	02/12/18				
	Name of the inspecting officer:	- Sh. Manoj	Kumar Sharma (AI	OO/CC)		
	Name & designation of officer					
	From the building side:-	Mr. Md. Sa	aud Alam			
9.	Year of construction:-	Old				
10	. Applicant's letter No:-	Nil dated 16/	/11/2018.			
S.No.	Minimum Standards on fire	Requirement/	Provided at site	Remarks		
	Prevention and fire safety	Existing fire safety		MR/NMR		
	U/R 33	arrangements				
1.	Access to Building	warmage				
	1) Road width	N/A	1.5 to 3.0 mtr.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arra					
	A. Number of staircases			9		
	1. Upper floors	01 Nos.	01 Nos.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	0.80 mtr.	0.80 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits		8			
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01 Nos.	01 Nos.	MR		
	staircase to terrace		i i			
	E. Width of corridor	N/A	N/A	N/A		
,	F. Door size	0.80 mtr.	0.86 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
rige	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural	MR		
	,		81	* *		
5.	Fire Extinguishers					
٥.	The Extinguishers					

5.	Fire Extinguishers			
J.	1) Total numbers	12 Nos.	12 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	required	TTOVIGEG	IVIIC
0.	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	TVIIC		
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	required	Tiovided	IVIK
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	T 4/ T F	14/11	IVA
11.	Internal Hydrants			District Control of the Control of t
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	1771	1071	14/71
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	1771		
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement		11/11	1771
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump		A 1/4 h	11/11
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
		Required	Provided	MR
	c) Power supply d) Auto starting of pump	Required Required	Provided Provided	MR MR

m

14.	Captive Water Storage for	r Fire Fightin		
	capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	DI/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A N/A
15.	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
16.	Exit Signage.	Required	Provided	
10.	Provision of Lifts.	- required	Frovided	MR
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switche) Lift signage	N/A	N/A	N/A
17.	Stand by Power S	N/A	N/A	N/A
18.	Stand by Power Supply Refuge Area	Required	Provided	MR
		N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
9.	Fire Control Room a) Detector system	N/A	N/A	N/A
	panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	77/4
	c) PA system panel	N/A	N/A	N/A
		N/A	N/A	N/A N/A
	e) Building floor plan	N/A	N/A	N/A
).	Special Fire Protection System Risk, if any:	for Protection	on of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/576 dated 21/04/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Dy. CFONDZ

F.A. M. SCELL Fth.

F.F. Letter is part