

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2019/SZ/ 1702

Dated: 28/8 /2019

FIRE SAFETY CERTIFICATE

Certified that M/s **SETZ Restaurant** (A unit of DLF Emporio Restaurants Ltd) located at Shop No-405, DLF Emporio Shopping Mall, Plot No-4, Nelson Mandela Marg, Vasant Kunj, New Delhi, comprised of three basements, ground, upper ground plus two upper floors. The restaurant running at 2nd floor of the building has already been issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2016/SZ/1128 dated 08/07/2016. The premise was re-inspected by the officer concerned of this department on 26/07/2019 in the presence of Mr. Anupam Sharma of the restaurant and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that premises is fit for occupancy class "**Assembly, Group-D**" (Restaurant) with effect from 28/8 /2019 for period of **Three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued 28 / 8 /2019 at New Delhi by


(Atul Garg)
Chief Fire Officer
Tel. 011-23414250


Copy to: -

1. The Director M/s DLF Emporio Restaurants Ltd, DLF Emporio, Plot No-4, Vasant Kunj Malls, Nelson Mandela Road, Vasant Kunj Phase-II, New Delhi-110070
2. The DHO, South MCD, Health Department, South Zone, Green Park, New Delhi-110016

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non- functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL- 2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

INSPECTION REPORT

1	Name & Address of the Building	M/s Setz Restaurant (U/o DLF Emporio Restaurants Ltd), Shop No. 405, 2 nd Floor, DLF Emporio Mall, Plot No-4, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly, 'Group D' (Restaurant at 2nd Floor)		
3	Building Comprised of	Three Basements, Ground, Upper Ground + 02 UFs		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/2016/SZ/1128 Dated 08-07-2016		
6	Fire Safety Directives Letter No	F6/MS/DFS/BP/2005/831 dated 20-04-2005 (Bldg.)		
7	Date of Inspection	26-07-2019		
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)		
9	Name & Designation of Officers from the building side	Mr. Anupam Sharma		
10	Year of construction	2007		
11	Applicant letter No.	Outdoor Diary No. 14230 dated 27-06-2019		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.	F.6/DFS/MS/Mall/SZ/2017/1305 Dtd 29-08-17 (Bldg.)		
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	Restt within DLF Emporio Mall	As above As above As above	MR N/A N/A
2	Number, width, type & arrangement of exits.	Provided & Maintained by DLF Emporio Mall		
	a) Number of Staircase	2 Nos		
	➤ Upper floors.	N/A	As above	MR
	➤ Basement floor.	N/A	As above	N/A
	b) Width of Staircase	1.5 mtr		
	➤ Upper floors	N/A	As above	MR
	➤ Basement floor	N/A	As above	N/A
	c) Protection of exits	Required		
	➤ Fire check door	Required	As above	MR
	➤ Pressurization	Required	As above	MR
	d) No. of continuous staircase to terrace	Required	As above	MR
	e) Width of corridor	1.5m	As above	MR
	f) Door size	2m	2m x 2 nos.	MR
3	Compartmentation.	Provided & Maintained by DLF Emporio Mall		
	• Fire check door.	Required	As above	MR
	• Sealing of electrical shafts.	Required	As above	MR
	• Fire rating of shaft door.	Required	As above	MR
	• Water curtain	N/A	As above	N/A
	• Fire dampers.	N/A	As above	N/A
4	Smoke Management system.	Provided & Maintained by DLF Emporio Mall		
	• Basement	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Exhaust fan provided	MR
5	Fire Extinguishers.	Provided & Maintained by DLF Emporio Mall		
	• Total numbers	Portable fire extinguishers	10 Nos	MR
	• Types	ISI marked	ABC & CO ₂	MR
	• ISI Marking	ISI marked	Provided	MR
6	First Aid Hose Reels.	Provided & Maintained by DLF Emporio Mall		
	• Total numbers on each floor.	Hose Reels	2 Nos Near Restt	MR
	• Length of hose-reel hose.		30m	MR
	• Nozzle Diameter		5mm	MR
7	Automatic fire detection & alarming system.	Provided & Maintained by DLF Emporio Mall		
	• Type of detectors	Required	As above	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	Required	As above	MR
	• Alternate source of power	Required	As above	MR
	• Hooter's location	Required	As above	MR

8	MOEFA	Required	Provided	MR
9	Public Address System	Provided & Maintained by DLF Emporio Mall		
10	Automatic Sprinkler System	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> Basement 	N/A	As above	N/A
	<ul style="list-style-type: none"> Restaurant Area 	Required	As above	MR
	<ul style="list-style-type: none"> Sprinkler above false ceiling 	N/A	As above	N/A
11	Internal Hydrants.	Provided & Maintained by Hotel Management		
	<ul style="list-style-type: none"> Size of Riser/Down-comer 	Required	As above	MR
	<ul style="list-style-type: none"> Number of Hydrant per floor 	Required	As above	MR
	<ul style="list-style-type: none"> Hose box. 	Required	As above	MR
12	Yard Hydrants.	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> Total number of hydrants. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Hose box. 	N/A	As above	N/A
13	Pumping arrangements.			
	<ul style="list-style-type: none"> Ground Level 	Fire fighting arrangements are common for entire bldg.		
	<ul style="list-style-type: none"> ➤ Discharge of main pump. 	N/A	4550 LPM	N/A
	<ul style="list-style-type: none"> ➤ Head of main pump. 	N/A	40m	N/A
	<ul style="list-style-type: none"> ➤ Number of main pumps. 	N/A	02 Nos	N/A
	<ul style="list-style-type: none"> ➤ Jockey Pump output. 	N/A	180 LPM	N/A
	<ul style="list-style-type: none"> ➤ Jockey Pump head. 	N/A	40m	N/A
	<ul style="list-style-type: none"> ➤ Standby Pump output. 	N/A	4550 LPM	N/A
	<ul style="list-style-type: none"> ➤ Standby Pump head. 	N/A	40m	N/A
	<ul style="list-style-type: none"> ➤ Auto Starting/Manual Stopping. 	N/A	Provided	N/A
	<ul style="list-style-type: none"> ➤ Pump house access. 	N/A	Provided	N/A
	<ul style="list-style-type: none"> Terrace Level 	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> ➤ Discharge of pump. 	450 LPM	As above	MR
	<ul style="list-style-type: none"> ➤ Head of pump. 	40m	As above	MR
	<ul style="list-style-type: none"> ➤ Power supply. 	Required	As above	MR
	<ul style="list-style-type: none"> ➤ Auto starting of pump. 	Required	As above	MR
14	Captive water storage for fire fighting.	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> Underground tank capacity. 	N/A	5,00,000 Lts	N/A
	<ul style="list-style-type: none"> ➤ Draw-off connection. 	N/A	Provided	N/A
	<ul style="list-style-type: none"> ➤ Fire Service Inlet. 	Required	Provided	MR
	<ul style="list-style-type: none"> ➤ Access to tank. 	N/A	Provided	N/A
	<ul style="list-style-type: none"> Overhead tank capacity. 	10,000 Lts	50,000 Lts	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> Pressurization of lift shaft. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Pressurization of lift lobby. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Communication in lift car. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Fireman's switch. 	N/A	As above	N/A
	<ul style="list-style-type: none"> Lift signage. 	N/A	As above	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	<ul style="list-style-type: none"> Total area 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Location 	N/A	N/A	N/A
19	Fire Control Room.	Provided & Maintained by DLF Emporio Mall		
	<ul style="list-style-type: none"> Detector system panel. 	Required	As above	MR
	<ul style="list-style-type: none"> Flow switch panel. 	Required	As above	MR
	<ul style="list-style-type: none"> PA system panel. 	Required	As above	MR
	<ul style="list-style-type: none"> Battery backup. 	Required	As above	MR
	<ul style="list-style-type: none"> Building floor plan. 	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of Special Risk, if any.	Provided & Maintained by DLF Emporio Mall		N/A

N/-14

M/s SETZ Restaurant, Shop No-405, 2nd Floor, DLF Emporio Mall, Plot No-4, Vasant Kunj, New Delhi.

The Fire protection systems provided in the building/ premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2016/SZ/1128 dated 08/07/2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Mehmo
29/3/19

Signature of the Inspecting Officer
Name: Mehmoood
Design: ADO (SJ)

DO (SD)

*All speak about the requirement of FPF
AS measures applicable on Restaurant.*

Quilash
31/3/19

ADO
SJ

*Sr. Spoken and Awarded Inspection in the
hotel requirements of F.P. & G. measures
on Restaurant is submitted for approval please
Re-submitted plan*

Sharma
29/3/19
ADO (SO)

DO (SO)

Quilash
21/8/19

dy. cfo (SO) *W*
2/8

ADO
23/8/19

