GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2019/SZ / 2/64

Dated: 15/11/19

FIRE SAFETY CERTIFICATE

Certified that the **Satyam Public School**, 129, Bhagwati Garden Extn., Near Kakrola Mode, Uttam Nagar, New Delhi-110059, comprised of ground floor plus three upper floors, owned/occupied by Satyam Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2014/SZ/522 dated 28.04.2014. The School building was re-inspected by the officer concerned of this department on 01.11.2019 in the presence of Smt. Anita Khatri (H.O.S) and found that Satyam Public School have deemed with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (for GF+FF+SF whereas Third floor is used for residential) is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(RAJESH PANWAR) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Manager, Satyam Public School, 129, Bhagwati Garden Extn., Near Kakrola Mode, Uttam Nagar, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
- 9. This FSC is not valid for third floor being used as residential.

INSPECTION REPORT Satyam Public School, 129, Bhagwati Garden Extn., Near Kakrola 1. Name & address of the building: Mode, Uttam Nagar, New Delhi-110059 Educational Type of Occupancy Renewal 3. Type of Case F.6/DFS/MS/School/2014/SZ/522 dated 28.04.2014 4. Details of Previous NOC N/A 5. Fire Safety directives letter No : 19.09.2019 6. Date of inspection A.D.O. Sandeep Duggal Name of Inspecting Officer Name and designation of officers Sh. Amit (Caretaker) From the building side 2002 (GF, FF & SF) & 2013 (Third floor) 9. Year of Construction : Nil dated 30.07.2019 10. Applicant's letter No. Remarks Provided at site Minimum Standards on fire prevention and **NBC** S. No. MR/NMR Requirements fire safety U/R 33 Access to building 1. M/R Accessible 06 mtrs Provided Road width MR Directly accessible 4.5 mtrs Gate width from road N/A N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases M/R Two Two Upper Floors N/A N/A N/A **Basements** b. Width of staircases M/R 140 cms & 100 cms 150 cms/additional Upper Floor staircase of 75 cms if less than 150 cms **Basements** N/A N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to M/R Provided Required terrace M/R e. Width of Corridor 250 cms 150 cms. M/R being old case 90 cms 100 cms in f. Door Size Class rooms Compartmentation 3. N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A **Basements** M/R Natural ventilation Required Upper floors provided Fire Extinguishers 5. M/R Provided 02 no's Total numbers on each floor M/R ABC/CO2 type Provided **Types** ISI marked M/R Provided IS marking First-Aid Hose Reels 6. M/R Provided One Total numbers on each floor 30 mtrs M/R Length of hose reel hose Provided 5 mm Nozzle diameter M/R Provided

| 7. | Automatic fire detection and alarming system | 1 | | |
|-----|--|-----------------|----------|--|
| | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| 8. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | | | |
| | Basement | N/A | N/A | N/A |
| | Ground Floor | N/A | N/A | N/A |
| 11. | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants | | | |
| | Size of riser/down-comer | N/A | N/A | N/A |
| | Number of hydrants per floor | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 12. | Yard Hydrants | | | |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 13. | Pumping Arrangements | | | |
| | Ground Level | | | |
| | Discharge of main Pump | N/A | N/A | N/A |
| | Head of Main pump | N/A | N/A | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | Jockey Pump out putJockey pump head | N/A | N/A | |
| | Standby Pump out put | 1000, 1000, 100 | | N/A |
| | Standby Pump Head | N/A | N/A | N/A |
| | ➤ Auto Starting/Manual Stopping | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Pump House Access | N/A | N/A | N/A |
| | • Terrace level | | | and the state of t |
| | Discharge of pumpHead of the pump | 450 LPM | Provided | M/R |
| | Power Supply | 30 mtrs | Provided | M/R |
| | > Auto Starting of pump | Required | Provided | M/R |
| 4.4 | | Required | Provided | M/R |
| 14. | Captive Water Storage for fire fighting | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | Draw-off connectionFire service inlet | N/A | N/A | N/A |
| | Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | N/A | N/A | N/A |
| | | 10000 ltrs | Provided | M/R |
| 15. | Exit Signage. | Required | Provided | M/R |
| 16. | Provision of Lifts. | | | No Lift |
| | Pressurization of Lift Shaft | N/A | N/A | N/A |
| | Pressurization of Lift lobby | N/A | N/A | N/A |
| | Communication In lift Car | N/A | N/A | N/A |
| | Fireman's Grounding Switch Lift Signage | N/A | N/A | N/A |
| | Lift Signage | N/A | N/A | N/A |
| 17. | Standby power supply | N/A | N/A | N/A |
| 10 | Pofugo A vog | | | |
| 18. | Refuge Area. > Total Area | N/A | N/A | N/A |
| | > Location | | | |
| | | N/A | N/A | N/A |

| Fire Control Room | | | | |
|---|--|-----------------------|---|--|
| Detector System Panel Flow Switch Panel PA System Panel | N/A | N/A | N/A | |
| | N/A | N/A | N/A | |
| | N/A | N/A | N/A | |
| | N/A | N/A | N/A | |
| Building Floor Plans | N/A | N/A | N/A | |
| Special Fire Protection System for Protection | N/A | N/A | N/A | |
| | Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection | Detector System Panel | • Detector System Panel N/A N/A • Flow Switch Panel N/A N/A • PA System Panel N/A N/A • Battery backup N/A N/A • Building Floor Plans N/A N/A | |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/School/2018/SZ/2134 dated 18.05.18 have been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/School/2014/SZ/522 dated 28.04.2014 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Please reconfin the
Width of Stourcore as in
width of Stourcore or 1950 the
prot only sain care of 1950 the
food my reported and
food my reported addition
Also state whether any addition
alternate has been dear or
alternate width has increased
width has increased

175 to 140 cm

517