

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Audi/2020/SZ/ 263

Dated: 17/07/2020

FIRE SAFETY CERTIFICATE

Certified that the **Auditorium Building at India Islamic Cultural Centre** at 87-88, Lodhi Marg, New Delhi-110003, comprised of lower ground, ground plus one floor but Auditorium at first floor only, owned/occupied by India Islamic Cultural Centre was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2017/SZ/365 dated 14/03/2017. The said premise was re-inspected by the officer concerned of this department on 02/07/2020 in presence of Mr. Mohd. Nausherawan, Manager and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class **Group "D" Assembly** (Auditorium) as above with effect from 17/07/2020 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 as below.

Issued on 17/07 /2020 at New Delhi by


(Sunil Choudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:

1. Sh. Mohd. Nausherawan, (Manager-Admn), India Islamic Cultural Centre, Lodhi Estate, New Delhi-110003
2. The Addl. Commissioner of Police (Lic.), 1st Floor, PS Defence Colony, New Delhi- 49

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non- functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of DFS Rules, 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of
6. UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT

1	Name & Address of the Building	M/s Auditorium Building at India Islamic Cultural Centre, 87-88, Lodhi Road, New Delhi-110003		
2	Type of Occupancy	Group "D" Assembly Building		
3	Building Comprised of	Lower ground, ground + one upper floor (Auditorium at first floor only having 300 seats)		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/2017/SZ/365 dated 14-03-2017		
6	Fire Safety Directives Letter No	F6/DFS/MS/95/4336 dated 10-04-1995		
7	Date of Inspection	02-07-2020		
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)		
9	Name & Designation of Officers from the building side	Mohd. Nausherawan (Manager)		
10	Year of construction	2006		
11	Applicant letter No.	Outdoor Diary No. 5830 dated 15-06-2020		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	9m	20m	MR
	• Gate width	5m	5m	MR
	• Width of internal road	-NA-	-NA-	-NA-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	05 Nos	05 Nos	MR
	➤ Basement floor.	-NA-	-NA-	-NA-
	b) Width of Staircase			
	➤ Upper floors	Required	3nos=1.5m, 1no=2m & 1no=1.25m	MR (old case)
	➤ Basement floor	-NA-	-NA-	-NA-
	c) Protection of exits			
	➤ Fire check door	-NA-	-NA-	-NA-
	➤ Pressurization	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	One	One	MR
	e) Width of corridor	-NA-	-NA-	-NA-
	f) Door size	Required	03 Entry/Exits 2nos=1.5m & 1no=0.96m	MR (old case)
3	Compartmentation.			
	• Fire check door.	-NA-	-NA-	-NA-
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	-NA-	-NA-	-NA-
	• Water curtain	-NA-	-NA-	-NA-
	• Fire dampers.	-NA-	-NA-	-NA-
4.	Smoke Management system.			
	• Basement	30 ACPH	-NA-	-NA-
	• Upper floors / Auditorium	12 ACPH	Exhaust fan provided	MR
5.	Fire Extinguishers.			
	• Total numbers	06 Nos	10 Nos	MR
	• Types	ABC/W.CO ₂ /CO ₂	ABC, W.CO ₂ & CO ₂	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.	Fire fighting system is common for entire building		
	• Total numbers on each floor.	2nos near Audi	4nos near Audi	MR
	• Length of hose-reel hose.	30m	30m	MR
	• Nozzle Diameter	5mm	5mm	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	Smoke	Smoke	MR
	• Location of Main Panel	Ground floor	Ground floor	MR
	• Location of Repeater Panel	-NA-	-NA-	-NA-
	• Alternate source of power	Required	Battery backup	MR
	• Hooter's location	All Floors	All Floors	MR

8.	MOEFA	Required	Provided		MR
9.	Public Address System	Required	Provided		MR
10.	Automatic Sprinkler System				
	• Basement	-NA-	-NA-		-NA-
	• Upper floors/Auditorium	Required	Provided		MR
	• Sprinkler above false ceiling	-NA-	-NA-		-NA-
11.	Internal Hydrants.	Fire fighting system is common for entire building			
	• Size of Riser/Down-comer	100mm	100mm		MR
	• Number of Hydrant per floor	01no near Audi	01no near Audi		MR (old case)
	• Hose box.	01no near Audi	4nos near Audi		MR
12.	Yard Hydrants.				
	• Total number of hydrants.	-NA-	-NA-		-NA-
	• Hose box.	-NA-	-NA-		-NA-
13.	Pumping arrangements.				
	• Ground Level	Fire fighting system is common for entire complex			
	➤ Discharge of main pump.	2800 LPM	2800 LPM		MR
	➤ Head of main pump.	70m	70m		MR
	➤ Number of main pumps.	01 No	01 No		MR
	➤ Jockey Pump output.	180 LPM	180 LPM		MR
	➤ Jockey Pump head.	70m	70m		MR
	➤ Standby Pump output.	2800 LPM	2800 LPM		MR
	➤ Standby Pump head.	70m	70m		MR
	➤ Auto Starting / Manual Stopping.	Required	Provided		MR
	➤ Pump house access.	Required	Provided		MR
	• Terrace Level				
	➤ Discharge of pump.	-NA-	-NA-		-NA-
	➤ Head of pump.	-NA-	-NA-		-NA-
	➤ Power supply.	-NA-	-NA-		-NA-
	➤ Auto starting of pump.	-NA-	-NA-		-NA-
14.	Captive water storage for fire fighting.	Fire fighting system is common for entire complex			
	• Underground tank capacity.	100,000 Ltr	100,000 Ltr		MR
	➤ Draw-off connection.	Required	Required		MR
	➤ Fire Service Inlet.	Required	Required		MR
	➤ Access to tank.	Required	Required		MR
	• Overhead tank capacity.	30,000 Ltr	30,000 Ltr		MR
15.	Exit Signage.	Required	Provided		MR
16.	Provision of Lifts.				
	• Pressurization of lift shaft.	-NA-	-NA-		-NA-
	• Pressurization of lift lobby.	-NA-	-NA-		-NA-
	• Communication in lift car.	-NA-	-NA-		-NA-
	• Fireman's switch.	-NA-	-NA-		-NA-
	• Lift signage.	-NA-	-NA-		-NA-
17.	Standby Power Supply	Required	Provided		MR
18.	Refuge Area				
	• Total area	-NA-	-NA-		-NA-
	• Location	-NA-	-NA-		-NA-
19.	Fire Control Room.	Fire fighting system is common for entire complex			
	• Detector system panel.	Required	Provided		MR
	• Flow switch panel.	-NA-	-NA-		-NA-
	• PA system panel.	Required	Provided		MR
	• Battery backup.	Required	Provided		MR
	• Building floor plan.	-NA-	-NA-		-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	ABC & CO ₂ fire extinguishers provided for electric panel			MR

24/44

M/s Auditorium at India Islamic Cultural Centre, 87-88, Lodhi Road, New Delhi-110003

The fire protection systems provided in the building/premises were test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/2017/SZ/365 dated 14/03/2017, renewal under Rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Hammed
21/7/2020

Signature of the Inspecting Officer

Name: Mehmood

Design: ADO (SJ)

DO (SD)

Pl. spe about point No. 13.

ling
08/07

ADO(SJ)

Sw a typing error found in para 13
a new inspection etc put up for
signature please

Re-Inspected
Hammed
21/7/2020

ADO(SJ)

ling
10/07 F.T. please

DeFO(SJ)
17/7

Ad(SJ)

Sw of A.T. letter put up for signature please
Hammed
21/7/2020