FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI**

No. F6/DFS/MS/WZ/2020/ EH /119

Dated: (0/08/2020

FIRE SAFETY CERTIFICATE

Certified that the McDonalds Family Restaurant Located at Ground & First Floor, M2K Multiplex, New Delhi 110034 Pitampura, was issued FSC vide F6/DFS/MS/EH/2016/WZ/319 dated 29-02-2016. M2k Multiplex, Pitampura has already issued FSC vide letter no. F6/DFS/MS/2020/53 dated 20/01/2020. The premises was re inspected by the officers concerned of this department on 15-07-2020 in the presence of Sh. Manoj (Legal Adviser) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from 10 8 20 20 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10.08.2020. at New Delhi by.

(Dharampal Bhardwaj)

Dy. Chief Fire Officer

Copy to:- Sh. Manoj (Legal Adviser), M/s. McDonalds Family Restaurant located at Ground & First Floor, M2K Multiplex, Pitampura, New Delhi – 110034

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: McDonald Family Restaurant Located at Ground & First Floor, M2K Multiplex, Pitam Pura New Delhi -34

2. Type of Occupancy: Assembly (Restaurant) Building (Class-D)Located at Ground & 1st Floor in M2K Mall Rani Bagh

3. Type of Case : Renewal

4. Details of previous NOC: F6/DMS/MS/EH/2016/WZ/319 Dated 29-02-2016 (F6/DFS/MS/2020/53 dated 20/01/2020 issued to the building)

5. Fire Safety directives Letter No.: issued to mall
6. Date of inspection : 15/07/2020
7. Name of the Inspecting Officer: ADO (WP)

8. Name and designation of Officer

from the building side : Sh. Manoj (Legal Adviser)

9. Year of Construction

10. Applicant's letter No. : 2020061005315 dated 01/07/2020

Sr.	Minimum standards on fire	NBC Provided at s		l at site	Remarks				
No	prevention and fire safety U/R 33	Requ	uirements				MR/NMR		
1.	Access of building								
200	Road width		9mtr		Provided		MR		
	 Gate width 		05 mtrs		Prov	ided(In mall)	MR		
	 Width of internal road 		NA	NA		NA	NA		
2.	Number, width, Type & Arrangements of exits(Inside M2K Mall)								
	a. Number of staircases					Ŷ			
	 Upper floors 		2			Provided	MR		
	 Basements 	NA				NA	NA		
	b. Width of staircases					02			
	• Upper floors	1		1.5, 1 X 1m		Provided	MR		
	 Basements 	NA			NA		NA		
	c. Protection of exits								
	 Fire check door 				NA	NA			
	 Pressurization 		NA	NA		NA	NA		
	d. No of continuous staircase to terrace		Required			Provided	MR		
	e. Width Of Corridor	NA				NA	NA		
	f. Door Size	Old Case			Old Case		Old case		
3.	Compartmentation								
	Fire check door		NA		NA		NA		
	 Sealing of electrical shafts 		NA			NA	NA		
	 Fire Rating of shaft door 		NA			NA	NA		
	Water Curtain			NA		NA	NA		
1	 Fire Dampers 		NA		*	NA	NA		
4.	Smoke managements System			0.	-				
	Basements		30 a/c per hr		hr	NA	NA		
-	 Upper floors 			12 a/c per hr		NA	NA		



	Fire Extinguishers	02			Provi	ded		MR
	 Total numbers 	02 ABC / CO2 ISI marked		Provided			MR	
	 Types 							MR.
	 IS marking 	151 1110	IROG			9		
5.	First – Aid Hose Reels			1		Provided		MR
	Total numbers on each floor			m		Provided		MR
	 Length of hose reel 			30 m		Provided		MR
	Nozzle diameter	100						
7.	Automatic fire detection and alarming syst			IA		Provided	3	NA
	Type of detectors			NA NA		Provided		NA
	 Location of Main Panel 			NA		NA		NA
	 Location of Repeater 	Panel		NA		Provided		NA
	 Alternate source of p 	ower		VA		Provided		NA
	 Hooters' Location 			NA	Provid		12	MR
8.	MOEFA	Requ			NA			NA
9.	Public Address System	N.	A		INA			1 12 2
10.	Automatic Sprinkler System			NT A		NA		NA
	Basements		_	NA		NA		NA
	 Upper Floor 			NA		NA NA		NA
	Sprinkler above false	e ceiling_		NA		TALL		
11.	Internal Hydrants:			1.50		Provided		MR
	Size of riser/down- comer			150 mm		Provided		MR
	 Number of hydrants 	per floor		<u>l</u>		Provided		MR
	Hose Box			1		Provided		TVIIC
12	The same of the sa					214	_	NA
12	Total number of hydrants			NA		NA NA		NA
	 Hose Box 			NA		NA		IVA
13			Don see					
13	Pumping Arrangements: (c	ommon w	ith ma	ıll)	B			
	Ground Level					Provid	ed	NA
		Discharge of main pump		NA		Provided		NA
	> Head of main pump)		NA		Provided		NA
	> Number of main pu	C		NA		Provided		NA
	 Jockey pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Staring/Manual stopping 			NA		Provided		NA
			_	NA		Provided		NA
			_	NA		Provided		NA
				NA		Provided		NA
			g	NA NA		Provided		NA
	> Pump House Access			NA		110410		
	• Terrace level		-	4501	- 100	Provid	ded	MR
	Discharge of pump			450 lpm		Provided		MR
	Head of the pumpPower supply			40 m		Provided		MR
				Required		Provided		MR
	> Auto starting of pu	ımp		Required		Provi	ueu	IVIIC
						1		
								.



	C C C Ltings	(common with)				
14.	Captive water Storage for firefighting:	NA NA	Provided	NA		
	Underground tank capacity	NA	Provided	NA		
3	Draw off connectionFire service inlet	NA	Provided	NA		
	> Access to tank	NA	Provided	NA		
	Overhead Tank capacity	10, 000 liters	Provided	MR		
1.5		Required	Provided	MR		
15	Exit Signage Required Provided Provision of Lifts(Common With M2K Mall)					
16.	> Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of lift lobby	Required	Provided	MR		
	Communication in lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	➤ Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area					
10.	> Total area	NA	NA	NA		
1	> Location	NA	NA	NA		
19.	Fire control room					
17.	> Detector system panel	NA	NA	NA		
	> Flow Switch Panel	NA	NA	NA		
	> PA System Panel	NA	NA	NA		
	> Battery backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DMS/MS/EH/2016/WZ/319 Dated 29-02-2016 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer

Officer
Name Udu Vr
Designation

Signature of the Inspecting

Name

Designation