GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/EH/2020/SZ/ 64

Dated: 26/11/2026

FIRE SAFETY CERTIFICATE

Certified that McDonald's Family Restaurant (M/s Connaught Plaza Restaurant Pvt. Ltd) located at Shop no-1, GF, Satyam Cinema Complex, Nehru Place, New Delhi building comprised of Basement, Ground plus two upper floors. The restaurant running at ground floor only was granted FSC by this department vide letter no F6/DFS/MS/EH/2017/SZ/17 dated 02/01/2018. The restaurant premise was re-inspected by the officers concerned of this department on 29/10/2020 in the presence of Mr.Rajkumar Ray (Restt. Manager) and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D " Assembly Building" (Restaurant) as above with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions

(Sunil Chawdhary) Dy. Chief Fire Service Delhi Fire Service

Copy to: -

- 1. The Auth. Signatory, M/s Connaught Plaza Restaurant Pvt. Ltd, 13-A, Jor Bagh Market New Delhi-1100103
- 2. The DHO (Central Zone), South MCD, Health deptt, Lajpat Nagar, New Delhi-24

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

4	INS	PECTION REPORT			
1	Name & Address of the Building	McDonald's Family Restaurant, Shop no-1, GF, Satyam Cinema Complex, Nehru Place, New Delhi.			
		(Operated by M/s Co	onnaught Plaza Restt P	vt. Ltd)	
2	Type of Occupancy	Assembly, "Group-I			
3	Building Comprised of	Basement, Ground	Basement, Ground + 02 upper floors		
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/EH/201	7/SZ/17 dated 02/01/2	018	
6	Fire Safety Directives Letter No	Cir no. 4/22/2004/H	Cir no. 4/22/2004/HP-III/356-369 dated 22/03/2005		
7	Date of Inspection	29/10/2020			
8	Name of the Inspecting Officers	ADO Avtar Singh			
9 -	Name & Designation of Officers from the building side	Mr. Rajkumar Ray (Mr. Rajkumar Ray (Restt. Manager)		
10	Year of construction	2006 Restt running only at ground floor of the bldg			
11	Applicant letter No.	Online ID no.20200	Online ID no.2020091707037 dated 17/09/2020		
S.	Minimum standards on Fire	Old NOC			
No	Prevention and Fire Safety U/R 33	Requirements	Site	MR/NMR	
1	Access to Building.	Provided & Ma	intained by Building N	/anagement	
	Road width	Restt. Located at	As Above	MR	
	Gate width	Satyam Cineplex	-N/A-	-N/A-	
	Width of internal road	-N/A-	-N/A-	-N/A-	
2	Number, width, type & arrangemen	nt of exits. Provided &	Maintained by Building	g Management	
	a) Number of Staircase				
	Upper floors.	Restt at GF only	-N/A-	-N/A-	
	Basement floor.	-N/A-	-N/A-	-N/A-	
	b) Width of Staircase		aintained by Building N	Management	
	- Upper floors	-N/A-	As Above	-N/A-	
	Basement floor	-N/A-	As Above	-N/A-	
	c) Protection of exits		aintained by Building N		
	Fire check door	-N/A-	As Above	-N/A-	
	Pressurization	-N/A-	As Above	-N/A-	
			As Above	-N/A-	
	d) No. of continuous staircase to terrace	-N/A-	As Above	-N/A-	
	e) Width of corridor			MR	
	f) Door size	Two Exits	1.41 m & 1.40 m		
3	Compartmentation.		ined by Building Mana As Above	-N/A-	
	• Fire check door.	-N/A-	CH CHEST FOR STORY OF	-N/A-	
	Sealing of electrical shaftFire rating of shaft door.		As Above		
	Water curtain	-N/A-	As Above	-N/A-	
	Fire dampers.	-N/A-	As Above	-N/A-	
		-N/A-	As Above	-N/A-	
4.	Smoke Management system.		ned by Building Mana		
	• Basement	-N/A-	As Above	-N/A-	
	Upper floors	-N/A-	Provided in Restt.	-N/A-	
5.	Fire Extinguishers.		ained by Building Man		
	Total numbers	05 nos	05Nos '	MR	
146	• Types	ABC / CO ₂	ABC-05	MR	
	ISI Marking	ISI Marked	Provided	MR	

6.	First Aid Hose Reels.		Drovided	MR
0.	Total numbers on each floor			MR
	• Length of hose-reel hose.	30m		MR
	 Nozzle Diameter 	1	Maintained by Building Ma	magement
7	Automatic fire detection & alarming sys	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		MR
	Type of detectors	Required	and the same of th	
	Location of Main Panel	Required		
	Location of Repeater Panel	-N/A-		
	Alternate source of power	Required		
	Hooter's location	Required	One Provided MR 5mm Provided MR m. Provided & Maintained by Building Management Required As Above MR Required Provided MR -N/AN/AN/A- rovided & Maintained by Building Management -N/A- As Above -N/A- -N/A- As Above -N/A- rovided & Maintained by Building Management -N/A- As Above -N/A- -N/A- As Above -N/A- -NA- As Above -NA- -NA- As Above -NA- -NA- As Above -NA- -NA- As Above -N/A- -NA- As Above -N/A- -NA- As Above -N/A- -N/A- As Above	
		Required	The second secon	
8.	MOEFA	-N/A-		
9.	Public Address System	Provided & Mainta	ined by Building Manage	ment
10			As Above	-N/A-
	Basement.	-N/A-	As Above	
	• Upper floors	NΔ-		
	Sprinkler above false ceiling	Provided & Mainta	ained by Building Manage	ement
11	. Internal Hydrants.		As Above	-NA-
	Size of Riser / Down-comer Garage Garag		As Above	-NA-
	 Number of Hydrant per floor 		As Above	-NA-
	 Hose box. 	D wided & N	Agintained by Building M	anagement
12			As Above	-N/A-
	 Total number of hydrants. 	N/A	As Above	
	Hose box.	Provided & Main	tained by Building Manag	gement
1	3. Pumping arrangements.	One Provided MR		
	 Ground Level 	-N/A-	As Above	-N/A-
	 Discharge of main pump. 		As Above	-N/A-
	Head of main pump.		As Above	-N/A-
	Number of main pumps.		As Above	-N/A-
	Jockey Pump output.			-N/A-
	Jockey Pump head.			-N/A-
	Standby Pump output.			-N/A-
	Standby Pump head.Auto Starting/Manual stopping			-N/A-
e	Pump house access.			-N/A-
	rump nouse access.	-N/A-		Management
	Terrace Level		As Above /	MR
	 Discharge of pump. 	450 LPM	,	MR
	- Head of pump.	40 m		
	Power supply.	Required		-N/ANANANANANANAN/AN/AN/AN/AN/AN/AN/AN/AN/AN/AN/AN/AN/AN/A- Management MR MR MR MR MR
	Auto starting of pump.	Required		
	tage for firefight	ing. Provided &	Maintained by Building N	Management
	14. Captive water storage for in engine	C	As Above	-N/A-
	 Underground tank capacity. Draw-off connection. 		As Above	1
	Fire Service Inlet.		As Above	-N/A-
	Access to tank.		As Above	-N/A-
	• Overhead tank capacity.		As Above	MR
				MR
	15. Exit Signage.	Required		

	Provision of Lifts.	Provided & Maintained by Building Management		
	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
	n intimatification	-N/A-	-N/A-	-N/A-
	 Communication in lift car. 	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
	• Fireman's switch.	-N/A-	-N/A-	-N/A-
	Lift signage.	Required	Provided	MR
17	Standby Power Supply	Provided & Maintained by Building Management		
18.	Refuge Area		-N/A-	-N/A-
	Total area	-N/A-	-N/A-	-N/A-
	 Location 	-N/A-		
19.	Fire Control Room.	Provided & Maintained by Building Management		
	Detector System Panel. On the Panel On the Panel	-N/A-	-N/A	-N/A-
		-N/A-	-N/A-	-N/A-
	Danal	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
	Battery backup Deltain floor plan	-N/A-	-N/A-	-N/A-
	 Building floor plan Special Fire Protection System for 			-N/A-

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/EH/2017/SZ/17 dated 02/01/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name : Avtar Singh

Designation: ADO (M.RD)