GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/EH/SZ/2020/ 9 Dated 29/12/2020

FIRE SAFETY CERTIFICATE

Certified that M/s ADAAB Restaurant (A Unit of ADAAB Hotels Ltd.) located at T-307, 3rd floor at Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 running at 3rd floor in Ambience Mall was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/EH/2017/SZ/561 Dated 19/04/2017. The restaurant premise was re-inspected by the officer concerned of this department on 16/12/2020 in the presence of Mr. Shivaji Roa (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant as above with effect from 29. 1.2/2020 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29 / 12 /2020 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) **Delhi Fire Service**

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049.

2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016.

3. M/s ADAAB Restaurant (A Unit of ADAAB Hotels Ltd.) T-307, 3rd floor at Ambience Mall. Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any,

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1	Name & Address of the Building	M/s ADAAB Restaurant, T-307, 3 rd floor at			
		Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 (A Unit of ADAA			
		Hotels Ltd.)	TOUTO (A OII	II OI ADAAI	
2	Type of Occupancy	Assembly Building "Group-D" Restaurant			
3	Building Comprised of	Three tier Basement, Ground + 03 upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/E	EH/2017/SZ/561 Dated 19	/04/2017	
6	Fire Safety Directives Letter No	Nil		Ti .	
7	Date of Inspection	16/12/2020		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers	Mr. Shivaji Roa (Manager)			
10	from the building side				
10	Year of construction	2006-07	Restaurant running at 3	rd Floor in	
11	Applicant letter No.	Online: 1 20	Ambiance Mall buildin	g.	
S. No.	Minimum standards on Fire Prevention		020101507700 dated 20/1	T	
138 1 196	and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR	
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2020/SZ/56 Dated 21/01/2020 of Ambience Mall				
	Road width	Restaurant	As above	MR	
	Gate width	within Mall	As above	N/A	
	Width of internal road		As above	N/A	
2	Number, width, type and arrangements of	f exits.		1 1/12	
	a. Number of Staircase	Provided & Maintained by Ambiance Mall			
	Upper floors	02 Nos	As above	MR	
	Basement floor	N/A	As above	N/A	
	b. Width of Staircase	Provided &	& Maintained by Ambian	1	
	Upper floors	Required	As above	MR	
	Basement floor	N/A	As above	N/A	
	c. Protection of exits		Maintained by Ambian		
	Fire check door	Required	As above	MR	
	 Pressurization 	N/A	As above	N/A	
	d. No. of continuous staircase to terrace	Required	As above		
	e. Width of corridor	N/A	N/A	MR N/A	
	f. Door size	Required	2.0 m & 1.67 m	MR	
		required	2.0 m & 1.0 / m	(old case)	
3	Compartmentation.	Provided & Maintained by Ambiance Mall			
	Fire check door.	Required	As above	MR	
	 Sealing of electrical shafts. 	N/A	As above	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	• Fire dampers.	N/A	N/A	N/A	
4.	Smoke Management system.	Provided &	Maintained by Ambien	550	
	Basement	N/A	As above	N/A	
	• Upper floors	Required	Exhaust fans provided	MR	
5.	Fire Extinguishers.		Extitust rails provided	IVIIX	
	Total numbers	06 Nos	06 Nos.	MD	
	• Types	001100	ABC-04, W.CO ₂ -02	MR	
	ISI Marking	ISI marked	Provided	MR	
6.	First Aid Hose Reels.			MR	
-		r rovided &	Maintained by Ambien		
	Total numbers on each floor.	Hose Reel	One in Restaurant	MR	
	Length of hose-reel hose.Nozzle Diameter		30m 5mm	MR	
7	Nozzle Diameter		omm	MR	

	Type of detectorsLocation of Main Panel	Required Required	Smoke & Heat As above	MR MR	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	Alternate source of power	Required	As above	MR	
NC E MANDAN	 Hooter's location 	Required	As above	MR	
8.	MOEFA	Required	As above	MR	
9.	Public Address System	Required	As above	MR	
10.	Automatic Sprinkler System		& Maintained by Ambie	1	
	Basement	Required	As above	MR	
	 Upper floors 	Required	Provided in Restt.	MR	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
11.	Internal Hydrants.	Provided &	& Maintained by Ambie		
	 Size of Riser/Down-comer 	Required	As above	MR	
	 Number of Hydrant per floor 	Required	As above	MR	
	Hose box.	Required	As above	MR	
12.	Yard Hydrants.	Provided & Maintained by Ambience Mall			
	 Total number of hydrants. 	N/A	As above	N/A	
	• 2. Hose box.	N/A	As above	N/A	
13.	Pumping arrangements.		2 15 400 40	IN/A	
	Ground Level	Provided & Maintained by Ambience Mall			
	Discharge of main pump.	4500 LPM	As above	MR	
	Head of main pump.	70 mtr	As above	MR	
	Number of main pumps.	Two	As above	MR	
	Jockey Pump output.	450 LPM	As above	MR	
	Jockey Pump head.	70 mtr	As above	MR	
	Standby Pump output.	4500 LPM	As above	MR	
	Standby Pump head.	70 mtr	As above	MR	
	Auto Starting / Manual Stopping.	Required	As above	MR	
	Access to pump house	Required	As above	MR	
	Terrace Level	Provided & Maintained by Ambience Mall			
	Discharge of pump.	N/A	N/A	N/A	
	Head of pump.	N/A	N/A	N/A	
	Power supply.	N/A	N/A	N/A	
	Auto starting of pump.	N/A	N/A	N/A	
4.	Captive water storage for Fire Fighting.	Provided &	Maintained by Ambien		
	 Underground tank capacity. 	5,00,000 Ltr	As above	MR	
	Draw-off connection.	Required	As above	MR	
	Fire Service Inlet.	Required	As above	MR	
	Access to tank.	Required	As above	MR	
	Overhead tank capacity.	20,000 Ltr	As above	MR	
5.	Exit Signage.	Required	Provided	MR	
6.	Provision of Lifts.	Provided &	Maintained by Ambien		
	 Pressurization of lift shaft. 	N/A	N/A	N/A	
	 Pressurization of lift lobby. 	N/A	N/A	N/A	
	 Communication in lift car. 	N/A	N/A	N/A	
de la constante	• Fireman's switch.	N/A	N/A	N/A	
	L.	2711	NT/A		
	 Lift signage. 	N/A	N/A	N/A	
	Lift signage. Standby Power Supply	N/A Required	Provided (DG Set)	MR	
8.	 Lift signage. 				
	Lift signage. Standby Power Supply				
	Lift signage. Standby Power Supply Refuge Area	Required	Provided (DG Set)	MR	
	 Lift signage. Standby Power Supply Refuge Area Total area 	Required N/A N/A	Provided (DG Set) N/A	MR N/A N/A	

11/12

20.	Special Fire Protection System for the Protection of special Risk, if any:	N/A	As above	N/A
~ ~	Building floor plan	N/A	As above	N/A
	PA system Panel. Battery backup	N/A	As above	N/A
		N/A	As above	N/A
	• Flow Switch Panel.	N/A	As above	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/2017/SZ/561 Dated 19/04/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO/BCP

Dy Golsz M

M-5-Cell