GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS//2021/ 90

Dated:

13/01/2021

To.

Sh. Virender Kumar Manager (Operation) Pragati Power Corporation Limited, PPS-III, DSIIDC, Industrial Area, Sec.-5, Bawana, Delhi-110039

Sub: - Regarding issuance of Fire Safety Certificate in r/o Pragati Power Corporation Limited, PPS-III, DSIIDC Industrial area, sec.-5, Bawana, Delhi-110039.

Sir,

This has reference to your Letter no. GM(T)/PPS-III/19-20/875 dated 24.11.2020 on the subject cited above. In this connection, it is to inform you that the above mentioned site was visited by the officer concerned of this department in presence of Sh. Virender Kumar (Manager operation) on 23.12.2020 to verify the fire safety arrangements installed in the building. Your request for issue of FSC is rejected under sub rule(3) of Rule 37, due to following shortcomings:

- 1. The width of second staircase of basement at O & M store block is 0.60m against required width of 1.35m.
- 2. Sprinkler system in O & M block not provided in basement.
- 3. Exit signage not provided at some places.

Keeping in view of the above Fire Safety Certificate can not be considered at this stage.

Ph: 011-23414000

su p