FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

No. F6/DFS/MS/2021/SW HOTEL 02

Dated: \4 /01/2021

FIRE SAFETY CERTIFICATE

Certified that the Radisson Blu Hotel (A Unit of Divine Infracon Pvt. Ltd.) Located at Plot No.4, Sector-13 Dwarka city centre, New Delhi-110075. comprised of 3 Basement + Ground + 10 Upper Floors was issued FSC vide Letter No. F6/DFS/MS/Hotel/2017/SZ/896 dated 21/06/2017. The premises was re inspected by the officers concerned of this department on 05/01/2021 in the presence of Sh. Anil Sharma (Director Engineering) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class A-5 "Hotel Building" with effect from hot prevention of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .\.H. .DI. ... 2021... at New Delhi by.

Director, Delhi Fire Service

Copy to:

- 1. The Chairman, DDA, VikasSadan, INA, Delhi-110023.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station, Defence Colony, New Delhi.
- 3. Sh. Anil Kumar Sharma (Director Engineering), Radisson Blu Hotel (A Unit of Divine Infracon Pvt. Ltd.) Plot No.4, Sector-13 Dwarka, city centre, New Delhi-110075.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. www.dfs.delhigovt.nic.in.

Re inspection to see the compliance of shortcomings noted during earlier inspection.

INSPECTION REPORT

 Name & address of the building: Radisson Blu Hotel (A Unit of Divine Infracon Pvt. Ltd.) Located at Plot No.4, Sector-13 Dwarka city centre, New Delhi-110075.

2. Type of Occupancy

: Residential ("A" 5 Hotel)

3. Type of Case : Renewal (3 Basement + Ground + 10 Upper Floors)

4. Details of previous NOC: F6/DFS/MS/Hotel/2017/SZ/896 dated 21/06/17

5. Fire Safety directives Letter No. : F6/DFS/MS /Hotel/BP/2008/1652 Dated 17/06/2008

6. Date of inspection

: 05/01/2021

7. Name of the Inspecting Officer: Dy.CFO/SZ & ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Anil Sharma (Director Engineering)

9. Year of Construction

: 2010

10. Applicant's letter No.

: Email dated 14/12/2020

S No	Minimum standards on fire prevention and fire safety U/R		As per N/125		Pro	Provided at site		Remarks		
	33	On					MR/NMR			
1.	Access of building			-						
	Road width		09 m			8				
	Gate width		4.7		20 m		MR(C	MR(Old Case)		
	• Width of internal i	1			06 m		MR(Old Case) MR(Old Case)			
,										
2.	Number, width, Type & A	rrange	rangements of evits					Tu Cusc)		
э	a. Nulliber of									
	staircases	121	Vos. (8 nos	hasei	ment	12 N (0				
	 Upper floors 	to terrace, 4 nos g			und	12 Nos. (8 nos		MR(Old		
		to se	ervice floo	r)	und	basement to	terrace,	Case)		
	•		1100	1)		4 nos ground	to .			
	 Basements 	08 + 07 + 02 8			s back	service floor)			
			- Tios. bascincin			ent to arrange				
			Ramps nos basement to grou 3 rd basement to first b			at to first be	id 01 no. Case)			
1.				ramn	s (som	e of the doors	ment, 2			
	1 week			locke	ed)	ie of the doors		d d		
	b. Width of staircases				(4)					
	 Upper floors 	1.5 n	ntr each		Provid	led	1 10/10			
	 Basements 	1.5 mtr & 1.0 mtr		ntr	110110	Provided	MR(C	IR(Old Case)		
	c. Protection of exits		Flovide			Flovided	MR(C	old Case)		
	 Fire check door 	Requ	ired	D	· 1	1				
	 Pressurization 	Requ			rovide]	MR		
	d. No of continuous		00 11		rovide		1	MR		
	staircase to terrace	30110			rovide	d	I	MR		
	e. Width Of Corridor	1.5 m	tr	D	• 1					
f. Door Size		1.5 mtr			Provided		MR			
	, '	1.0 111	LI	Pr	ovided	1	. N	/IR		
							1	deland		

			T	X/=la					2.
	3.	Compartmentation	+	70 01)				
		 Fire check door 	+	Required	D	rovided			
		 Sealing of 		Required		ovided			MR
		electrical shafts	and the same of th		11	Ovided			MR
		 Fire Rating of 		2hrs	Pr	ovided) (D
		shaft door				· raca			MR
		• Water Curtain		V/A	N/	'A		-	N/A
-	4.	• Fire Dampers		Required	Pro	ovided			MR
	7.	Smoke managements System						2	TVIIC
		Basements	-						
		Upper floors		Required		ovided ·	19		MR
1	5.	Fire Extinguishers	1	Required	Pro	vided	r.		MR
		Total numbers	2	75 man A.D.C.					
		• Types	6	75 nos ABC, 202 & WCO2		Nos.			MR
		IS marking		SI marked		C, CO2	11	- N	MR
6		First – Aid Hose Reels	-	or marked	Pro	vided			MR
		 Total numbers on 	4	nos. (upper floor					
		each floor	8	nos (Basement)) P	rovided			MR
		 Length of hose reel 	30) m	30 n	n			
		hose	5	mm .	5 mi		ži.		MR
7.		Nozzle diameter		2					MR
/.	F	Automatic fire detection and	ala	arming system			0.		
	-	• Type of detectors		Heat & Smoke	Pr	ovided		-	MR
		• Location of Main Pan	el	Required	Prov	vided			MR ·
		• Location of Repeater Panel		Required	Pro	ovided			MR
		 Alternate source of 		Down't 1		c ²⁰ oc			TVIIC .
		power		Required	Pro	ovided			MR
		 Hooters' Location 		Corridor	Duc	ovided			-
8.	N	OEFA		Required		7 155		7 .	MR
9.	Pu	ıblic Address System		Required		vided		ž.	MR
10.	A	utomatic Sprinkler System		required	Pro	vided			MR
		 Basements 		Required	Pro	vided		1.00	
		 Upper Floor 		Required		vided		MR	
		 Sprinkler above false 		Required		vided		MR MR	
11.	Local	ceiling				rucu		IVIK	
11.	1111	ernal Hydrants:		# # # # # # # # # # # # # # # # # # #			*		
		• Size of riser/down-comer		150 mm	150	mm		MR	
		comer							
8		 Number of hydrants 		010020		10			
22		per floor		04no's (upper flo 08 Nos. (baseme	or)&	Pro	vided	MR	2,
		-		oo 100s. (baselile	nt)				
		 Hose Box 	()4no's (upper floo	or) le	Duo	vided	1 (1)	*
				08 Nos. (basemen	nt)	110	vided	MR	
12.	Var	d Undant)				e m
14.	1 al	d Hydrants		W W	0	7		20	1
		 Total number of hydrants 	1	3	B. C. C.		Provid	led	MR
-		Hose Box	1	3	,60			v v	
*		DUA	1				Provid	ed	MR .
						6			
		0 0							
								- 1	
						2			
								1	1

							N-	V	12					
		13.	Pum	ping Arrangements:										
			•										^	
				Discharge of main			20.70							
			>	Head of main pum	pump		2850 lpi	m		285	0 lpm		MR	
				Number of main pull	p	}	120 m			120	m	10	MR	
	ľ			Jockey pump out p	unps	-	2			2			MR	
	ŀ		A	Jockey pump head		-	220 lpm			220	lpm		MR	
				Standby Pump out	nut	-	90 m			90 1			MR	
				Standby Pump Head	4	-	2850 lpn	n		285	0 lpm		MR	
				Auto Staring/Manua	al		90 m	_		90 r			MR	
				stopping			Required			Auto	mode		MR	
				Pump House Access	S	-	D						IVIIC	
	13			Terrace level		-	Required			Prov	ided		MR	
	1		A	Discharge of pump		-	200.1						1,111	
				Head of the numn			900 lpm			9001			MR	
				Power supply		_	10 m			40 m			MR	
				Auto starting of pum	р	1	Required	b		D.G S			MR	
	14	4.	Captive	e water Storage for fir	e fight	ina	Required			Provid	ded	-	MR	
			•	Under ground tank	o rigili		000 114							
	24			capacity	2,	00,0	000 litres		2,00,00	0 litres	3		MR	
			1	Draw off connection	P	equi	mo d						1,116	
				Fire service inlet		equi		-	Provide		100		MR	
				Access to tank		equi		1	Provide		¥		MR	
			• (Overhead Tank	20	00	0 litres	-	Provide				MR	
	1.7		C	apacity	20	, 00	Ulitres		20, 000	litres			MR	
	15	Ex	kit Sign	nage	Re	quir	and	+	-					a 1
	16.	Pr	ovisio	n of Lifts		quii	cu		Provided		•		MR	
			> P	ressurization of Lift S	Shaft	P	Aquino d							
			P	ressurization of lift lo	hhv		equired equired				ided		MR	
				ommunication in lift	Car		equired			Prov			MR	
=			F	reman's Grounding			equired			Prov		3	MR	
			2	witch						Prov			MR	
1	17	C	Li	ift Signage		1/6	equired			Prov	ided		MR	
-	17. SS	Sta	ndby p	power supply		Re	quired			D. C				
	22	Ref	uge A	rea		100	quired			D.G	Set		MR	
-			1 00							-			*	
				tal area		Red	quired	D	rovidad	(120				
-	19.	D.	Lo	cation		6 th	& 10 th F	loc	rovided	(130sq	.mt)	N	AR Colo	(ose)
-	19.	Fire	contro	ol room	1		ee 10 T	100)I	Provi	ded		MR	
		. ,	> De	tector system panel	Requ	irec	1	Dr	ovided		- a a			- Im
		7	FIO	w Switch Panel	Requ			_			MR	V		1
		,	PA	System Panel	Requ			_	ovided		MR			
			Bat	tery backup	Requ				ovided		MR			
			Bui	lding Floor Plans	Requ				ovided		MR			
					100			F1(ovided		MR			
							*							a .
				,									n "	
													*	
							10							
													2 0	
													-	

1	Special Fire Protection Systems for Protection of special Risks, if any;	Required	Provided manually operated Co2 protection system in HT & LT Panels	MR
---	--	----------	--	----

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/Hotel/2017/SZ/896 dated 21/06/2017 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Not;- Hotel management submitted undertaking (Placed at C/375) stating that the Material used in the passage & staircase has been treated with the fire retardant paint and the material used in carpets in the corridors is made of fire retard cloth material.

Signature of the Inspecting Officer

Name;-Sh Sunil Choudhary

Designation Dy. CFO/SZ

Signature of the Inspecting Officer

Name ;-Udaivir Singh

Designation ADO/DWK

12/1/21

Dh M 2021

FTP5

F.t. is but up for signature, please

Directo & Migor)