## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001**

F.6/DFS/MS/EH/SZ/2021/ 53 No.

Dated 03. / 03. /2021

## **FIRE SAFETY CERTIFICATE**

Certified that M/s Starbucks Coffee- A Tata Alliance, Shop No G - 42, 45 & 46 Ground floor, Select City Walk, Saket, New Delhi- 110017 comprised of three tiers Basement Ground Plus Seven Upper Floors (Restt. running at ground floor of the building) was issued Fire Safety Certificate by this department vide letter no. F.6/MS/DFS/EH/2009/474 dated 16/02/2010 in the name & Style of M/s Coffee beans & Tea leaf. The premise was reinspected by the officer concerned of this department on 19/02/2021 in the presence of Mr. Pardeep Kumar of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant as above with effect from 0.3. / 0.3 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03 / 03 /2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ)

**Delhi Fire Service** 

Copy to: -

1. The Joint C.P (Lic) First Floor, PS Defence Colony, New Delhi – 110049

2 The Dy. Health Officer, Health Department, South MCD, Lajpat Nagar, New Delhi

3 M/s Starbucks Coffee- A Tata Alliance, Shop no.G-42,45 & 46 Ground floor, Select City Walk, Saket, New Delhi- 110017

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

## INSPECTION REPORT

1. Name & address of the building :M/s Starbucks Coffee- A Tata Alliance, Shop no. G-42,45 & 46

Ground floor, Select City Walk, Saket, New Delhi- 110017.

2. Type of Occupancy : Assembly (Ground floor only)

3. Type of Case : Renewal

4. Details of previous NOC : F6/MS/DFS/EH/2009/474 dated 16/02/2010 ( for in the name & Style

of M/s Coffee beans & Tea Leaf)

5. Fire Safety directives letter No : Nil

6. Date of inspection : 19.02.2021

7. Name of the Inspecting Officers : ADO (BCP)

8. Name and designation of officers

from the building side : Mr. Pardeep Kumar (Manager)

9. Year of Construction/conversion : 2013

10. Applicant's letter No. : Online I. D. no 2020060905274 dated 09.10.2020

fire safety U/R 33  ccess to building  Road width Gate width Width of internal road  umber, Width, Type & Arrangement of  Number of staircases Upper Floors Basements  Width of staircases	09m NA NA Exits (Restaurant at GF onl	12m approx NA NA NA NA	MR/NMR  MR  NA  NA				
<ul> <li>Road width</li> <li>Gate width</li> <li>Width of internal road</li> <li>umber, Width, Type &amp; Arrangement of</li> <li>Number of staircases</li> <li>Upper Floors</li> <li>Basements</li> </ul>	NA NA Exits (Restaurant at GF onl	NA NA	NA				
<ul> <li>Gate width</li> <li>Width of internal road</li> <li>umber, Width, Type &amp; Arrangement of</li> <li>Number of staircases</li> <li>Upper Floors</li> <li>Basements</li> </ul>	NA NA Exits (Restaurant at GF onl	NA NA	NA				
<ul> <li>Width of internal road</li> <li>umber, Width, Type &amp; Arrangement of</li> <li>Number of staircases</li> <li>Upper Floors</li> <li>Basements</li> </ul>	NA  Exits (Restaurant at GF onl	NA y)					
<ul> <li>width, Type &amp; Arrangement of</li> <li>Number of staircases</li> <li>Upper Floors</li> <li>Basements</li> </ul>	Exits (Restaurant at GF onl	у)	NA				
Number of staircases  Upper Floors  Basements	NA						
<ul><li>Upper Floors</li><li>Basements</li></ul>		NA					
• Basements		NA					
• Basements	NIA	LALL	NA				
Width of staircases	INA	NA	NA				
Upper Floors	NA	NA	NA				
Basements	NA	NA	NA				
Protection of exits							
	NA	NA	NA				
	NA	NA	NA				
Pressurization							
No. of continuous staircases to terrace	NA	NA	NA				
Width of Corridor	NA	NA	NA				
Door Size	2m & 1.50m	2.00m & 2.00m	MR				
partmentation.							
Fire check door	NA NA	NA	NA				
Sealing of electrical shafts	NA	NA	NA				
Fire Rating of shaft door	NA	NA	NA				
<ul><li>Water Curtain</li><li>Fire Dampers</li></ul>	NA	NA	NA				
The Dampers	NA	NA	NA				
moke Management System.	oke Management System						
Basements			NA				
a Unner floore (Craved Diseas)	12 a/c per hour	Provided	MR .				
Opper Hoors (Ground Floor)							
Fire Extinguishers		5nos I	MR				
	Upper floors (Ground Floor)	• Upper floors (Ground Floor)  12 a/c per hour  Fire Extinguishers	Upper floors (Ground Floor)     12 a/c per hour Provided				

			Co2-1		
	ISI marking	Yes	Yes	MR	
5	First-Aid Hose Reels.Common with Mall				
	Total numbers on each floor	01	Provided	MR	
	Length of hose reel hose	30m	Provided	MR	
	Nozzle diameter				
	Automotic fire detection and clauming system	5mm	Provided	MR	
	Automatic fire detection and alarming system.				
	Type of detectors	NA NA	NA NA	NA NA	
	Location of Main Panel	NA NA	NA NA	NA NA	
	Location of Repeater Panel			NA NA	
	Alternate source of power	NA	NA		
	Hooters' Location	NA	NA -	NA	
	MOEFA	Required	Provided	MR	
	Public Address System.	NA	NA	NA	
0	Automatic Sprinkler System.				
		NA	NA	NA	
	Basement	NA NA	NA NA	NA NA	
	Upper Floor(Ground floor)				
	Sprinkler above false ceiling	NA	NA	NA	
Ĭ	Internal HydrantsCommon with Mall				
	Size of riser/down-comer	100mm	Provided	MR	
	Number of hydrants per floor	01	Provided	MR	
	• Hose Box	01	Provided	MR	
2	Yard Hydrants.				
	Total number of hydrants	NA NA	NA	NA	
	Hose Box	NA	NA	NA	
3	Pumping Arrangements.Common with Mall				
	Ground Level				
	Discharge of main Pump	4500 lpm	4500 lpm	MR	
	➤ Head of Main pump	88m	88m	MR	
	Number of main pumps	02	02	MR	
	➤ Jockey Pump out put	180 lpm	180 lpm	MR	
	> Jockey pump head	88m	88m	MR	
	Standby Pump out put	4500 lpm	4500 lpm	MR	
	Standby Pump Head	88m	88m	MR	
	➤ Auto Starting/ Manual stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided .	MR	
	Terrace level				
	> Discharge of pump	N/A	N/A	N/A	
	➤ Head of the pump	N/A	N/A N/A	N/A N/A	
	> Power Supply	N/A			
	> Auto Starting of pump	N/A	N/A	N/A	
		an with Mall		1	
14	Captive Water Storage for fire fighting. Comm	CHE ANTER LARSER			

	> Draw-off connection	Required	Provided	MR			
	> Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	30,000 ltr	Provided	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	NA	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA			
	Lift Signage	NA	NA	NA			
17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA			

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/MS/DFS/EH/2009/474 dated 16/02/2010, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/BCP

Defolds)

refolds) Et.

PDO BODI

in the factor was