FORM 'H'

## FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No.

\$10\$51 ms 2021 ws VGP) 159

Dated:

10/03/2021

## FIRE SAFETY CERTIFICATE

Issued on 10/03/2, 2) at New Delhi by.

Director Delhi Fire Service

Copy to:

1. M/s. Time Entertainment Private Ltd. (Video Game Parlour), SH/3F/05, 3<sup>rd</sup> Floor, Pacific Mall, Tagore Garden, New Delhi.

2. Joint Commissioner of Police (Licensing), 1<sup>st</sup> Floor, Police Station Defence Colony, New Delhi- 110049.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.

## INSPECTION REPORT

1. Name & address of the building: M/s. Timezone Entertainment Private Ltd., SH/3F/05, 3<sup>rd</sup> Floor, Pacific Mall, Tagore Garden, Najafgarh Road,

New Delhi- 110018.

2. Type of Occupancy : Assembly

3. Type of Case : New Case

4. Details of previous NOC : N/A

5. Fire Safety directives Letter No.: N/A

6. Date of inspection : 02-03-2021

7. Name of the Inspecting Officer : Sarabjeet Singh, ADO (MN)

8. Name and designation of Officer

From the building side : Sh. Ashok Kumar (Manger)

9. Year of Construction : 2011

10. Applicant's email date : Joint CP/Lic (Amst.) Dated, New Delhi

The said Timezone Entertainment Private Ltd. Video game parour is running on third floor of Pacific Mall-FSC of Mall issued vide letter No. F.6/DFS/MS/WZ/2020/267 dated 22.07.2020.

S	Minimum standards on fire	BBL	Provided at site	Remarks		
No	prevention and fire safety U/R 33	Requirements		MR/NMR		
1.	Access of building		7 11 1	) MD		
	Road width	12 mtrs	Provided	MR		
	Gate width	5 mtr	Provided	MR		
	Width of internal road	6m	Provided	MR		
2.	Number, width, Type & Arrangements of exits: common with the mall					
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	2	Provided by mall	MR		
	• Basements	NA	NA	NA		
	b. Width of staircases					
	• Upper floors	Required	Provided by mal			
	Basements	NA	NA	NA		
	c. Protection of exits					
	• Fire check door	NA	NA	NA		
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA		
	d. No of continuous staircase to	) NA	NA	NA		
	terrace	Required	Provided by mal	1 MR		
	e. Width Of Corridor	2 mts	Provided	MR		
	f. Door Size	&1.5 mtr				
3.	Compartmentation					
	<ul><li>Fire check door</li><li>Sealing of electrical shafts</li></ul>	NA	NA	NA		
		NA	NA	NA		
	• Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	• Fire Dampers	NA	NA	NA		
4.	Smoke managements System					
	Basements	NA	NA	NA		

71 7 7	Upper floors	12 a/c per	Provided	MR			
5.	Circ Extinguishors	hour	· ·				
٥.	Fire Extinguishers  • Total numbers						
			Provided	MR MR			
	• Types	DCP &CO <sub>2</sub>	Provided	MR			
	IS marking	ISI marked	Tiovided	IVIIC			
6.	First – Aid Hose Reels						
	<ul> <li>Total numbers on each floor</li> </ul>		Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR			
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR			
7.	Automatic fire detection and alarmi						
	<ul> <li>Type of detectors</li> </ul>	Smoke	Provided	MR			
	<ul> <li>Location of Main Panel</li> </ul>	Required		MR			
	<ul> <li>Location of Repeater Panel</li> </ul>	NA	NA NA	NA			
	<ul> <li>Alternate source of power</li> </ul>	Required		MR			
	<ul> <li>Hooters' Location</li> </ul>	Required	and the second s	MR			
8.	MOEFA	Required		MR			
9.	Public Address System	NA	Provided	NA			
10.	Automatic Sprinkler System						
	<ul> <li>Basements</li> </ul>	NA	NA	NA			
	<ul> <li>Upper Floor</li> </ul>	Required		MR			
	<ul> <li>Sprinkler above false ceiling</li> </ul>	g Required	l Provided	MR			
11.	Internal Hydrants: Common with the mall						
	Size of riser/down- comer	150 mm	Provided	MR ••			
	<ul> <li>Number of hydrants per floor</li> </ul>	or Required		MR			
	<ul> <li>Hose Box</li> </ul>	Required	l Provided	MR			
12.	Yard Hydrants						
	<ul> <li>Total number of hydrants</li> </ul>	NA	NA	NA			
	<ul> <li>Hose Box</li> </ul>	NA	NA	NA			
13.	Pumping Arrangements: Common with the mall						
	Ground Level						
	<ul> <li>Discharge of main Pump</li> </ul>	NA	Common with the ma				
	Head of main pump	NA	Common with the ma				
	Number of main pumps	NA	Common with the ma				
	Jockey pump out put	NA	Common with the ma				
	Jockey pump head	NA	Common with the ma				
	Standby Pump out put	NA	Common with the ma				
	> Standby Pump Head	NA	Common with the ma				
	<ul><li>Auto Staring/Manual stopping</li><li>Pump House Access</li></ul>	2 12 2	Common with the ma				
		NA	NA   Common with the mall				
	<ul><li>Head of the pump</li></ul>	900 lpm	Common with the ma				
	> Power supply	40 m	Common with the ma				
	> Auto starting of pump	Required	Common with the ma				
1.4		Required	Common with the ma	11 MR			
14.	Captive water Storage for firefighti		D.T.A				
	• Underground tank capacity	NA	2,00,000 litres	NA			
				NA			
	Fire service inlet	Require		MR			
	Access to tank	NA 10, 000 liv	Provided 20,000 Lituas	NA MB			
	Overhead Tank capacity	10, 000 lit	res 30, 000 Litres	MR			



15	Exit Signage	Required	Provided	MR	
16.	Provision of Lifts				
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of lift lobby	NA	NA	NA	
	Communication in lift Car	NA	NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
17.	Standby power supply	Required	Provided	MR	
18.	Refuge Area				
	Total area	NA	NA	NA	
	Location	NA	NA	NA	
19.	Fire control room				
	Detector system panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Battery backup	NA	NA	NA	
	Building Floor Plans	NA	NA	NA	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA	

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The shortcomings pointed by this deptt. Vide letter No. F6/DFS/MS/MN/2021 VGP/ 462 dated 26/02/2021 have complied by the management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate as per as per the Delhi Fire Service Rules 2010 under Delhi Fire Service Act- 2007.

Accordingly, DFA is put up please

85 ADO MN 04 03 2021

DATED. 413. 204

Do (west)

Signature of the Inspecting Office Name: Sarabjeet Singh

Designation: ADO (MN)

DOFO (WZ)

Jam

of the mont

10/0%