L-57

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/2021/School/WZ/

528

Dated 26/7 /2021

FIRE SAFETY CERTIFICATE

Issued on ... 26 7 ... at New Delhi

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel:-01123414250

Copy to: -

- The Director of Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2 The Principal, Lancer's Convent Sr. Sec. School, Sector-14, Rohini, Delhi-85.

Conditions for the validity of Fire Safety Certificate:

- 1 All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5 This certificate cannot be treated in any case for regularizations of unauthorized construction.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7 The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

	1 Name & address of the building	·Land	CHUN Per's Co	KEPUR'				
			i-110085	nvent Sr.	Sec. School, Sector-1	4, Rohini		
	2 Type of Occupancy							
	3 Type of Case	:Rene	wal	1 DIOCK- E	3 + G + 02 Upper floor)			
	4 Details of previous NOC		A	017/Saba	ool/WZ/1339 dated 08.0			
	5 Fire Safety directives letter No	: NBC		OT HOUNG	301/ WZ/1339 dated 08.0	9.2017		
	6 Date of inspection	: 06.07						
	7 Name of the Inspecting Officers		: A.K.Sharma ADO (Rohini)					
	8 Name and designation of officers		maina r	IDO (NOI	iini)			
	from the building side		ogender M	Mann (So.	avata			
	9. Year of Construction	Jogender Mann (Secretary)						
	202Ó							
	Minimum Standards on fire pro and fire safety U/R 33	NBC	Provided at site	Remarks				
1			Keq	uirement		MR/NMR		
	Treetess to building							
	Road width		Acc	essible	Accessible	MR		
		Gate width		quired	Provided	MR		
2	 Width of internal road 			NA	NA	NA		
-	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	 Upper Floors 			04	04	MR		
	Basements		4 9	stairs	4 stairs	MR		
	b. Width of staircases					1411		
		Upper Floors		0 m	1.68m x 4	MR		
	Basements		1.4	50m	1.50m x 4	MR		
	c. Protection of exits		275			17117		
		- magain		uired A	Provided	MR		
				1	NA	NA		
					all	MR		
	e. Width of Corridor			mtr	2.5 m	MR		
3	f. Door Size		1.()m	1.0m	MR		
)	Compartmentation. • Fire check door • Paguin 1							
				ired	Provided	MR		
	seaming of electrical sharts		N/		N/A	N/A		
	Fire Rating of shaft doorWater Curtain		N/.	A	N/A	N/A		
			NA		NA	NA		
	The Dampers		NA		NA	NA		
4	Smoke Management System.			~~~				
	 Basements 	30 a/c pe			Exhaust Fan	MR		
Per l	 Upper floors 	12 a/c per	hour	N	atural Ventilation			
5	Fire Extinguishers			110	v Chillation	MR		
and the second s	Total numbers 50nos 50 MP					MR		
	• Types		CO2/ A	BC	35-ABC/15- Co2	MR		
	a ISI marking							

6	First-Aid Hose Reels.		,	By				
	Total numbers on each floor	04	Provided	MR				
	 Length of hose reel hose 	30 m	Provided	MR				
	Nozzle diameter	5mm	Provided	MR				
7	Automatic fire detection and alarming sys		11011404	14114				
	Type of detectors	N/A	N/A	N/A				
	 Location of Main Panel 	N/A	N/A	N/A				
American Commission of the Com	 Location of Repeater Panel 	N/A	N/A	N/A				
	Alternate source of power	N/A	N/A	- N/A				
	Hooters' Location	N/A	N/A					
8	MOEFA	N/A		N/A				
9	Public Address System.	Required	N/A Provided	N/A MR				
10	Automatic Sprinkler System.		Tiovided	IVIIX				
	Basement	Required	Provided	MR				
	Upper Floor	. NA	NA	NA				
	Sprinkler above false ceiling	NA	NA	NA				
11	Internal Hydrants			141				
THE RESIDENCE OF THE PARTY OF T	Size of riser/down-comer	6 "Required	Provided	MR				
	 Number of hydrants per floor 	4	Provided	MR				
	Hose Box	4	Provided	MR				
12	Yard Hydrants.							
	Total number of hydrants	08	08	MR				
	Hose Box	08	08	MR				
13	Pumping Arrangements.			1417				
	Ground Level							
	Discharge of main Pump	2280 lpm	2280 lpm	MR				
	Head of Main pump	70 M	70m	MR				
	Number of main pumps	01	Provided	MR				
	Jockey Pump out put	180 LPM	180 LPM					
	Jockey pump head	70 M		MR				
	Standby Pump out put		70m	MR				
7.000	Standby Pump Head	2280 lpm	2280 lpm	MR				
	Auto Starting/ Manual stopping	70 M	70m	MR				
	Pump House Access	Required	Provided	MR				
	Terrace level			-				
	Discharge of pump	900 lpm	900 lpm	MR				
	➤ Head of the pump	40m	. 40m	MR				
	Power Supply	Required	Provided	MR				
1.4	Auto Starting of pump	Required	Provided	MR				
14	Captive Water Storage for fire fighting.							
	Underground tank capacity	10,0000ltr.	0,0000ltr. 10,0000 ltr					
	Draw-off connection	Required	Provided	MR				
	Fire service inlet	Required	Provided	MR				
	Access to tank	Required	Provided	MR				
	Overhead Tank canacity	50,000 14-	CO 000 I					

Prov	vision of Lifts.	N/A	N/A	N/A			
0	Pressurization of Lift Shaft			N/A			
•	Pressurization of Lift lobby	N/A	N/A	IV/A			
	Communication In lift Car	N/A	N/A	N/A			
0	Fireman's Grounding Switch	N/A	N/A	N/A			
- 6	Lift Signage	N/A	N/A	N/A			
Sta	ndby power supply	Required	Provided	MR			
	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
Fir	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	 Flow Switch Panel 	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
Sp	ecial Fire Protection Systems for otection of special Risks, if any:	N/A	N/A	N/A			

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 206 dated 09.04.2021, the FSC issued vide letter no. F.6/DFS/MS/2017/School/WZ/1339 dated 08.09.2017, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

Perus al and Signature plans.