CMS

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2021/EH/WZ/ / 5 9

Dated 29/7/21

## FIRE SAFETY CERTIFICATE

Certified that the M/s Pizza Hut a Unit of Devyani international ltd. Shop No. G-20, GF, Funcity Mall, Sector-14, Prashant Vihar, Rohini, Delhi-110085 in the building comprised of basement, ground and 04 upper floor owned/ occupied by M/s Pizza Hut a Unit of Devyani department vide international Itd was granted NOC by this F.6/DFS/MS/2018/EH/WZ/1979 dated 29.08.2018. The premises was re-inspected by the officers concerned of this department on 05.07.2021 in the presence of Sh. Selesh (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010. Hence the NOC is renewed and premises is fit for occupancy Class (Assembly) Shop No. G-20, GF with effect from -28(7/2/ for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 28/7/21... at New Delhi by

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

OLL

Copy to:-

- 1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.
- 2. Sh. Selesh (Manager), M/s Pizza Hut a Unit of Devyani international ltd. Shop No. G-20, GF, Funcity Mall, Sector-14, Prashant Vihar, Rohini, Delhi-110085.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

0								
	INSPECTIO	N REPORT	motional 14	d Shon No	G-20	GF.		
1.	Name & address of the building: Pizza Hut a Unit of Devyani international ltd. Shop No. G-Funcity Mall, Sector-14, Prashant Vihar, Rohini, Delhi-110							
	Funcity Mail, Sector 11, 11 annual Shap No. G-20)							
	Domay 1							
3. 4	Type of case	Details of Previous NOC : F.6/DFS/MS/2018/EH/WZ/1979 dated 29.08.2018  Fire Safety directives letter No : (F.6/DFS/MS/2019/WZ/911 dated 29.04.2019 - Mall NOC)						
5.	Fire Safety directives letter No : (F.6/DFS/MS/							
6.	Date of inspection : 05.07.2021	DO(Rohini)						
7.				*				
8.	Name and designation of officers From the building side : Sh. Selesh (M	lanager)						
9	2007		C10555 1	. 102 10 20	20			
10	Applicant's letter No. :Online application	tion No.20210226	Provided	ted UZ.1U.Z	Remarks			
. No.	C I I C TO	NBC	at Site	MR/N				
	and fire safety U/R 33	Requirement	/DEC/MS/20	10/W7/911 da	-			
0	Access to building (Ring Road Mall issued FSC	Accessib	10 TS/1VIS/20	Accessibl	e	MR		
	Road width	Accessib		Accessibl		MR		
	• Gate width	Accessio NA			NA			
	Width of internal road		aintained by		ementl	and the same of th		
10	Number, Width, Type & Arrangement of E	XITS Provided & M	annamed by	vian manag	, , , , , , , , , , , , , , , , , , , ,			
	a. Number of staircases	Doctorment with	nin Mall	As Abov	re l	NA		
	<ul> <li>Upper Floors</li> </ul>	Restaurant within Mall Restaurant within Mall		As Abov		NA		
	<ul> <li>Basements</li> </ul>			1151100				
	b. Width of staircases	Destaurant with	Restaurant within Mall		ve	NA		
	Upper Floor	· ·		As Above		NA		
	Basements	Restaurant within Mall		AS AUG	VC			
	c. Protection of exits	D. A. saturithin Moll		As Above		NA		
	Fire check door[Provided &	Restaurant within Mall		As Abo		NA		
	<ul> <li>Pressurization</li> </ul>		Restaurant within Mall		ve	NA		
	d. No. of continuous staircases to terrace		Restaurant within Mall			NA		
	e. Width of Corridor		Restaurant within Mall		As Above			
	f. Door Size	02 Ex	it	1.80m & 1	./Um	MR		
3.	Compartmentation							
J 0	Fire check door		Restaurant within Mall		ve	NA		
	Sealing of electrical shafts	Restaurant within Mall Restaurant within Mall Restaurant within Mall Restaurant within Mall		As Abo		NA		
	<ul> <li>Fire Rating of shaft door</li> </ul>					NA		
	Water Curtain			As Above		NA		
	• Fire Dampers			As Above		NA		
4.	Smoke Management System [Provided & Maintained by Mall management]							
	Basements	Restaurant v		1 As Above N		NA		
	Upper floors	Restaurant within Mall		As Al	bove	NA		
and the second	Fire Extinguishers							
5.	Total numbers	04		04		MR		
	• Types	ABC/Co2/DCP		ABC	/Co2	MR		
	• IS marking	ISI M	ISI Marked		es	MR		
6.	To Harring Weinteined by Well management							
0.	Total numbers on each floor	01		As A		MR		
	• Length of hose reel hose	30m		As Above		MR		
	Nozzle diameter	5mm			As Above MF			
7.	Automatic fire detection and alarming sy	stem. [Provided &	Maintained	l by Mall mar	nagemer	nt]		

	Location of Main Panel	Restaurant within Mall	As Above	NA		
	<ul> <li>Location of Repeater Panel</li> </ul>	Restaurant within Mall	As Above	NA		
	Alternate source of power	Restaurant within Mall	As Above	NA		
	Hooters' Location	Restaurant within Mall	As Above	NA		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	NA	As Above	NA		
10.	Automatic Sprinkler System [Provided & M	aintained by Mall managemen	nt]			
	Basement	Restaurant within Mall	As Above	NA		
	Ground & Upper Floors	Restaurant within Mall	As Above	NA		
	Sprinkler above false ceiling	Restaurant within Mall	As Above	NA		
11.	Internal Hydrants [Provided & Maintained	by Mall management]				
	Size of riser/down-comer	100mm	As Above	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>	One (near to Restaurant)	As Above	MR		
	Hose Box	One (near to Restaurant)	As Above	MR		
12.	Yard Hydrants[Provided & Maintained by Ma	all management]	1			
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13.	Pumping Arrangements[Provided & Maintained by Mall management]					
	Ground Level					
	Discharge of main Pump	NA	NA	NA		
	Head of Main pump	NA	NA	NA		
	Number of main pumps	NA	NA	NA		
	Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA		
	Standby Pump out put	NA	, NA	NA		
	Standby Pump Head	NA	NA	NA		
	Auto Starting/Manual Stopping	NA	NA	NA		
	Pump House Access	NA	NA	NA		
			Maintained by Mall management]			
	Terrace level	NA	As above	MR		
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	NA	As above	MR		
	Power Supply	Required	As above	MR		
	Auto Starting of pump	Required	As above	MR		
14.	Captive Water Storage for fire fighting	required	713 000 00	IVIIC		
14.		NA	As above	NA		
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	NA	As above As above	NA		
	Fire service inlet		As above As above	NA NA		
	> Access to tank	NA				
	Overhead Tank capacity	NA	As above	NA		
1.5	Euit Ciana an	NA Paguired	As above	NA		
15.	Exit Signage.  Drawisian of Lifts   Drawided & Maintain	Required	Provided	MR		
16.		ned by Mall management]				
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA NA		
	Communication In lift Car     Fireman's Grounding Switch	NA	NA	NA		
	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	NA	NA	NA		
	Lift Signage	NA	NA	NA		
17.	Standby power supply	Required	As above	MR		
18.	Refuge Area. [Provided & Maintained by M	all management]				
	> Total Area	NA	NA	NA		

(5-LR

1	> Location	NA	NA	NA			
19.	Fire Control Room [Provided & Maintained by Mall management]						
	Detector System Panel	NA	NA	NA			
	Flow Switch Panel	NA	NA	NA			
	PA System Panel	NA	NA	NA			
	Battery backup	NA	NA	NA			
	Building Floor Plans	NA	NA	NA			
20.	Special Fire Protection Systems for Protection	NA	NA	NA			
	of special Risks, if any:						

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2018/EH/WZ/1979 dated 29.08.2018. Renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Ajay Kumar Sharma Name Designation ADO (Rohini)

FT letter is fait up for kind pensa Signature Bease