GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/School/2021/SZ/

657

Dated: 27.1.8.1/2021

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Senior Secondary School, No-2, Badarpur, New Delhi-110044 (ID-1925054) comprised of Old Block, (Ground plus one upper floor) and New Block (Ground plus three upper floor) was issued FSC by this department vide letter No. F.6/DFS/MS/School/2017/SZ/21 dated 02/01/2018. The premises was re-inspected by officer concerned by this department on 19/08/2021 in the presence of Ms. Kamakshi Jolly (Vice Principal) of the school and observed that the school premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" Group—B (School) as above with effect from the date of issue of this certificate for period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of conditions mentioned below.

Issued $\frac{17}{8}$ /2021 at New Delhi by

DY. CHIEF FIRE OFFICER (SZ)
DELHI FIRE SERVICE

Copy to: -

- 1. Govt. Girls Senior Secondary School, No-2, Badarpur, New Delhi-110044 (ID-1925054)
- 2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. Basement shall be used strictly in accordance with provisions of BBL-1983.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1	Name	** INSPE & Address of the Building	CTION REPORT	r Sagandary Sahaal Na	2 Padarnus	
			Govt. Girls Senior Secondary School, No-2, Badarpur, New Delhi-110044 (ID-1925054)			
2	- principle of green commence	f Occupancy	Educational Building "Group-B" (School)			
3	Buildin	g Comprised of	Old Bldg - Ground Plus one upper floor New Bldg - Ground Plus three upper floors (2 Blocks)			
4	Type of	f Case	Renewal			
5	Details	of Previous NOC	F.6/DFS/MS/School/2017/SZ/21 dated 02/01/2018			
6	Fire Sa	fety Directives Letter No	F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011			
7	Date of Inspection		19/08/2021			
8	Name of the Inspecting Officers		Sh. Rajesh Kumar ADO (BCP)			
9	Officer	Designation of sfrom the building side	Ms. Kamakshi Jolly (Vice Principal)			
0		construction ant letter No.	Old bldg2008, New bldg2016			
l l I		um standards on Fire Prevention	Gmail dated 03/08/2021 As Per Old NOC Provided at Site Remarks			
lo .	1	re Safety U/R 33	AS FEE OIG NOC	Frovided at Site	MR/NMR	
1		to Building.		ll	IVARO I VIVIA	
-	Access	Road width	Required	6 mtr	MR	
		Gate width	-N/A-	4.5 mtr	-N/A-	
		Width of internal road	-N/A-	-N/A-	-N/A-	
Ž.		r, width, type & arrangement of exits	-1N//A-	-IV/A-	-14/1/-	
		mber of Staircase				
			01411 1 2	01111 1 1 5	* ***	
	A	Upper floors	Old block- 5	Old block 1-5 nos	MR	
	Taxanian and San		New Bk- 3 & 1 nos	New Bk- 3 & 1 no	MR	
	. >	Basement floor	-N/A-	-N/A-	-N/A-	
	b) Wie	dth of Staircase				
	A	Upper floors	1.5 m/0.75m	Old block - 1. 7 m × 3, 1.84 m, 1.45 m New Block - 1.60 m × 3 m & 1.70 m	MR	
	7	Basement floor			-N/A-	
	c) Protection of exits		-N/A-	-N/AN		
	-	Fire check door	-N/A-	-N/A-	-N/A-	
	A	Pressurization	-N/A-	-N/A-	-N/A-	
		of continuous staircase to terrace	Required	Old Bk-2, New Bk- 2 + 1	Secretary and an expension of the first state of the property of	
		dth of corridor	-N/A-	-N/A-	-N/A-	
	f) Door size		1 mtr	1 mtr Provided		
3		rtmentation.	>T/A	NI/A	> T / A	
	•	Fire check door.	-N/A-	-N/A-	-N/A-	
	*	Sealing of electrical shafts.	-N/A-	-N/A-	-N/A-	
	•	Fire rating of shaft door.	-N/A-	-N/A-	-N/A-	
	•	Water curtain	-N/A-	-N/A-	-N/A-	
المراجعة والمراجع		Fire dampers.	-N/A-	-N/A-	-N/A-	
	Smoke	Management system.		And a second desirable		
l.	-	Basement	-N/A-	-N/A-	-N/A-	
l.,	•	Control of the Contro				
	•	Upper floors	-N/A-	-N/A-	-N/A-	
	•	Control of the Contro		-N/A-	-N/A-	
	•	Upper floors		-N/A-	-N/A-	
	• Fire Ex	Upper floors tinguishers. Total numbers	-N/A-	44 nos	MR	
	Fire Ex	Upper floors tinguishers.	-N/A- 40 nos ABC / CO ₂	44 nos ABC-23, CO ₂ -16, DCP-05	MR MR	
5.	Fire Ex	Upper floors tinguishers. Total numbers Types	-N/A-	44 nos	MR	
5.	Fire Ex	Upper floors tinguishers. Total numbers Types ISI Marking	-N/A- 40 nos ABC / CO ₂ ISI marked	44 nos ABC-23, CO ₂ -16, DCP-05 Provided	MR MR MR	
5.	Fire Ex	Upper floors tinguishers. Total numbers Types ISI Marking id Hose Reels.	-N/A- 40 nos ABC / CO ₂ ISI marked New Bk- 3 + 1	44 nos ABC-23, CO ₂ -16, DCP-05 Provided Provided	MR MR MR	
5.	Fire Ex	Upper floors tinguishers. Total numbers Types ISI Marking id Hose Reels. Total numbers on each floor.	-N/A- 40 nos ABC / CO ₂ ISI marked	44 nos ABC-23, CO ₂ -16, DCP-05 Provided	MR MR MR	

	Location of Repeater Panel	-N/A-	-N/A-	-N/A-
	Alternate source of power	-N/A-	-N/A-	-N/A-
	Hooter's location	-N/A-	-N/A-	-N/A-
8.	MOEFA	-N/A-	-N/A-	-N/A-
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			-1\/A-
10.	Basement	-N/A-	-N/A-	T/A
	Upper floors		201 and 4017000	-N/A-
	Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
11.	Internal Hydrants.	-N/A-	-N/A-	-N/A-
11.		DT/A	21/4	
	Size of Riser/Down-comerNumber of Hydrant per floor	-N/A-	-N/A-	-N/A-
	Hose box.	-N/A-	-N/A-	-N/A-
12.	Vand Huduanta	-N/A-	-N/A-	-N/A-
12.	Yard Hydrants.	27/4	27/4	
	Total number of hydrants.Hose box.	-N/A-	-N/A-	-N/A-
1		-N/A-	-N/A-	-N/A-
13.	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	Head of main pump.	-N/A-	-N/A-	-N/A-
	Number of main pumps.Jockey Pump output.	-N/A-	-N/A-	-N/A-
	Jockey Pump head.	-N/A-	-N/A-	-N/A-
	Standby Pump output.	-N/A- -N/A-	-N/A-	-N/A-
	Standby pump head.	-N/A- -N/A-	-N/A-	-N/A- -N/A-
	Auto Starting/Manual Stopping.	-N/A-	-N/A-	-N/A-
	Terrace Level			
	Discharge of pump.	450 LPM each	Provided	MR /
	Head of pump.	40 m	Provided	MR
	Power supply.	Required	Provided	MR (
	Auto starting of pump.	Required	Provided	MR /
14.	Captive water storage for Fire Fighting.	1	Tiovidod	TVIIC /
	Underground tank capacity.	-N/A-	-N/A-	-N/A-
	> Draw-off connection.	-N/A-	-N/A-	-N/A-
	Fire Service Inlet.	-N/A-	ancocanisas per asur anche spross pressoren pressoren pressoren pressoren per a company anche per a compan	-N/A-
		-N/A-	-N/A-	
	Access to tank.		9	-N/A-
	Overhead tank capacity.	10,000 ltrs	Provided	MR 1
15.	Exit Signage.	Required	Provided	MR /
16.	Provisions of Lifts.	DI/A	27/4	
	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
	Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-
	Communication in lift car.	-N/A-	-N/A-	-N/A-
	• Fireman's switch.	-N/A-	-N/A-	-N/A-
	• Lift signage.	-N/A-	-N/A-	-N/A-
17	Standby Power Supply	-N/A-	-N/A-	-N/A-
18.	Refuge Area		national property of the liberty	L 1/ L X
	Total area	-N/A-	-N/A-	-N/A-
	• Location	-N/A-	-N/A-	-N/A-

F. N. S.

a Flow S	witch Panel	-N/A-	-N/A-	-N/A-
	 Flow Switch Panel. PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
		-N/A-	-N/A-	-N/A-
		Dystaction of enecial Ris	k. if anv.	- N/A-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 23 dated 12/01/2021

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/School/2017/SZ/21 dated 02/01/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: Sh. Rajesh Kumar

Designation: ADO (BCP)