(5

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F.6/DFS/MS/EH/2021/SZ/ 2 37

FIRE SAFETY CERTIFICATE

Dated: 16/8/2/

Certified that the M/s The Beer Café (A Unit of BTB Marketing Pvt. Ltd.) running at second floor only in a building comprised of Two tier basement, ground plus eight upper floor located at Unit no. 204, Second Floor Orchard Mall Unit one, MLPC Plot, West Metro Station, Janakpuri, New Delhi-110058, owned/occupied by M/s The Beer Café (A Unit of BTB Marketing Pvt. Ltd.) have complied with the fire prevention and fire safety requirements in accordance with the rule 33 of the Delhi Fire Service Rule 2010 and verified by the officer concerned of this department on 18/08/21 & 04/09/2021 in the presence of manager and found that the building is fit for occupancy 'Class D' "Assembly Building" (Restaurant/Bar) ' for with effect from [.6/3./2.]... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Delhi Fire Service

To,

M/s The Beer Café (A Unit of BTB Marketing Pvt. Ltd.) Unit no. 204, Second Floor Orchard Mall Unit one, MLPC Plot, West Metro Station, Janakpuri, New Delhi-110058.

Copy to:-

The Dy. Health Officer (West Zone), SDMC, Public Health Department, Rajouri Garden, New Delhi.

Following fire safety directives must be adhered to:-

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building: M/s The Beer Café (A Unit of BTB Marketing Pvt. Ltd.) Unit no. 204, Second Floor Orchard Mall Unit one, Janakpuri, MLPC Plot, West Metro Station, Janakpuri, New Delhi-110058 Building is comprised of : Two tier basement, ground plus eight upper floor but restaurant at second floor only 3. Type of Occupancy Group D (Assembly) 4. Type of Case New 5. Details of Previous NOC F.6/DFS/MS/PRKG/2019/SZ/173 dated 24.01.19 (for MLCP cum Commercial Complex Janakpuri) 6. Fire Safety directives letter No: 7. Date of inspection 18/08/21 & 04/09/2021 8. Name of Inspecting Officers A.D.O. R.K. Yadav 9. Name and designation of officers From the building side : Manager 10. Year of Construction : 2015 11. Applicant's letter No. : online application ID 2021072716021 dated 28/07/2021 S. Minimum Standards on fire prevention and Requirements Provided at Remarks No. fire safety U/R 33 MR/NMR site 1. Access to building Road width 09 mtrs. Provided M/R Gate width 06 mtrs. Provided M/R Width of internal road 06 mtrs. Provided M/R 2. Number, Width, Type & Arrangement of Exits (Restaurant at SF only) a. Number of staircases Upper Floors MR 03 no.'s 03 no.'s Basements 03 no.'s 03 no.'s MR b. Width of staircases Upper Floor 1.5 M each 1.5 M each MR Basements 1.5 M each 1.5 M each MR c. Protection of exits Provided MR Required Fire check door Provided MR Pressurization Required d. No. of continuous staircases to Required Provided MR terrace 1.50 m 1.50 m l M/R e. Width of Corridor 12 m & 1.5 m 2 m & 1.5 m M/R f. Door Size OZMELSM GEL 3. Compartmentation (Restaurant at SF only) Provided MR Fire check door Required Sealing of electrical shafts Provided Required MR Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers Provided Required MR 4. Smoke Management System (Restaurant at SF only) Provided Required MR Basements Upper floors Required Provided MR 5. Fire Extinguishers Total numbers in restaurant 04 no.'s Provided M/R ABC/CO2 Provided M/R Types ISI marked IS marking Provided M/R

2

6.	First-Aid Hose Reels	(Common with	MLCP cum commer	cial complex)	
7.	Total numbers for restaurant	3 Nos.	Provided	M/R	
	 Length of hose reel hose 	30 mtrs	Provided	M/R	
	Nozzle diameter	5 mm	Provided	M/R	
	Automatic fire detection and alarming system in restaurant (Restaurant at SF only				
	Type of detectors Smoke/Heat	Heat & smoke	provided	MR	
	Location of Main Panel	Required	provided	MR	
	Location of Repeater Panel	GF	provided	MR	
	Alternate source of power	Required	provided	MR	
	Hooters' Location	Required	provided	MR	
	MOEFA with talk back system	Required	provided	MR	
	Public Address System	Required	provided	MR	
0.	Automatic Sprinkler System		(Restaurant at S	F only)	
	Basement	Required	provided	MR	
	Ground Floor at restaurant	Required	provided	MR	
	Sprinkler above false ceiling	Required	provided	MR	
1.	Internal Hydrants				
	Size of riser/down-comer	150/100 MM	provided	MR	
	Number of hydrants	Three	provided	MR	
	Hose Box	Three	provided	MR	
2.	Yard Hydrants		For entire buildi	ng	
	Total number of hydrants Hose Box	Required	Provided	M/R	
		Required	Provided	M/R	
13.	Pumping Arrangements		For entire build	ing	
	Ground Level				
	Discharge of main Pump	2850 LPM	Provided	M/R	
	> Head of Main pump	90 mtrs	Provided	M/R	
	Number of main pumpsJockey Pump out put	two	Provided	M/R	
	> Jockey pump head	280 LPM	Provided	M/R	
	, come y pamp man	90 mtrs	Provided	M/R	
	Standby Pump out put	2850 LPM	Provided	M/R	
	Standby Pump Head	90 mtrs	Provided	M/R	
	Water curtain PumpAuto Starting/Manual Stopping	Required	Provided	M/R	
	Auto Starting/Manual Stopping	Required	Provided	M/R	
		Required	Provided	M/R	
		required	1101100		
	Pump House Access Terrace level	900 lpm	Provided	M/R	
	Discharge of pump	40 m	Provided	M/R	
	Head of the pump		Provided	M/R	
	Power SupplyAuto Starting of pump	Required			
	Tuto outring of pump	Required	Provided	M/R	
14.	Captive Water Storage for fire fighting	(Common with	MLCP cum comme	rcial complex)	
	Underground tank capacity for entire bldg.	2,00,000 ltrs	Provided	M/R	
	Draw-off connection	Required	Provided	M/R	
	Fire service inlet	Required	. Provided	M/R	
	Access to tank	Required	Provided	M/R	
	Overhead Tank capacity	20000 ltrs	Provided	M/R	

15,	Exit Signage.					
16.		Required	Provided	MR		
10.	Provision of Lifts					
	Pressurization of Lift Shaft Pressurization of Lift Islands	Required	Provided	MR		
	Litt 1000y	Required	Provided	MR		
	Communication in int Car	Required	Provided	MR		
100	Fireman's Grounding SwitchLift Signage	Required	Provided	MR		
	Diff Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	M/R		
18.	Refuge Area.					
	Total AreaLocation	N/A	N/A	N/A		
		N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System PanelFlow Switch Panel	Required	Provided	MR		
	• PA System Panel	Required	Provided	MR		
	Battery backup	Required	Provided	MR		
	Building Floor Plans	Required	Provided	MR		
		Required	Provided	MR		
20.	Special Fire Protection System for Protection of special Risks, if any:	Required co2 Flooding in LT & HT Panel	Provided	MR		

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

Keeping in view of the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

The FSC was issued vide letter no. F.6/DFS/MS/PRKG/2019/SZ/173 dated 24.01.19 (for MLCP cum Commercial Complex)

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

D.O.(South West)

Dy. cho/(52)

The doer Size is 12 mer et 2001 on station then is only one station control of the let.