

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/2021/ 605

Dated : 02.12.2021

FIRE SAFETY CERTIFICATE

Certified that the **Constitution Club of India** located at **Rafi Marg, New Delhi** comprised of **Ground + 02 Upper floors**, presently running at ground & first floor was earlier granted FSC vide letter No. F6/DFS/MS/2018/NDZ/577 dated 04.04.2018. Now, the premises was re-inspection by the officers concerned of this department on dated 29.11.2021 in presence of Sh. Manoj Kumar, JE and the **club is running at ground and first floor whereas second floor is under renovation**, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and found the premises is fit for occupancy class **Assembly Building Group D at Ground & first floor only** with effect from 02.12.21...for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued...02.12.2021.....at New Delhi by.



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.
2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Ref. ID 2021021910594 dated 02.04.21 and 2021031911426 dated 22.03.21.
3. The Director/ Manager (Admin), Constitution Club of India at Vithal Bhai Patel House, Rafi Marg, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid only for ground and first floor.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

INSPECTION REPORT

1. Name & address of the building : **Constitution Club of India, New Delhi**
2. Type of occupancy : **Assembly Building Gr. + 02 upper floor**
Presently is running at ground & first floor and second floor under renovation.
3. Type of case:- : **Renewal**
4. Details of previous NOC : **F6/DFS/MS/2018/NDZ/577 dated 04.04.2018**
5. Fire safety directives No. : **F6/DFS/MS/BP/2006/1308 dated 12.06.2006**
6. Date of inspection:- : **29.11.2021**
7. Name of the inspecting officer : **Sh. Rajinder Atwal DO/CD & Sh. Ravinder Singh ADO/CC**
8. Name & designation of officer From the building side : **Sh. Manoj Kumar JE (E)**
9. Year of construction : **2006**
10. Applicant's letter No : **ID No 2021021910594 dated 02.04.21 and 2021031911426 dated 22.03.21 & letter No AE-2/Delhi Electric Division-102/20201-22/208 dated 18.11.2021.**

Old Case

S.No.	Minimum Standards on fire Prevention and fire safety U/R- 33	Requirements/ex isting fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	09 mtr.	36.5 Mtr.	MR
	2) Gate width	05mtr.	05 mtr.	MR
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	03 Nos.	03Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.50 mtr.	1.50 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	NA	NA	NA
	2. Pressurization	NA	NA	NA
	D. No. of continuous staircase to terrace	01 Nos.	01 Nos.	MR
	E. Width of corridor	NA	NA	NA
	F. Door size	01 mtr.	01mtr.	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	NA	NA	NA
	4) Water curtain	NA	NA	NA
	5) Fire Dampers	NA	NA	NA
4.	Smoke Management System			
	1) Basements	NA	NA	NA
	2) Upper floors	12 ACPH	Natural	MR
5.	Fire Extinguishers			
	1) Total numbers	14nos	14nos	MR
	2) Types	ABC, CO2	ABC, CO2	MR
	3) ISI marking	Required	Provided	MR

6.	First-Aid Hose Reel			
	1) Total number at each floor	02	02	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	5 mm	5 mm	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	Ground	Provided	MR
	3) Location of repeater panel	NA	NA	NA
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	At each floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	NA	NA	NA
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false ceiling	NA	NA	NA
11.	Internal Hydrants			
	1) Size of riser/down-comer	150 MM	150 MM	MR
	2) Number of hydrants per floor	02	02	MR
	3) Hose box each floor	02	02	MR
12.	Yard Hydrants			
	1) Total number of hydrants	03nos	03nos	MR
	2) Hose box	03nos	03nos	MR
13.	Pumping Arrangement		Pumps are provided at the terrace of high rise residential block with boosting arrangement of 450 LPM at ground level to replenish the OHT.	
	1) Ground level			
	a) Discharge of main pump	450lpm	provided	MR
	b) Head of main pump	45 mtr.	405mtr.	MR
	c) Number of main pump	01	01	MR
	d) Jockey pump out put	NA	NA	NA
	e) Jockey pump head at terrace level	NA	NA	NA
	f) Stand by pump output	NA	NA	NA
	g) Stand by pump head	NA	NA	NA
	h) Auto starting/Manual stopping	Required	provided	MR
	2) Terrace level			
	a) Discharge of pump	2280 LPM	2280 LPM	MR
	b) Head of pump	70 mtr.	70 mtr.	MR
	c) Jockey pump out put at terrace level	180 LPM	220 LPM	MR
	d) Jockey pump head at terrace level	70 mtr.	70 mtr.	MR
	e) Power supply	Required	provided	MR
	f) Auto starting of pump	Required	provided	MR

	1) Under ground tank with replenish arrangements for OHT	50,000 ltr.	50,000 ltr.	MR
	a) Draw-off connection	NA	NA	NA
	b) Fire service inlet	NA	NA	NA
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	20,000 ltr.	20,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	NA	NA	NA
	Total area location	NA	NA	NA
19.	Fire Control Room			
	a) Detector system panel	NA	NA	NA
	b) Flow switch panel	NA	NA	NA
	c) PA system panel	NA	NA	NA
	d) Battery backup	NA	NA	NA
	e) Building floor plan	NA	NA	NA
20.	Special Fire Protection System for Protection of special Risk, if any:			MR

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. Further, underground tank and pump room for the entire complex is under renovation.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the DFS Rules 2010, we may renew the FSC issued vide letter No. F6/DFS/MS/2018/NDZ/577 dated 04.04.2018, under rule 35 of the Delhi Fire Service Rules 2010,. Accordingly, reply letter is prepared and put up for kind perusal and approval please.

Signature of the Inspecting Officer

Rajinder Atwal
11/12/21

Name :- Rajinder Atwal
Designation :- DO (CD)

Signature of the Inspecting Officer

Ravinder Singh
11/12/21

Name :- Ravinder Singh
Designation :- ADO (CC)



Syeds Amir

Rajinder Atwal
11/12/21

A-DO (CC)

As suggested for perusal and signature please.

Rajinder Atwal
11/12/21