

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6 DFS/MS/School/2021/SZ/ 1043

Dated: <u>91</u> / <u>19</u> / 2021

(-16

FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary Co-ed School, located at Asola New Delhi -110074 comprised of ground plus One upper floor was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2018/SZ/2704 Dt. 14/12/2018. The said premises was re-inspected by officer concerned of this department on 10-12-2021 in presence of Mrs. Sudha Sharma (Principal) of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class "Educational Building Group – B" with effect from 21 / 12 / 2021 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on $\frac{21}{12}$ 2021 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. The Principal, S.D.M.C Primary Co-ed School, located at Asola New Delhi -110074.
- The Directorate of Education, South MCD, Civic Centre, Minto Road, New Delhi-110002. 2.

Conditions for the validity of Fire Safety Certificate:-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 6. 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECT	ION REPORT				
1	Name & Address of the Building	and the second state and a second state of the	ry Co-ed School, Asola	New Dell		
2 Type of Occupancy Educational Group-B (School)						
3	Building Comprised of	Ground plus One Upper Floor Renewal				
4	Type of Case					
5	Details of Previous NOC	tails of Previous NOC F6/DFS/MS/School/2018/SZ/2704 Dt. 14/12/2018				
6	Fire Safety Directives Letter No	F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011				
7	Date of Inspection 10-12-2021					
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP) Mrs. Sudha Sharma (Principal)				
9	Name & Designation of Officers					
	from the building side					
10	Year of construction	2004				
11	Applicant letter No.	Nil Dated 28/09/2021				
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remark		
	and Fire Safety U/R 33	Requirement		MR/NM		
1	Access to Building.					
	Road width	06 mtr	06 mtr	MR		
	Gate width	04 mtr	04 mtr	MR		
	 Width of internal road 	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	Upper floors.	02 No's	02 Nos	MR		
	Basement floor.	-NA-	-NA-	-NA-		
	b) Width of Staircase			-14A-		
	Upper floors	1.50 m/ 0.75 m	1.77 mtr & 1.62 mtr	MR		
	Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits			=INA=		
	Fire check door	-NA-	-NA-	NI.		
	Pressurization	-NA-		-NA-		
	d) No. of continuous staircase to terrace		-NA-	-NA-		
	e) Width of corridor	01 Nos	Provided	MR		
	f) Door size	1.5 mtr	2.11 mtr Provided	MR		
3	Compartmentation.	1 mtr	Provided	MR		
	P					
	Fire check door.	-NA-		1		
	 Sealing of electrical shafts. 	-NA-	-NA-	-NA-		
	 Fire rating of shaft door. 	-NA-	-NA-	-NA-		
	 Water curtain 	-NA-	-NA-	-NA-		
	 Fire dampers. 		-NA-	-NA-		
4.	Smoke Management system.	-NA-	-NA-	-NA-		
	Basement					
	Upper floors	-NA-	-NA-	-NA-		
5.	Fire Extinguishers.	-NA-	-NA-	-NA-		
	Total numbers	07.0	-			
		07 Required	07 Nos	MR		
	• Types	ABC	ABC & Co2 Type	MR		
	ISI Marking	ISI mark				
6		ISI IIIdi K	Provided	MR		
6.	First Aid Hose Reels.					
	 Total numbers on each floor. 	-NA-	-NA-	NT A		
	 Length of hose-reel hose. 	-NA-	-NA-	-NA-		
	Nozzle Diameter	-NA-		-NA-		
7	Automatic fire detection & alarming system.	-11/1-	-NA-	-NA-		
·	 Type of detectors 					
		-NA-	-NA-			

N 20

N 21

				γ
	Location of Main Panel	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	 Alternate source of power 	-NA-	-NA-	-NA-
	 Hooter's location 	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9,	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	 Upper floors 	-NA-	-NA-	-NA-
	 Sprinkler above false ceiling 	-NA-	-NA-	-NA-
11.	Internal Hydrants.			
	 Size of Riser/Down-comer 	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			
	 Total number of hydrants. 	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			
	Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.			
	 Underground tank capacity. 	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	 Overhead tank capacity. 	-NA-	-NA-	-NA-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	 Communication in lift car. 	-NA-	-NA-	-NA-
				-NA-
		-NA-	-N A -	
	• Fireman's switch.	-NA-	-NA-	
15	Fireman's switch.Lift signage.	-NA-	-NA-	-NA-
17.	 Fireman's switch. Lift signage. Standby Power Supply 			
17. 18.	 Fireman's switch. Lift signage. Standby Power Supply Refuge Area 	-NA- -NA-	-NA- -NA-	-NA- -NA-
	 Fireman's switch. Lift signage. Standby Power Supply 	-NA-	-NA-	-NA-
	 Fireman's switch. Lift signage. Standby Power Supply Refuge Area 	-NA- -NA-	-NA- -NA-	-NA- -NA-
18.	 Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location 	-NA- -NA-	-NA- -NA- -NA-	-NA- -NA- -NA-
	 Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location Fire Control Room.	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-
18.	 Fireman's switch. Lift signage. Standby Power Supply Refuge Area Total area Location 	-NA- -NA-	-NA- -NA- -NA-	-NA- -NA- -NA-

- - ^

foun

nd >

-



20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-
	 Building floor plan. 	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	 PA system panel. 	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/School/2018/SZ/2704 Dt. 14/12/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

DO (SØ

Defolso the for your approved, F.T. Letter in mature PI Ally TTI2 Dy cfo/152