GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE Dated: 21 /1/22 **NEW DELHI- 110001**

No.F.6/DFS/MS/EH/2022/SZ/ 09

FIRE SAFETY CERTIFICATE

Certified that the M/s Burger King restaurant running at ground floor only in a building comprised of basement, ground plus three upper floors located at Shop no.554, G.F. Shivaji Marg, TudaMandi, Najafgarh Main Road, New Delhi-110043, owned/occupied by Burger King India Limited have complied with the fire prevention and fire safety requirements in accordance with the rule 33 of the Delhi Fire Service Rule 2010 and verified by the officer concerned of this department on 14/01/2022 in the presence of Sh. Krishan Kumar Jain and found that the building is fit for occupancy 'Class D "Assembly Building" (Restaurant) ' for with effect from 2.11.1.1.22... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Delhi Fire Service

To,

M/s Burger King (A unit of Burger King India Limited), 554, G.F. Shivaji Marg, TudaMandi, Najafgarh Main Road, New Delhi-110043.

Copy to:-

The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station, Defence Colony, New Delhi.

Following fire safety directives must be adhered to:-

- This NOC is valid only for ground floor.
- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building

: M/s Burger King restaurant (Burger King India

Limited), Shop no. 554, G.F. Shivaji Marg, Tuda Mandi,

Najafgarh Main Road, New Delhi-110043.

Building is comprised of 2.

: B,G+3 floors But Burger king running at Gr. floor only

3. Type of Occupancy

: Assembly (Eating)

4. Type of Case : New

: Nil

Details of Previous NOC letter

Fire Safety direction letter No

: NBC Part-IV

Date of Inspection

: 14/01/2022

8. Name of the Inspecting officers

: ADO R.K. Yadav

9. Name and designation of Officer

from the building side

: Sh. Krishan Kumar Jain

10. Year of Construction

: 2020

11. Applicant's letter No.

Appli	cant's letter No : II	O No. 2022010800	455 Dated 08/01/2022					
Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	NBC Part-IV Requirement	Provided at Site	Remarks MR/NMI				
01	Access to Building.							
	Road width	06 m	Provided.	MR				
	Gate width	N/A	N/A	N/A				
	 Width of internal road 	N/A	N/A	N/A				
02 .	Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases							
	Upper floor	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	B. Width of Staircases							
	Upper floor	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	c. Protection of Exits							
	 Fire check door 	Required	Provided	MR				
	 Pressurization 	N/A	N/A	N/A				
	d. No. of Continuous Staircases to Terrace	N/A	N/A	N/A				
ŀ	e. Width of Corridor	N/A	N/A	N/A				
ŀ	f. Door Size	2X 1.5 m each	2 x 1.5 m & 1 No. of 2 m	MR				
03	Compartmentation.							
	Fire check door	Required	Provided	MR				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	• Fire rating of shaft door	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	• Fire dampers	N/A	N/A	N/A				
04	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	N/A	N/A	N/A				
05.	Fire Extinguishers.							
	Total numbers	04 nos.	04nos.	MR				
	Total numbersTypes	ABC /CO ₂	Provided	MR				
- 1	• Types	ISI marked	Provided	MR				

06	First-Aid-Hose Reels.						
	Total numbers on each floor	01 No.	Provided	MR			
	• Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	05 mm	Provided	MR			
07	Automatic Fire Detection and Alarming System.						
	Suraka Provid I						
	• Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
00	Hooter's location	Required	Provided	MR			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.						
10	Automatic Sprinkler System. N/A N/A N/A N/A						
	Basement	N/A	N/A	N/A			
	 upper floor 	N/A	N/A N/A	N/A N/A			
	 sprinkler above false ceiling 	N/A	N/A	IN/A			
11	Internal Hydrants			1			
	size of riser/down-comer	100 MM	Provided	MR			
	 Number of hydrants per floor 	01 No.	Provided	MR			
	Hose box	01 No.	Provided	MR			
12	Yard Hydrants.						
		N/A	N/A	N/A			
	Total number of hydrantsHose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	* 1	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Jockey pump head Standbar grown out put	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	Pump house access Terrace Level	IVA	IVA	1 1/71			
		450 Lpm.	Provided	MR			
	Discharge of pump	40 M	Provided	MR			
	Head of the pump	Required	Provided	MR			
	Power supply		Provided	MR			
1.4	Auto starting of pump Continue Water Starting for Fire Fighting	Required	Provided	IVIIC			
14	Captive Water Storage for Fire Fighting.	27/4	NT/A	NI/A			
	Underground tank capacity	N/A	N/A	N/A N/A			
	Draw-off connection	N/A	N/A				
	 Fire service inlet 	N/A	N/A	N/A			
	 Access to tank 	N/A	N/A	N/A			
	 Overhead tank capacity 	20,000 Ltrs.	20,000 Ltrs	MR			
15	Exit Signage.						
16	Provision of Lifts.						
	Pressurization of lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	1 ICSSULIZATION OF THE TORRY			N/A			
		N/A	N/A	1 17/7			
	 Communication in lift car Firemen's grounding switch 	N/A N/A	N/A N/A	N/A			

17 Standby Power Supply	Required	Provided	MR			
18 Refuge Area.						
Total area	N/A	N/A	N/A			
• Location	N/A	N/A	N/A			
19 Fire Control Room						
Detector system panel	N/A	N/A	N/A			
Flow switch panel	N/A	N/A	N/A			
PA system panel	N/A	N/A	N/A			
Battery backup	N/A	N/A	N/A			
Building floor Plans	N/A	N/A	N/A			
20 Special Fire Protection Systems for	N/A	N/A	N/A			
Protection of Special Risks, if any:						

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

The total covered area of the eating house at GF is 179 sq. meters. As per Part-IV, NBC-2016, Total the number of persons will come Approx. 99 (179 /1.8= 99.44 i.e. 99) for the restaurant.

Signature of the Inspecting Office Name:-R.K.Yadav Designation:-ADO (JKP)

DO (South West)

Dy cho /22,

F.O. D

));X2 (/ S)

20/01/1022

P.T.