C-28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/WZ/2022/ 97

Dated: 01/2/2

FIRE SAFETY CERTIFICATE

Issued on Ol/2/22 at New Delhi by

DIRECTOR Ph; 011-23414000

of c

Copy to:

- 1. The Principal, Govt. Boys Sr. Sec. School, Prashant Vihar, Delhi-110085.
- 2. The Director of Education, GNCT of Delhi Old Secretariat, Delhi-110054 Conditions for validity of Fire Safety Certificate;
- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form "K" is available on

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: Govt. Boys Sr. Sec. School, Prashant Vihar, Delhi-110085. : Educational (Ground + 3 upper floors) (School ID-1413016)

2. Type of Occupancy

3. Type of Case 4. Details of Previous NOC : NA

5. Fire Safety directives letter No : NBC Part-IV : 17.01.2022 6. Date of inspection

: A.K.Sharma ADO(Rohini) 7. Name of Inspecting Officer

8. Name and designation of officers

: Sh. Vinit Goel (Electrician) From the building side

: 2021 9. Year of Construction

S. No.		Standards on fire prevention	NBC	Provided at site	Remarks MR/NMR			
		fety U/R 33	Requirement					
1.	• Road width		6.0m	9.0m	MR			
			4.5m`	6m	MR			
		e width	NA NA	NA	NA			
		Ith of internal road		1112				
2		Number, Width, Type & Arrangement of Exits a. Number of staircases						
			03	04 + 01 ramp	MR			
		per Floors		NA	NA			
		ements	NA	NA	1471			
	b. Width of	fstaircases	1.5	1.00 0. 1.00	MR			
	• Upp	per Floor	1.5m	1.60m & 1.80m ramp				
	• Bas	ements	NA	NA	NA			
	c. Protection	on of exits						
	Fire chec	ck door	NA	NA	NA			
	• Pres	ssurization	NA	NA	NA			
	d. No. of o	continuous staircases to terrace	04	04	MR			
	e. Width o	of Corridor	1.5m	1.8m	MR			
	f. Door S		NA	NA	NA			
3.	Compartm	Compartmentation						
	-	check door	NA	NA	NA			
	1	ling of electrical shafts	NA	NA	NA NA			
	1	Rating of shaft door	NA	NA				
		ter Curtain			NA			
	• Fire	Dampers	NA NA	NA NA	NA NA			
4.		Smoke Management System						
	+	ements	20 -/ 1	274				
			30 a/c per hour	NA	NA			
		per floors	12 a/c per hour	Natural ventilation	MR			
5.	Fire Extinguishers							
		al numbers	60nos.	120nos.	MR			
	• Typ		ABC/CO2	ABC-60/CO2-60	MR			
		narking	ISI marked	Yes	MR			
6.	First-Aid Hose Reels							
		al numbers on each floor	04	Provided	MR			
		gth of hose reel hose	30mm	Provided	MR			
7.		zle diameter	5m	Provided	MR			
7.	Automatic fire detection and alarming system							
		e of detectors	NA	NA	NA			
		ation of Main Panel ation of Repeater Panel	NA	NA	NA			
	Alte	ernate source of power	NA	NA	NA			
		oters' Location	NA	NA	NA			
	1100	Location Location	NA	NA	NA			

				274			
8.	MOEFA	NA	NA	NA NA			
9.	Public Address System	NA	NA	INA			
10.	Automatic Sprinkler System			NA			
	Basement	NA	NA	NA			
	 Ground & Upper Floors 	NA	NA				
	Sprinkler above false ceiling	NA	NA	NA			
11.	Internal Hydrants			27.4			
	Size of riser/down-comer	NA	NA	NA			
	 Number of hydrants per floor 	NA	NA	NA			
	Hose Box	NA	NA	NA			
12.	Yard Hydrants						
	Total number of hydrants	NA	NA	NA			
	Hose Box	NA	NA	NA			
13.	Pumping Arrangements						
	Ground Level	NA	NA	NA			
	Discharge of main Pump	NA	NA	NA			
	➤ Head of Main pump	NA	NA	NA			
	> Number of main pumps	NA	NA	NA			
	> Jockey Pump out put	NA	NA	NA			
	> Jockey rump but put > Jockey pump head	NA	NA	NA			
	Standby Pump out put	NA	NA	NA			
	> Standby Pump Head	NA NA	NA NA	NA NA			
	> Auto Starting/Manual Stopping	NA	NA	NA			
	> Pump House Access	NA	NA	NA			
	Terrace level						
	Discharge of pump	450lpm	2 x 450lpm	MR			
	Head of the pump	40m	Provided	MR			
	Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	NA	NA	NA			
	Draw-off connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			
	Access to tank	NA	NA NA	NA			
	Overhead Tank capacity	10,000ltr	15,000ltr				
5.	Exit Signage.	Required	Provided	MR MR			
6.	Provision of Lifts.	resquired	Tiovided	IVIK			
	Pressurization of Lift Shaft Pressurization of Lift labbur	NA NA	NA	NA			
	Pressurization of Lift lobby Communication In lift Car	NA NA	NA NA	NA			
	Communication in fitt car		NA	NA			
	i noman s Grounding Switch	NA	NA	NA			
	211 218111180	NA	NA	NA			
7.	Standby power supply	Required	Provided	MR			
8.	Refuge Area.			1.11			
	> Total Area	NA	NA	NT A			
	> Location	NA	NA NA	NA NA			
19.	Fire Control Room						
	Detector System Panel	NA	NIA				
	Flow Switch Panel	NA NA	NA NA	NA			
	PA System Panel	NA NA	NA NA	NA			
	Battery backup	NA NA	NA	NA			
	Building Floor Plans	NA NA	NA	NA			
	Special Fire Protection System for		NA	NA			
20.	Special Fire Frotection System for	NA	NA	NA			

S

. The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer Name Ajay Kumar Sharma Designation ADO(Rohini)

DO NW) 25/01/2020

27/1/202

27/1/21

Agril 22/1

2021

Any Repue

FT letter is put up for Kind perusal and agreeting please.

Director hul 19000