GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/Banquet/WZ/\

## Dated: 17 03 202L

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Dee Pearls Banquet Hall located at 2nd floor, D Mall, Sector-10, Rohini, Delhi, is running in a mall at 2<sup>nd</sup> floor comprised of Three Tiered Basement, Ground + Five upper floors has already been issued FSC by this department vide letter No. F.6/DFS/Ms/2018/977 dated 09.05.2018. The premises was re-inspected by the officer concerned of this department on 10.03.2022 in the presence of Mr. Ravinder Kumar (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Class-Sub Div. D-5 (Assembly Building) for Banquet hall is running at in a mall 2<sup>nd</sup> floor with effect from 17 03 2022 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... | 3 2027 at New Delhi by

Conditions for the validity of fire safety certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency and this fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.

5. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

6. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

7. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

	200			1				
		1. Name &	address of the bound	ON REPORT				
		- Lane o	address of the building: Dee Pearls B	sanquet Hall, 2 <sup>nd</sup> floor,	D Mall, Sector-10	, Rohini,		
	2. Type of Occupancy							
		3. Type of	Type of Case Assembly Building (Banquet Hall)					
	5. Fire Safety directives letter No. :(F.6/DFS/Ms/2018/977 dated 09.05.2018					<b>(r</b> )		
						SC)		
7 Name of Inspection : 10.03.2022								
		3. Name at	Inspecting Officer : A. K. Sharma, ADO (Rohini) & D.B Mukherjee, DO (NW) ad designation of officers					
		From the		Yr (3.7				
	9	9. Year of		Kumar (Manager)				
	10. Applicant's letter No. Online application No. 2022022702703 dated 01 03 2022					122		
	S.	Minimur	n Standards on fire prevention and	NBC	Provided at	Remarks		
	No.	fire safet	y U/R 33	Requirement	site	MR/NMR		
	1.	Access to	building(Twin District Centre, D Mal	Sector-10 Robini iss	ued FSC vide lette	er		
		Access to building(Twin District Centre, D Mall, Sector-10, Rohini issued FSC vide letter No.F.6/DFS/MS/2021/WZ/420 dated 27.08.2021)						
		• R	ad width	Accessible	Accessible	MR		
	,	• G	ate width	Accessible	Accessible	MR		
		• W	idth of internal road	NA	NA	NA		
	2.	Number.	Width, Type & Arrangement of Evit		INA	1471		
2. Number, Width, Type & Arrangement of Exits a. Number of staircases								
			pper Floors	Banquet within mal	l As Above	MR		
			asements	Banquet within mal		MR		
			of staircases	Banquet within mai	As Above	MIK		
			pper Floor	Banquet within mal	l As Above	MR		
			asements					
			on of exits	Banquet within mal	l As Above	MR		
			eck door	D (11)				
			ressurization	Banquet within mal		MR		
			continuous staircases to terrace	Banquet within mal Banquet within mal		MR		
			of Corridor	Banquet within mal		MR MR		
		f. Door	Size	Required	Provided	MR		
	3.	Comparti	nentation[Provided & Maintained by M		Tiovided	MK		
		Picture 1						
			aling of electrical shafts	Banquet within mal		MR		
			e Rating of shaft door	Banquet within mal		MR		
7			ter Curtain			MR		
			e Dampers	Banquet within mal		MR		
-	4.		anagement System[Provided & Mainta	Banquet within mal	l As Above	MR		
-		• Bas	sements					
-				Banquet within ma		MR		
L			per floors	Banquet within ma	ll As Above	MR		
15	5.	Fire Extin						
			al numbers	20nos.	20nos.	MR		
		• Typ		ABC/CO2	ABC/CO2	MR		
			marking	ISI marked	Yes	MR		
6	•	First-Aid I				1711(		
		• Tota	al numbers on each floor	02	As Above	MR		
		• Len	gth of hose reel hose	30mm	As Above	MR		
			zle diameter	5m	A - A1			
7.		Automatic	fire detection and alarming system[F	Provided & Maintaina	d by Mall ====	MR		
		Typ	e of detectors	Banquet within ma				
		• Loca	ation of Main Panel		1 - 2 1 1 2 0 7 0	MR		
			ation of Repeater Panel	Banquet within ma		MR		
				Banquet within ma	ll As Above	MR		
3.70				The state of the s				

	A 1.		T . 41		MR
	Alternate source of power	Banquet within mall	As Abo		MR
8.	Hooters' Location	Banquet within mall	As Abo		MR
	MOEFA	Required	Provid		MR
9.	Public Address System	Restaurant within mall	As Abo	ve	14114
10.	Automatic Sprinkler System[Provided & Maint		MR		
	<ul> <li>Basement</li> </ul>	Banquet within mall	As Abo		MR
	<ul> <li>Ground &amp; Upper Floors</li> </ul>	Banquet within mall	As Abo	_	MR
	<ul> <li>Sprinkler above false ceiling</li> </ul>	Banquet within mall	As Abo	ve	IVIK
11.	Internal Hydrants[Provided & Maintained by M	[all management]			) (D
	Size of riser/down-comer	100mm	As Abo		MR
	Number of hydrants per floor	One(near to Banquet)	As Abo	_	MR
	Hose Box	One(near to Banquet)	As Abo	ve	MR
12.	Yard Hydrants[Provided & Maintained by Mall	management]			) (D
	Total number of hydrants	Restaurant within mall	As Abo	_	MR
	Hose Box	Restaurant within mall	As Abo	ve	MR
13.	Pumping Arrangements[Provided & Maintained	d by Mall management]			
	Ground Level				) (D
	<ul><li>Discharge of main Pump</li></ul>	Banquet within mall	As Abo	_	MR MR
	➤ Head of Main pump	Banquet within mall	As Abo		
	> Number of main pumps	Banquet within mall	As Abo	_	MR MR
	> Jockey Pump out put	Banquet within mall	As Abo	_	
	> Jockey pump head	Banquet within mall	As Abo		MR
	Standby Pump out put	Banquet within mall	As Abo	-	MR
	Standby Pump Head	Banquet within mall	As Abo	-	MR
	Auto Starting/Manual Stopping	Banquet within mall	As Abo		MR
	> Pump House Access	Banquet within mall	As Abo	ve	MR
	Terrace level		4 41		MR
	Discharge of pump	NA	As Abo		MR
	Head of the pump	NA	As Abo		MR
	> Power Supply	Required	As Abo	-	MR
	> Auto Starting of pump	Required	As Abo		IVIIC
14.	Captive Water Storage for fire fighting [Providence]	iiij	MR		
	Underground tank capacity	Banquet within mail	AS Abo	YC	
	> Draw-off connection	Banquet within mall	As Abo	1	MR
	Fire service inlet	Banquet within mall	As Abo	-	MR
	> Access to tank	Banquet within mall	As Abo	-	MR
	Overhead Tank capacity	Banquet within mall	As Abo	-	MR
15.	Evit Signage.	Required	Provide	0	MR
16.	Provision of Lifts. [Provided & Maintained by				
	Pressurization of Lift Shaft	Banquet within mall	As Abo		MR
	Pressurization of Lift lobby	Banquet within mall	As Abo	ve	MR
	Communication In lift Car	Banquet within mall	As Abo	ve	MR
	Fireman's Grounding Switch	Banquet within mall	As Abo	ve	MR
	· ·	Banquet within mall	As Abo	ve	MR
17	Lift Signage  Stondby power supply	Required	As Abo	ve	MR
17. 18.	Standby power supply  Refuge Area. [Provided & Maintained by Mall m	1			
10.		NA	NA		NA
	<ul><li>Total Area</li><li>Location</li></ul>	NA	NA		NA
19.	Fire Control Room[Provided & Maintained by Mall management]				
19.		ve	MR		
	Detector System Panel     Flow Switch Panel	Banquet within mall Banquet within mall	As Abo	-	MR
	Flow Switch Panel	Banquet within mall	As Abo	-	MR
		Danquet within man	73 700	1	17114

n							
		A System Panel	Banquet within mall	As Above	MR		
	• B	attery backup uilding Floor Plans	Banquet within mall	As Above	MR		
20.	Special I of specia	ire Protection System for Protection   Risks, if any:	NA	Kitchen suppression system & gas	NA		
				detector found installed			

The fire protection systems provided in the building were test checked and found functional at the time of inspection. Note: The internal walls of corridor of the banquet hall are of soft partition.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules and the FSC to main occupancy building D-Mall already been issued vide letter No. F.6/DFS/MS/2021/WZ/420 dated 27.08.2021, if agreed, renewal of FSC issued to banquet hall vide letter no. F.6/DFS/Ms/2018/977 dated 09.05.2018 is recommended under rule 37 of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting Office Name: - D.B Mukherjee Designation:- DO/NW Signature of the Inspecting Officer Name: - Ajay Kumar Sharma Designation:- ADO/Rohini

Dyeto (wz)

19/18/2022

of cheminal

x1 79

The latter is the

is placed for signatures poleciese

Duector, NF3 11000000

ishoasel Whom