OVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/WZ/ Glass Jug 5
FIRE SAFETY CERTIFICATE

Certified that the Vidya Jain Public School, Sector-6, Rohini, Delhi-110085, comprised of Ground + 03 upper floors has already been issued FSC by this department vide letter No. F.6/DFS/MS/2018/2642 dated 07.12.2018. The premises was re-inspected by the officer concerned of this department on 25.04.2022 in the presence of Sh. Neeraj Kumar (Care Taker) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Educational "Group B" with effect from of los lost for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(Dhrampal Bhardwaj) Dy.Chief Fire Officer Tel;-01123414250

> 01 5 CM

Copy to :-

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi 54.
- 2. The Principal, Vidya Jain Public School, Sector-6, Rohini, Delhi-110085.

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner/occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1. Name & address of the building: Vidya Jain Public School, Sector-6, Rohini, Delhi-110085.

: Educational 2. Type of Occupancy

: Renewal (Ground + 03 upper floors) 3. Type of Case : F.6/DFS/MS/2018/2642 dated 07.12.2018 4. Details of Previous NOC

5. Fire Safety directives letter No : NBC Part-IV : 25.04.2022 6. Date of inspection

: A.K.Sharma ADO(Rohini) 7. Name of Inspecting Officer

8. Name and designation of officers

: Sh. Neeraj Kumar (Care Taker) From the building side

10 1	- liand	onstruction : 2004 's letter No. : Online e-mai	1 dated 12.03.2022. NBC	Provided at site	Remarks MR/NMR
No.	Minimu	m Standards on tire prevention	Requirement		1,225
	and fire	safety U/R 33		Accessible	MR
	Access	o building	Accessible	Accessible	MR
		Road width	4.5m	Accessible	NA
	• (Gate width	NA	NA	
	•	Width of internal road	Trite		
	Numbe	r, Width, Type & Arrangement of I	JARG		MR
	d. Num	ber of staircases	02	02	NA
	•	Upper Floors	NA	NA	IVA
	•	Basements) (D
	e Wid	th of staircases	1.5m	1.52m	MR
		Upper Floor		NA	NA
		Basements	NA	1.17.2	
	C Duct	ection of exits		NA	NA
		check door	NA	NA NA	NA
	Fire		NA	NA NA	NA
	•	Pressurization of continuous staircases to terrace	NA	2.54m	MR
	d. No	of continuous stancases to terrain	1.5m		MR
		idth of Corridor	1m	1m	17121
		oor Size			
3.	Compartmentation		NA	NA	NA
	•	Fire check door	NA	NA	NA
	•	Sealing of electrical shafts		NA	NA
	•	Fire Rating of shaft door	NA	NA	NA
	•	Water Curtain	NA	NA	NA
	•	Fire Dampers	NA	1471	
4.	Smoke Management System		30 a/c per hour	NA	NA
4.	• Office	T n			MR
		Upper floors	12 a/c per hour	Ivaturar ventriated	
	•			1 00	MR
5.	Fire	Extinguishers	18nos.	22nos.	MR
	•	_	ABC/CO2	ABC-18/CO2-4	
	•	Types	ISI marked	Yes	MR
	•	IS marking		D 111	MR
6.	Firs	Aid Hose Reels Total numbers on each floor	01	Provided	MR
	•	- 1 Classo real hose	30mm	Provided	
		ar 1 diameter	5m	Provided	MR
	Nozzle diameter Automatic fire detection and alarming sy		ystem	NT A	NA
7.	Aut	Type of detectors		NA	
		Location of Main Panel	NA	NA	NA
		Location of Repeater Panel	NA	NA	NA
		Alternate source of power	NA	NA	NA

20.

NA NA NA Special Fire Protection System for 20. Protection of special Risks, if any:

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 42 dated 01.02.2022, the FSC issued vide letter no. F.6/DFS/MS/2018/2642 dated 07.12 2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO (Rohini)

Plotumi

FT letter is put up for kind perusal and
signature pease.