GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/SZ/2022/ 279

Dated: 24/06/2022

Directo

Delhi Fire Service

.43

FIRE SAFETY CERTIFICATE

Certified that the **Padma Tower- II** located at Plot No. 22, Rajendra Place, New Delhi-110008, comprised of Basement, Lower Ground, Upper Ground plus eight upper floors was issued No Objection Certificate by this department vide letter No. F.6/DFS/MS/2015/1385 dated 26.06.2015 for occupancy of building and re-inspected by the officers concerned of this department on 14.06.2022 in presence of Mr. Chandeshwer (Manager) & S. Bhatia (Estate Manager), and found that the said business building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class **Group E (Business Building)** with effect from $\frac{2y/sl/ww}{2y/sl/ww}$ for a period of **03 (three)** years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on ______ s6/2022 at New Delhi by.

Copy to: -

- 1. Sh. Prem Kumar (Estate Manager), Padma Tower, 22, Rajendra Place, New Delhi- 08.
- 1. The Joint Director (Building) C&I, DDA, Building Section, DDA, Vikas Sadan, INA, New Delhi.

Following Fire Safety Directives Must Be Adhered To:-

- 1. Providing of fire safety measures does not give any guarantee that there will be No fire. These equipments/installation can minimize the losses if maintained in good working condition and handled efficiently in case of fire.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Name of the Inspecting Officers Name and designation of officers from the building side Year of Construction Applicant's letter No.	 Vedpal Chhikara, DO (SW) & P.V. Rathee, ADO (SRD) Mr. Chandeshwer (Manager) & S. Bhatia (Estate Manager) 1986-87 Nil dated 25.05.2022
Name and designation of officers from the building side	: Mr. Chandeshwer (Manager) & S. Bhatia (Estate Manager)
Name and designation of officers	
Name of the Inspecting Officers	: Vedpal Chhikara, DO (SW) & P.V. Rathee, ADO (SRD)
N 1 C.1 I	$\mathbf{P} = \mathbf{P} \mathbf{P} \mathbf{P} \mathbf{P} \mathbf{P} \mathbf{P} \mathbf{P} \mathbf{P}$
Date of inspection	: 14.06.2022
Fire Safety directives letter No	: F.6/DFS/MS/2015/86/1660 dated 10.11.1986
Details of previous NOC	: F.6/DFS/MS/2015/1385 dated 26.06.2015
	Plus Eight upper floors)
Type of Case	: Renewal (Basement, Lower Ground, Upper Ground
· · ·	: Business (Class- E)
	: Padma Tower- II, Plot No. 22, Rajendra Place, New Delhi-110008
	Fire Safety directives letter No Date of inspection

)

a

ti a ĭr 26 is à

1

State State

lo.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC requirement/ le dated 26.06.201	0	Remarks MR/NMR			
	Access to building						
	Road width	Accessible	12 Mtrs	MR			
	• Gate width	6 Mtrs.	06 Mtrs.	MR			
	• Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	-	-	-			
	Upper Floors	02	02 Nos.	MR			
	Basements	02	02 No.	MR			
	b. Width of staircases	-	-	-			
	Upper Floors	120 cms & 90 C	Cms 125 Cms & 90 Cms	MR			
	• Basements	120 cms & 90 C	ims 125 Cms & 90 Cms	MR			
	c. Protection of exits	-	-	-			
	• Fire check door	Required	Provided	MR			
	 Pressurization 	N/A	N/A	N/A			
	e. No. of continuous staircases	to 02	02	MR			
	terrade	1.25 mts	1.74 & 1.34 mts	MR			
	g. Width of Corridor h. Door Size	Old case	0.91 & 1.99 mts	MR			
3	Compartmentation.						
-	• Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Sealed	MR			
	• Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	• Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basements	30 a/c per hour	Exhaust fans are Provided	MR			
	Upper floors	N/A	Natural Ventilation	MR			
5	Fire Extinguishers						
	Total numbers	04 Nos. at each floc	Trovided	MR			
	• Types	WCO2 ABC & CO2 ty		MR			
	• IS marking	ISI marked	Provided	MR			
6	First-Aid Hose Reels.						
		3	br				

		N-42		1
	 Total numbers on each floor 	01	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	g system.		MIK
	Type of detectors	Smoke detector	Provided	MD
	 Location of Main Panel 	N/A	Lower Ground	MR
	 Location of Repeater Panel 	N/A	N/A	MR
	• Alternate source of power	Required	D.G set (125KVA)	N/A
	Hooters' Location	Required	Provided near staircase	MR
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.	required	Tiovided	MR
	Basement	Required	Provided	
	 Upper Floor/Ground Floor 	Required	Provided	MR
	 Sprinkler above false ceiling 			MR
1.1		N/A	N/A	N/A
11	Internal Hydrants			
	• Size of riser/down-comer	150 mm	150 MM	MR
	• Number of hydrants per floor	01	Provided	MR
12	Hose Box	Required	Provided	MR
12	Yard Hydrants.			
	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level			
	 Discharge of main Pump 	2250 LPM	Provided	MR
	 Head of Main pump 	60 M	60 M	MR
	Number of main pumps	02	02	MR
	 Jockey Pump out put 	900 LPM	900 LPM	MR
	Jockey pump head	45 M	45 M	MR
	Standby Pump out put	2250 LPM	2250 LPM	MR
	 Standby Pump Head 	60 M	60 M	MR
	 Auto Starting/ Manual 	Both	Both	MR
	stopping	Required	Provided	MR
	 Pump House Access 			
	Terrace level Discharge of nump	N/A	N/A	N/A
	Discharge of pumpHead of the pump	N/A	N/A	N/A
	 Pread of the pump Power Supply 	N/A	N/A	N/A
	 Auto Starting of pump 	N/A	N/A	N/A
14	Captive Water Storage for fire fightin			
	Underground tank capacity	2.00000 Ltrs	2,00000 Ltrs.	MR
	 Draw-off connection 	Required	Provided	MR
	 Fire service inlet 	Required	Provided	MR
	 Access to tank 	Required	Provided	MR
	Overhead Tank capacity	20000 Ltrs	20000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	•		
	Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car		Provided	MR
	• Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR

Refi

0

10

Ø

	Ctall	dby power supply	Required	Provided	MR
17	Stan	ge Arca.		- 26 MA	
118	,	Total Area	N/A	N/A	N/A
"T	>	Location	N/A	N/A	N/A
10	Fire	Control Room			
19	135	 Detector System Panel 	N/A	Provided	MR
		 Flow Switch Panel 	N/A	N/A	N/A
		 PA System Panel 	N/A	Provided	MR
		 Batter backup 	N/A	Provided	MR
		 Building Floor Plans 	N/A	N/A	N/A
20		al Fire Protection Systems for ction of special Risks, if any:	N/A	CO ₂ fire extinguisher provided near electric Panel	MR

The fire protection systems provided in the building were test checked at random and found satisfactory at the time of inspection.

Note:- All the shortcomings pointed out by this department vide letter No. F.6/DFS/MS/SZ/2021/1833 dated 10.09.2021 have been compiled by the building management.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, the NOC issued vide letter No. F.6/DFS/MS/2015/1385 dated 26.06.2015, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

DFA is put up for approval & signature please

> 18/6/22

Rol 1716 22

Signature of the Inspecting Officer Name- Vedpal Chhikara Divisional Officer (SW)

MR IR

R

Signature of the Inspecting Officer Name- P.V. Rathee Divisional Asstt. Div. Officer (S.Rd)

0 Gul duly to Mapur. OUNP 6 06