(-0

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2022/SZ/ 3 5

Dated: 04/7/2012

FIRE SAFETY CERTIFICATE

Certified that the Shiaan International School, A-Block, Jai Vihar, Najafgarh, New Delhi-110043, Comprised of ground plus two upper floors, owned/occupied by Shiaan International School have complied with the fire prevention and fire safety requirements in accordance with the Rules 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 20/06/2022 in the presence of Sh. Shish Deshwal (Chairman) and found that the school building is fit for occupancy class B 'Educational Building' for with effect from O.M. To Delhi for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on04 17 2022 at New Delhi by

(Aful Garg).
Director

Delhi Fire Service

Copy to:-

 The Principal, Shiaan International SchoolA-Block, Jai Vihar, Najafgarh, New Delhi-110043

2. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1. Name & address of the building

: Shiaan International School, A-Block, Jai Vihar, Najafgarh,

New Delhi-110043.

2. Building is comprised of

: G+2 upper floors.

3. Type of Occupancy

: Educational

4. Type of Case

: New Case

5. Details of Previous FSC letter

: Nil

6. Fire Safety direction letter No

: NBC Part-IV

7. Date of Inspection

: 20/05/2022

8. Name of the Inspecting officers

: ADO R.K. Yadav

9. Name and designation of Officer:

From the building side

: Sh. Shish Deshwal (Chairman)

10. Year of Construction

: 2021

11. Applicant's letter No.

: Nil dated 03/06/2022

S. N	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR			
1	Access to building						
	• Road width	06 m.	Provided	MR			
	• Gate width	N/A	N/A	N/A			
_	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	03 Nos.	03 Nos.	MR			
	Basement	N/A	N/A	N/A			
	B. Width of Staircases						
	Upper Floor	1.50 m each	1.60 m each	MR			
	Basement	N/A	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of continuous staircases	02 No.	02 No.	MR			
	to terrace e. Width of Corridor	1.5 m.	2.30 m.	MR			
	f. Door Size	1.20 m	2X1.20 m	MR			
	Compartmentation.						
	Fire check door	N/A	N/A				
	Sealing of electrical shafts			N/A			
	• Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Fire Dampers Smoke Management System	IN/A	N/A	N/A			
	Smoke Management System.						
	Dascincin	N/A	N/A	N/A			
_	• Upper floor Fire Extinguishers	Required	Natural Ventilation	MR			
5.	The Extinguishers						
	Total Halliocis	12 nos.	Provided	MR			
	• Types	ABC /CO ₂	ABC /CO ₂	MR			
	 IS marking 	IS I marked	ISI marked				
				MR			



6	First-aid-Hose Reels. Total numbers of each floor	02 Nos.	Provided	MR				
	Total numbers of each floor	30 m	Provided	MR				
	Length of hose reel hose	05mm	Provided	MR				
,	Nozzle diameter							
7	Type of detectors	N/A	N/A	N/A				
	 Type of detectors Location of main panel 	N/A	N/A	N/A				
	r C	N/A	N/A	N/A				
	Location of repeater panelAlternate source of power	N/A	N/A N/A N/A	N/A N/A N/A				
	**	N/A						
		N/A						
8	MOEFA	N/A	N/A	N/A				
9	Public address System. N/A N/A N/A Automatic Sprinkler System.							
10	Basement	N/A	N/A	N/A				
	- upper floor	N/A	N/A	N/A				
	upper floorsprinkler above false	N/A	N/A	N/A				
	• sprinkler above false ceiling	14/74	17/71					
11	Internal Hydrants							
	size of riser/down-comer	N/A	Provided	MR				
	Number of hydrants per floor	N/A	Provided	MR				
	Hose Box	N/A	Provided	MR				
12	Yard Hydrants.							
	Total number of hydrants	N/A	N/A	N/A				
	Hose Box	N/A	N/A	N/A				
13	Pumping Arrangements.							
	Ground Level							
	Discharge of main	N/A	N/A	N/A				
	Pump Head of Main Pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey pump out put	N/A	N/A	N/A				
	> Jockey pump bad > Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A	N/A				
	Standby pump Head	N/A	N/A	N/A				
	➤ Auto Starting /Manual	N/A	N/A	N/A				
	stopping > Pump House Access	N/A	N/A	N/A				
-	Terrace Level	14/71	13/12	11/11				
	Discharge of pump	450 LPM	4500 LPM	MR				
	Head of the Pump	40 M	Provided	MR				
	> Power supply	Required	Provided	MR				
-	> Auto Starting of pump	Required	Provided	MR				
14	Captive Water Storage for Fire	required	,	,,,,,				
	Fighting. • Underground tank	N/A	N/A	N/A				
	capacity							
	Draw-off connection	N/A	N/A	N/A				
	Fire service inlet	N/A	N/A	N/A				
	Access to tank	N/A	N/A	N/A				
	 Overhead Tank capacity 	10,000 Ltr.	10,000 Ltrs	MR				
15	Exit Signage.	Required	Provided	MR				



16	Provision of Lifts.	N/A	N/A	N/A			
	Pressurization of Lift Shaft			N/A			
	Pressurization of Lift lobby Communication in lift car Firemen's grounding switch	N/A	N/A				
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply						
18	Refuge Area.	N/A	N/A	N/A			
	Total area	N/A	N/A	N/A			
	• Location						
19	Fire Control Room	N/A	N/A	N/A			
	Detector system panel Flow switch panel PA system panel Battery backup		N/A	N/A			
		N/A N/A	N/A	N/A			
				N/A			
		N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection systems for	N/A	N/A	[N//A			
20	protection of special Risks, if any:						

The fire protection systems provided in the building were tested/checked at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety as required under the Rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name- R.K. Yadav

Designation- A.D.O(JKP)

DO(South West)

M 27/6/2022

Ozero (\$2)

28/6

Sincelly My

39/09-2

AM MP