



FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35] GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/SZ/2022/ 2/2

Dated: 25/7 /2022

1-41

FIRE SAFETY CERTIFICATE

Certified that the M/s Singh Sahib (Unit of Chef Bobby Foods Pvt. Ltd.) Located at T-1, T-2, T-3 & T-4, 3rd floor, Manish link road, Plaza II. Plot No. 10, Sector – 5, Dwarka, New Delhi, in a building comprised of Ground + 03 Upper Floors owned/ occupied By **M/s Singh Sahib** have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on 22/07/2022 in the presence of Sh. Anil Kumar and found that the said building that the premises is fit for occupancy class "Assembly" Group D (3rd Floor) with effect from 29/2/22 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 2.8.1.2.2. at New Delhi by.

Director Delhi Fire Service

Copy to:

- 1. The Joint Commissioner Police, Licensing, 1st Floor, PS, Defence Colony, N Delhi.
- M/s Singh Sahib (Unit of Chef Bobby Foods Pvt. Ltd.) Located at T-1, T-2, T-3 & T-4, 3rd floor, Manish link road, Plaza II. Plot No. 10, Sector – 5, Dwarka, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <u>www.dfs.delhigovt.nic.in</u>.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

الالتي	Re inspection to see the compliance of shortcomings communicated vide letter <u>dated 25/09/2019</u>
	INSPECTION REPORT
	 .Name & address of the building: M/s Singh Sahib (Unit of Chef Bobby Foods Pvt. Ltd.) Located at T-1, T-2, T-3 & T-4, 3rd floor, Manish link road, Plaza II. Plot No. 10, Sector – 5, Dwarka, New Delhi. Type of Occupancy : Class-D (Assembly)
	3 Type of C

11

3. Type of Case : New (At 3rd floor in a building comprised of G+3 UFs)

Chef Bobby Manish link

- 4. Details of previous NOC : Nil
- 5. Fire Safety directives L. No. BBL/NBC Part IV
- 6. Date of inspection : 22/07/2022
- 7. Name of the Inspecting Officer ; DO /SW & ADO (DWK)
- 8. Name and designation of Officer

from the building side : Sh. Anil Kumar

9. Year of Construction. 2002

10. Applicant's letter No. : Email dated 05/07/2022

S	Minimum standards on fire	UBBL/NB		Prov	ided at site	Rema		
No	prevention and fire safety U/R 33	Requireme	ents			MR/1	NMI	۲
1.	Access of building							
	 Road width 	12 mtrs		Prov	ided	MR		
	 Gate width Width of internal road 	4.5 mtr	Dir	ectly a	ccessible from	road	N	/IR
	• width of internal road	NA		NA		NA		
2.	Number, width, Type & Arrangemer	nts of exits						
	 a. Number of staircases 							
	 Upper floors 	02 Nos.		Prov	vided			MR
	 Basements 	NA		NA				NA
	b. Width of staircases							
	 Upper floors 	1.5 mtr	each		Provided	N	1R	
	 Basements 	NA		Provided		N	NA	
	c. Protection of exits							
	 Fire check door 	NA			NA		N	A
	 Pressurization 	NA			NA		N	A
	d. No of continuous staircase to terrace	01		Provided			MR	
	e. Width Of Corridor	NA			NA		NA	
	f. Door Size	1.5 mtr			Provided			R
3.	Compartmentation							
	 Fire check door 	NA			Provided		N	A
	 Sealing of electrical shafts 	NA			NA		N	A
	 Fire Rating of shaft door 	NA			NA		N	A
	Water Curtain	NA			NA		N	A
	 Fire Dampers 	NA			NA		N	A

P

4	Smake managements System	NIIG		1			1
•	Smoke managements System Basements	NA			NA		NA
	Upper floors	12 a/c p	ar ho	-	NA Exhaust far		MR
-		12 a/c p	er no	jur t	anaust fai	1	MR
5.	Fire Extinguishers						
	Total numbers	04 nos.	ABC		Provided		MR
	• Types		CO2		Provided		MR
6.	IS marking First – Aid Hose Reel	ISI mar	ked	P	rovided		MR
0.							
	 Total numbers on each floor Length of hose reel hose 		01		Provided		MR
	 Length of hose reel hose Nozzle diameter 	30 m 5 mm	30 m		Provided		MR
7.	Automatic fire detection and alarmin			P	rovided		MR
	Type of detectors	Smoke		Derecid			
	 Location of Main Panel 	Ground flo	205	Provide		MR	
	 Location of Repeater Panel 	NA	bor	Provide NA	đ	MR	
	 Alternate source of power 	Required		Provide	d	NA	
	 Hooters' Location 	Required		Provide		MR	
8.	MOEFA	Required					
9.	Public Address System	NA		Provide NA	a	MR	
10.	Automatic Sprinkler System					NA	
	 Basements 	NA		NA		NA	
	 Upper Floor 	NA	Provi	ded in res	staurant	NA	
	 Sprinkler above false 	NA		NA		NA	
11.	ceiling Internal Hydrants:						
	 Size of riser/down- comer Number of hydrants nes 	Required		Provide		MR	
	 Number of hydrants per floor 	01 No		Provide	d	MR	
	Hose Box	01 No		Drawida	,		
2.	Yard Hydrants	01110		Provide	d	MR	
	 Total number of hydrants 	NA		NA		NIA	
	 Hose Box 	NA		NA		NA NA	
3.	Pumping Arrangements:					INA	
	Ground Level	Provi	ded	al	terrac	. to	net.
	 Discharge of main pump 	2280 lpm	Pr	ovided	anno		MR
	Head of main pump	50 mtr		ovided			MR
	Number of main pumps looker pumps	01	Pr	ovided			MR
	 Jockey pump out put Jockey pump head 	180 lpm		ovided			MR
	 Standby Pump nead Standby Pump out put 	50 mtr		ovided			MR
	 Standby Pump Head 	2280 lpm 50 mtr		ovided			MR
	 Auto Staring/Manual 			ovided			MR
	stopping > Pump House Access	Required	Pr	ovided			MR
	Terrace level	Required	Pr	ovided			MR
	 Discharge of pump 						
	 Head of the pump 	450 lpm		ovided			MR
	 Power supply 	40 m		ovided			MR
	 Auto starting of pump 	Required		ovided			MR
	0 - FF	Required	Pro	ovided			MR

			115					
4.	Captive water Storage for fire fighting:							
	 Under ground tank capacity Draw off connection 	100,000 ltr	Provided	MR Provide				
	 Fire service inlet 	Required	Provided	MR lorg le				
	 Access to tank 	Required	Provided	MR				
		Required	Provided	MR				
5	 Overhead Tank capacity Exit Signage 	10, 000 litr	es Provided	MR				
16.	Provision of Lifts	Required	Provided	MR				
·.								
	Pressurization of Lift Shaft	NA	NA	NA				
	Pressurization of lift lobby	NA	NA	NA				
	 Communication in lift Car Eirmanication in lift Car 	Required	Provided	MR				
	 Fireman's Grounding Switch 	Required	Provided	MR				
	Lift Signage	Required	Provided	MR				
17.	Standby power supply	Required	DG Set	MR				
18.	Refuge Area		20.30					
	Total area	NA	NA	NA				
_	Location	NA	NA	NA				
19.	Fire control room							
	Detector system panel	NA	NA	NA				
	Flow Switch Panel	NA	NA	NA				
	PA System Panel	NA	NA	NA				
	 Battery backup 	NA	NA	NA				
_	Building Floor Plans	NA	NA	NA				
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	ABC fire extinguisher provided MR near electric panel					

NII-

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rules 2010.

- M/s Singh Sahib (Unit of Chef Bobby Foods Pvt. Ltd.) Located at T-1, T-2, T-3 & T-4, 1. 3rd floor, Manish link road, Plaza II. Plot No. 10, Sector - 5, Dwarka, New Delhi
- 2. The total covered area for restaurant =130M²
- 3. As per part IV, NBC-2016, table no 4.3 under clause 4.4.2.1 the occupant load for dining area and restaurant is 1.8. Accordingly the number of seats come out to be 72 (130/1.8=72.22 say 72) for whole restaurant.
- The total seating capacity comes out be 72. 4.

Signature of Inspecting Officer

Name Sh. Ved Pal Designation _____

10

Signature of Inspecting Officer Name Uday VIX Designation ADO/DWK