

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2022/SZ/ 493

Dated: 54 / / //2022

FIRE SAFETY CERTIFICATE

Certified that M/s Epicuria Food Court located at Lower Ground Floor, TDI Mall, Nehru place Metro Station, New Delhi 110019 comprised of Basement, Lower Ground Floor and Upper Ground Floor owned/occupied by unit of V Cubed have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 31/10/2022 in the presence of Mr. Sameer Sharma and that the premise is fit for occupancy class Group—D Assembly (Restaurant at Lower Ground Floor only) with effect from 64/1/2022 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on OY / 11 /2022 at New Delhi by

(ATUL OARG)

Copy to: -

 The DHO, (South Zone), Municipal Corporation of Delhi, Public Health Department, Jal Vihar Lajpat Nagar, New Delhi –110024. (MHA Portal ID 2022101519127 dated 16/10/2022)

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 7. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

1				The state of the s		
1	INSPECT	ION REPORT	आजादी	.1		
	Name & Address of the Building M/s Epicuria Food Court (V Cubed), at Lower Groun					
	- are Dunding		ll, Nehru place Metro			
		Delhi 110019	ii, ricina place micro	Station, 1107		
2	Type of Occupancy		bly Building (Fating ho	use)		
3	Building Comprised of	Group-D Assembly Building. (Eating house)				
4	Type of Case	Basement, Lower ground floor & upper ground floor				
5	Details of Previous NOC	New Case				
6	Fire Safety Directives Letter No	Nil F6/DFS/MS/2022/SZ/434 dated 29/09/2022 (TDI Mall NOC)				
	The Salety Directives Letter No					
7	Date of Image of					
8	Date of Inspection	31/10/2022				
9	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
10	Name & Designation of Officers	Mr. Sameer Sharma				
	from the building side					
11	Year of construction	2007				
11	Applicant letter No.	MHA Portal ID 2022101519127 dated 16/10/2022				
S. No.	M:					
). INO.	Standards on the frevention	NBC / BBL	Provided at Site	Remarks		
	and Fire Safety U/R 33	Requirements		MR/NMR		
1	Access to Building.	TDI Mall F6/DFS/MS/2022/SZ/434 dated 29/09/2022				
	Road width	Restt. within				
	Gate width	TDI Mall	Provided*	MR		
		I DI Mali	Provided*	MR		
	Width of internal road		Provided*	MR		
2	Number width time 6		Piovided.	MIK		
	Number, width, type & arrangement of exits.					
	a) Number of Staircase	Provided & Maintained by TDI Mall				
	Upper floors.	NA	Restt. at Lower GF	NA		
	Basement floor.	N/A	As above	N/A		
	b) Width of Staircase					
	> Upper floors	NA	d & Maintained by TDI			
	Basement floor		Restt. at Lower GF	NA		
	c) Protection of exits	N/A	As above	N/A		
	Fire check door	Provide	d & Maintained by TDI	Mall		
	> Pressurization	N/A	N/A	N/A		
		N/A	N/A	N/A		
	d) No. of continuous staircase to terrace	Required	One	MR		
	e) Width of corridor	N/A	N/A	N/A		
	f) Door size	1.50 mtr each	1.50 m each	MR		
3	Compartmentation.	Provided & Maintained by TDI Mall				
	Fire check door.			Mali		
		N/A	N/A	N/A		
	or electrical silaits.	N/A	N/A	N/A		
	Fire rating of shaft door.	N/A	2714			
			N/A			
	Water curtain	N/A		N/A		
	Fire dampers.		N/A	N/A N/A		
4	Fire dampers.	N/A	N/A N/A	N/A N/A		
4	Fire dampers. Smoke Management system.	N/A	N/A	N/A N/A		
4	Fire dampers. Smoke Management system. Basement	N/A Provide	N/A N/A d & Maintained by TDI	N/A N/A N/A Mall		
4	Fire dampers. Smoke Management system. Basement	N/A Provide 30 ACPH	N/A N/A d & Maintained by TDI N/A	N/A N/A N/A Mall		
	 Fire dampers. Smoke Management system. Basement Upper floors 	N/A Provide 30 ACPH	N/A N/A d & Maintained by TDI	N/A N/A N/A Mall		
	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers.	N/A Provide 30 ACPH	N/A N/A d & Maintained by TDI N/A	N/A N/A N/A Mall		
	 Fire dampers. Smoke Management system. Basement Upper floors 	N/A Provide 30 ACPH 12 ACPH	N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided	N/A N/A N/A Mall N/A MR		
	 Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers 	N/A Provide 30 ACPH 12 ACPH 06 Nos	N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided	N/A N/A N/A Mall		
	 Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types 	N/A Provide 30 ACPH 12 ACPH	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ -	N/A N/A N/A N/A Mall N/A MR		
	 Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers 	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO2	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03	N/A N/A N/A Mall N/A MR		
,	 Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided	N/A N/A N/A N/A Mall N/A MR MR		
,	 Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. 	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided	N/A N/A N/A N/A Mall N/A MR		
,	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor.	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall	N/A N/A N/A N/A Mall N/A MR MR MR		
3	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose.	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided tained by TDI Mall Provided*	N/A N/A N/A N/A Mall N/A MR MR MR MR		
5	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose.	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall	N/A N/A N/A N/A Mall N/A MR MR MR		
5	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided tained by TDI Mall Provided* Provided*	N/A N/A N/A N/A Mall N/A MR MR MR MR MR MR		
5	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided tained by TDI Mall Provided* Provided*	N/A N/A N/A N/A Mall N/A MR MR MR MR		
	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided tained by TDI Mall Provided* Provided*	N/A N/A N/A N/A Mall N/A MR MR MR MR MR MR		
	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system Type of detectors	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall Provided* Provided* Provided* Provided*	N/A N/A N/A N/A N/A Mall N/A MR MR MR MR MR MR MR MR MR		
5	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system Type of detectors Location of Main Panel	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm 5mm n. Provided & Ma	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall Provided* Provided* Provided* intained by TDI Mall Provided*	N/A N/A N/A N/A N/A Mall N/A MR		
5	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system Type of detectors Location of Main Panel	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm 5mm n. Provided & Ma	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall Provided* Provided* Provided* Provided*	N/A N/A N/A N/A N/A Mall N/A MR MR MR MR MR MR MR MR MR		
	Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers ISI Marking First Aid Hose Reels. Total numbers on each floor. Length of hose-reel hose. Nozzle Diameter Automatic fire detection & alarming system Type of detectors Location of Main Panel	N/A Provide 30 ACPH 12 ACPH 06 Nos ABC/CO ₂ ISI marked Provided & Main One 30m 5mm 5mm n. Provided & Ma	N/A N/A N/A d & Maintained by TDI N/A Exhaust Fans Provided 10 Nos ABC-07 & CO ₂ - 03 Provided Itained by TDI Mall Provided* Provided* Provided* intained by TDI Mall Provided*	N/A N/A N/A N/A N/A Mall N/A MR		



	Alternate source of power	Required	Provided*	MR		
	Hooter's location	Required	Provided*	MR		
8	MOEFA	Required	Provided	MR		
9	Public Address System	N/A	N/A	N/A		
10	Automatic Sprinkler System	Provided & Maintained by TDI Mail				
	Basement	Required	Provided*	MR		
	Ground floor.	Required	Provided*	MR		
	Sprinkler above false ceiling	Required	Provided*	MR		
11	Internal Hydrants.	Provided	& Maintained by T	DI Mall		
	Size of Riser/Down-comer	Required	Provided*	MR		
	Number of Hydrant per floor	Required	Provided*	MR		
	Hose box.	Required	Provided*	MR		
12	Yard Hydrants.	Required	11071000	1		
		Required	Provided*	MR		
	Total number of hydrants.		Provided*	MR		
13	Hose box.	Required	Flovided			
13	Pumping arrangements. • Ground Level Provided & Maintained by TDI Mall					
	Ground Level			MR		
	Discharge of main pump.	2280 LPM	Provided* Provided*	MR		
	Head of main pump.	70 m		MR		
	Number of main pumps.	02	Provided*	MR		
	Jockey Pump output.	280 &180 LPM	Provided*	MR		
	Jockey Pump head.Standby Pump output.	70 m	Provided* Provided*	MR		
	Standby Pump output.Standby Pump head.	2280 LPM		MR		
	Auto Starting/Manual Stopping.	70 m	Provided*	MR		
	 Pump house access. 	Required	Provided*	MR		
		Required	Provided*	IVIK		
	Terrace Level	27/4	27/4	N/A		
	Discharge of pump.	N/A	N/A	N/A N/A		
	Head of pump.	N/A	N/A	N/A N/A		
	Power supply.	N/A	N/A	N/A N/A		
	> Auto starting of pump.	N/A	N/A			
14	Captive water storage for fire fighting.	Provided & Maintained by TDI Mall 1,00,000 ltr Provided* MR				
	Underground tank capacity.	1,00,000 ltr	Provided*	MR		
	Draw-off connection.	Required	Provided*	MR		
	Fire Service Inlet.	Required	Provided*	MR		
	Access to tank.	Required 10,000 ltr	Provided*	MR		
	Overhead tank capacity.	Required	Provided	MR		
15	Exit Signage.		& Maintained by TD			
16	Provision of Lifts.	N/A	N/A	N/A		
	Pressurization of lift shaft.	N/A N/A	N/A N/A	N/A N/A		
	Pressurization of lift lobby. Communication in lift com	N/A N/A	N/A N/A	N/A N/A		
	Communication in lift car.	N/A N/A	N/A N/A	N/A N/A		
	Fireman's switch.					
	Lift signage.	N/A	N/A	N/A		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
9	Fire Control Room.		& Maintained by TD			
	Detector system panel.	Required	Provided*	MR		
	Flow switch panel.	Required	Provided*	MR		
	 PA system panel. 	Required	Provided*	MR		
	 Battery backup. 	Required	Provided*	MR		
	Building floor plan.	. N/A	N/A	N/A		
-	Special Fire Protection System for the					
0	Special Fire Protection System for the	N/A	N/A	N/A		

Note: - * Provided & Maintained by TDI Mall management.



M/s Epicuria Food Court (V Cubed), at Lower Ground Floor, TDI Mall, Nehru place Metro Station, New Delhi 110019

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Designation: ADO (BCP)

Dy. OFO (SZ)

F.T. tetter és portib