

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2022/EH/ 63

Dated 05//2/2022

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Invitation K located at Second Floor, North Gate Orbit Plaza Mall, Gujrawala Town Part-II, Delhi-110009 in the building comprised of Ground & 02 upper floors owned/occupied by M/s Invitation K have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 21.10.2022 in the presence of Mr. Mohit Kakkar and that the building/ premise is fit for occupancy Class "D" Assembly (Restaurant) for second floor only with effect from Ostro-for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Atul Garg)
Director

Ph-011-23414000

Copy to:-

1. M/s Invitation K located at North Gate, Gujrawala Town Part-II, Delhi-110009.

## Conditions for the validity of Fire Safety Certificate:

- 1 This Fire Safety Certificate is valid only for restaurant at second floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2 All the means of escape/entry/exit shall be kept free from any obstruction.
- 3 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 4 Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5 All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.
- 7 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 8 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

### INSPECTION REPORT

1. Name & address of the building : M/s Invitation K located at Second Floor at North Gate Orbit Plaza Mall,

Gujrawala Town, Part-II, Delhi-110009.

Type of Occupancy : (Assembly) Restaurant

3. Composition of building : Ground & two upper floors but restaurant is running at second floor only,

1. Type of Case : New Case

Details of previous NOC

1

Fire Safety directives letter No : Nil

7. Date of inspection

: 21.10.2022

: Nil

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side

: Mr. Mohit Kakkar

10. Year of Construction

: 2000

11. Applicant's letter No.

: Online I D No. 2022093018479 Dated: 13.10.2022

12. Total covered area

: 266sqm

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 requirements	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	06	12m approx	MR		
	Gate width	4.5m	4.5m	MR		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02	Provided by mall	MR		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper Floors	1.5m	Provided by mall	MR		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	<ul> <li>Pressurization</li> </ul>	NA	NA	NA		
	d. No. of continuous staircases to terrace	02	03	MR		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	1.5m	1.50m each	MR		
3	Compartmentation.					
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NΛ	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke Management System.					
	• Basements	12 a/c per hour	NA	NA		
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	Natural Ventilation	MR		
5	Fire Extinguishers					
	Total numbers	10nos	12nos	MR		
	•					

<ul> <li>ISI marking</li> <li>First-Aid Hose Reels.</li> <li>Total numbers on each floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> <li>Automatic fire detection and alarming system.</li> </ul>	Yes  Oleach floor  30m	Yes	MR MR		
<ul><li>Total numbers on each floor</li><li>Length of hose reel hose</li><li>Nozzle diameter</li></ul>			MR		
<ul><li>Length of hose reel hose</li><li>Nozzle diameter</li></ul>					
Nozzle diameter		Provided			
Nozzle diameter	20	· Tovided	MR		
		Provided	MR		
G J	5mm	Provided	MR		
Type of detectors	Required	Provided	MR		
Location of Main Panel	NA	NA	NA		
Location of Repeater Panel	NA	NA	NA		
	NA	NA	NA NA		
	NA	NA	NA		
	Required	Provided			
	NΛ	NA	MR NA		
NA NA					
<ul> <li>Basement</li> </ul>	NA				
Upper Floor			NA		
<ul> <li>Sprinkler above false ceiling</li> </ul>		Provided	MR		
nternal Hydrants	NA	NA	NA		
	100mm	Provided	MR		
	01	Provided	MR		
	01	Provided	MR		
Yard Hydrants.					
<ul> <li>Total number of hydrants</li> </ul>	NA	NA			
• Hose Box	NA		NA		
Pumping Arrangements.	1474	INA	NA		
Ground Level					
	N.				
			NA		
· · · · · ·			NA		
			NA		
> Jockey pump head			N/A		
Standby Pump out put			N/A		
<ul><li>Standby Pump Head</li></ul>			N/A		
Auto Starting/ Manual stopping Pump House Access	N/A	N/A	N/A		
	N/A	N/A	N/A		
Terrace level					
	450lpm	450lpm	MR		
			MR		
Auto Starting of pump			MR		
	Kequired	Provided	MR		
water Storage for fire fighting.					
	<ul> <li>Upper Floor</li> <li>Sprinkler above false ceiling</li> <li>nternal Hydrants</li> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> <li>Hose Box</li> <li>Yard Hydrants.</li> <li>Total number of hydrants</li> <li>Hose Box</li> <li>Pumping Arrangements.</li> <li>Ground Level</li> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> <li>Terrace level</li> <li>Discharge of pump</li> <li>Head of the pump</li> <li>Power Supply</li> </ul>	Hooters' Location  MOEFA  Public Address System.  Automatic Sprinkler System.  Basement Upper Floor Sprinkler above false ceiling NA  NA  Required NA  NA  NA  NA  NA  NA  NA  NA  NA  NA	Alternate source of power Hooters' Location  MOEFA Public Address System.  Basement Upper Floor Sprinkler above false ceiling NA NA NA NA NA Required Provided NA NA NA Required Provided Provided NA		

g						
	➢ Draw-off connection	NΛ	NA	NA		
	➤ Fire service inlet	NA	NΛ	NΛ		
	➤ Access to tank	NA	NA	ΝΛ		
	Overhead Tank capacity	20,000ltr	Provided	MR		
5	Exit Signage.	Required	Provided	MR		
6	Provision of Lifts.		and account to the			
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	NΛ	NΛ	NΛ		
	Fireman's Grounding Switch	Required	Provided by mall	MR		
	Lift Signage	Required	Provided by mall	MR		
7	Standby power supply	Required	Provided by mall	MR		
8	Refuge Area.					
	> Total Area	N/A	N/Λ	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	, N/A	N/A		
	<ul> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
0.	Special Fire Protection Systems for Protection of special Risks, if any:	NΛ	NΛ	NΛ		

- A. The total covered area of the second floor Restaurant is 266sqm (Approx) including seating area, kitchen area, toilet area, bar area.
- B. As per the NBC Part IV, the number of occupants comes out to be approx 148 person's i.e. (266/1.8=148)

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

#### Note:-

The mall is not having valid FSC, but this restaurant owner has provided all fire safety measures as required under law, separately. FSC is recommended subject to condition that it will be null & void in absence of electrical and water supply to dedicated fire protection Systems of restaurant if same is disconnected for mall building.

Do (MM) - CHO MIREST

DY CTO (MIZ)

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation: - ADO/RN

The fourth of but

A most guly most grt North

P.T.