



No. F6/DFS/MS/EH/WZ/2022/367

Dated: 30 / 12 /2022

FIRE SAFETY CERTIFICATE

Certified that the M/s Punjabi Grill restaurant (A unit of Lite Bite Foods Pvt. Ltd.), located at Shop No. TF 01, 3rd Floor, Pacific Mall, Subhash Nagar, New Delhi - 110018, in a building comprised of 02 Basement. Ground + 04 Upper Floors plus Projection Room. Owned/Occupied by M/s. Punjabi Grill restaurant (A unit of Lite Bite Foods Pvt. Ltd.), was issued FSC Vide Letter No. F6/DFS/MS/WZ/2019/EH/1717 dated 04/09/2019. The premises was re - inspected by the officers concerned of this department on 30/11/2022 in the presence of Sh. Rajesh Kumar Giri & have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and found that the said building is fit for occupancy class "Assembly" Group D with effect from for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

(Dharampal Bhardwa))
Dy. Chief Fire Officer

West Zone

Copy to: -

The Owner/occupier M/s Punjabi Grill (A unit of Lite Bite Foods Pvt. Ltd.), located at Shop No. TF 01, 3rd Floor, Pacific Mall, Subhash Nagar, New Delhi – 110018 (Online Id:- 2022102419371 dated 24/10/2022)

2. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhowest zone@gmail.com).

3. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (addlep.lic-dl@nic.in).

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management/occupier.
- 3. The trained staff should be available round the clock.
- 4. Basement shall be used as per building bye laws.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

5

INSPECTION REPORT

Name & address of the building

Punjabi Grill (A Unit of Lite Bite Foods Pvt. Ltd.) located at Shop No TF 01, 3rd Floor, Pacific Mall, Subhash Nagar.

New Delhi-110018.

Type of Occupancy

Assembly

Type of Case 3.

: Renewal

4. Details of previous NOC

: F6/DFS/MS/WZ/2019/EH/1717 dated 04/09/2019

5. Fire Safety directives letter No : NIL

Date of inspection

: 30/11/2022

7. Name of the Inspecting Officers : DO (W) & ADO (MN)

Name and designation of officers from the building side

: Sh. Rajesh Kumar Giri

9. Year of Construction

: 2011(As per prev. insp. report dated 22/08/2019)

10. Applicant's letter No.

: Application no. 2022102419371 dated 24/10/2022

The said restaurant is running at 3rd floor in pacific mall comprised of two basement, ground plus four upper floors plus projection room. FSC of mall was issued vide letter no. F6/DFS/MS/WZ/2020/267 dated 22/07/2020

	Minimum 6/7 dated 22/07/2020.				
	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMF	
	Access to building			WHOTHIN	
	Road width	12 m	Provided	MR	
	Gate width	5 m	On Main Road	MR	
	 Width of internal road 		NA		
	Number, Width Type & Armonas	NA 1 CF H	INA	NA	
	Number, Width, Type & Arrangement of Exits a. Number of staircases				
	Upper Floors	02	Dugaridad by M. 11) (D	
	Basements	NA NA	Provided by Mall NA	MR	
	b. Width of staircases	1874	NA	NA	
	Upper Floors	1.5mtr each	Provided by Mall	MR	
	Basements	NA NA	NA	NA	
	c. Protection of exits	1,,,,	NA .	INA	
	Fire check door	Required	Provided	MR	
	Pressurization	NA	NA	NA	
	e. No. of continuous staircases to terrace	NA	NA	NA	
	f. Width of Corridor	Required	Provided by Mall	MR	
	g. Door Size	2mX 1, 1.5m X 1	Provided	MR	
3	Compartmentation.	Common with the mall			
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
	Fire Dampers	NΛ	NA	NA	
	Smoke Management System	Common with the mall			
4	Basements	30 a/c per hour	Provided	MR	
	Upper floors	12 a/c per hour	Provided	MR	
	Fire Extinguishers				
5	Total numbers	06 nos.	Provided	MR	
		ABC, CO_2	Provided	MR	
	Types IS marking	ISI marked	Provided	MR	

		7-113		-
	First-Aid Hose Reels.	Common with the mal	1	
	 Total numbers on each floor 	01	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system. Common with the mall			
	Type of detectors	Smoke	Provided	MR
	 Location of Main Panel 	3 rd floor at restaurant lev		MR
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	Required		MR
	Hooters' Location	Required	Provided	MR
3	MOEFA	-	Provided	
<u> </u>	Public Address System.	Required	Provided	MR
10		Required for the mall	Provided	MR
	Automatic Sprinkler System.	Common with th		
	Basement Upper Florer	Required	Provided	MR
	 Upper Floor Sprinkler above false cailing 	Required	Provided	MR
	Springer above raise cerinig	Required	Provided	MR
11	Internal Hydrants	Common with the mal	I	
	 Size of riser/down-comer 	150mm	Provided	MR
	 Number of hydrants per floor 	01	Provided	MR
	Hose Box	Required	Provided	MR
12	Yard Hydrants. Common with the mall			
	 Total number of hydrants 	NA	Provided	NA
	Hose Box	NA	Provided	NA
13	Pumping Arrangements. Common with the mall			
	Ground Level			
	Discharge of main Pump	NR	2850 LPM	NR
	Head of Main pump	NR	60 m	NR
	Number of main pumps	NR	02	NR
	Jockey Pump out put	NR	180 LPM	NR
	Jockey pump head	NR	60 m	NR
	Standby Pump out put	NR	2850 LPM	NR
	> Standby Pump Head	NR	60 m	NR
	Auto Starting/ Manual stopping Pump House Access	NR	Provided	NR
	Tamp House Access	NR	Provided	NR
	 Terrace level Discharge of pump 	150.1	D	
	Discharge of pump	450 lpm	Provided	MR
	Head of the pump	50 m	Provided	MR
	Head of the pump Power Supply	Required	Provided	MR MR
14	Head of the pumpPower SupplyAuto Starting of pump	Required Required	Provided Provided	
14	Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting	Required Required g. Common with the man	Provided Provided	MR
14	 Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting Underground tank capacity 	Required Required g. Common with the management of the management	Provided Provided Provided	MR
14	 Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting Underground tank capacity Draw-off connection 	Required Required g. Common with the many NR NR	Provided Provided Provided Provided	MR MR
14	 Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting Underground tank capacity Draw-off connection Fire service inlet 	Required Required g. Common with the many of the many	Provided Provided Provided Provided Provided Provided	MR MR NR
14	 Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting Underground tank capacity Draw-off connection Fire service inlet Access to tank 	Required Required g. Common with the many of the many	Provided Provided Provided Provided Provided Provided Provided	MR MR NR NR NR
14	 Head of the pump Power Supply Auto Starting of pump Captive Water Storage for fire fighting Underground tank capacity Draw-off connection Fire service inlet 	Required Required g. Common with the many of the many	Provided Provided Provided Provided Provided Provided	MR MR NR NR

N	1	ı	4

	Provision of Lifts.	Common with the	mall		
	Pressurization of Lift Shaft	NA	Provided	NA	
	Pressurization of Lift lobby	NΛ	Provided	NA	
	Communication In lift Car	NΛ	Provided	NΛ	
	 Fireman's Grounding Switch 	NA	Provided	NΛ	
	Lift Signage	NΛ	Provided	NA	
7	Standby power supply	Required	Provided	MR	
8	Refuge Area. Common with the mall				
	➤ Total Area	NΛ	NA	NA	
	> Location	NΛ	NA	NA	
9	Fire Control Room Common with the mall				
	Detector System Panel	NA	Provided	NA	
	 Flow Switch Panel 	NA	Provided	NA	
	 PA System Panel 	NA	Provided	NA	
	Batter backup	NA	Provided	NA	
	Building Floor Plans	NA	Provided	NA	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Provided	MR	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/WZ/2019/EH/1717 dated 04/09/2019 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name: - M. K. Chattopadhyay

Signature of the Inspecting Officer Name: - Sarabjeet Singh Designation: - DO (West) Designation: - ADO (MN)

Sir, At was a typical center, it is 2m&1.5m in requirement & provided by restaurant is 1x 210 cm, 1x 160 cm & 1x 1.1m. Accordingly necessary Corrocknis made in the Imp. performa. Submitted plants