GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI IEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/ 29

Dated 3.1. / 0.1./2023

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s NIK BAKERS located at S-24. Ground Floor, Green Park, New Delhi 110016 in the building comprised of Basement, Ground plus Two Upper Floors owned/occupied by A Unit of MG Bakers Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2020/SZ/37 dated 07/02/2020. The restaurant premise was re-inspected by the officer concerned of this department on 23/01/2023 in the presence of Mr. Barish Uddin and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly ..31....04...2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions ander rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 3/2/2023 at New Delhi by

## (SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

Copy to: -

 The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016 (Ref. MHA Portal 2022122821937 dated 13/01/2023)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. The basement shall be used as per the provisions of BBL /NBC Part- IV.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

(17

Comprised of Comprised of Case Previous NOC y Directives Letter No spection the Inspecting Officers Designation of Officers Designation of Officers Duilding side Distruction letter No. <b>In standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width /idth of internal road width, type & arrangement of ex	S-24, Ground Floo Group–D Assembl Basement, Ground Renewal F6/DFS/MS/EH/20 Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ref	S (Unit of MG Bake r, Green Park, New 1 y Building. (Eating 1 + Two upper floor )20/SZ/37 dated 07/0	Delhi 1100 House) 02/2020 Dor only
Comprised of Case Previous NOC y Directives Letter No Ispection the Inspecting Officers Designation of Officers Duilding side Donstruction letter No. <b>a standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width Vidth of internal road width, type & arrangement of ex	S-24, Ground Floo Group–D Assembl Basement, Ground Renewal F6/DFS/MS/EH/20 Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ru MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	r, Green Park, New 1 y Building. (Eating 1 + Two upper floor )20/SZ/37 dated 07/0 O (BCP) unning at Ground Flo 2122821937 dated	Delhi 1100 House) D2/2020 Dor only 13/01/202
Comprised of Case Previous NOC y Directives Letter No Ispection the Inspecting Officers Designation of Officers Duilding side Donstruction letter No. <b>a standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width Vidth of internal road width, type & arrangement of ex	Basement, Ground Renewal F6/DFS/MS/EH/20 Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ru MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	+ Two upper floor )20/SZ/37 dated 07/( O (BCP) unning at Ground Flo 2122821937 dated	02/2020 Dor only 13/01/202
Previous NOC         y Directives Letter No         uspection         the Inspecting Officers         Designation of Officers         puilding side         onstruction         letter No.         n standards on Fire Prevention         Safety U/R 33         Building.         oad width         ate width         /idth of internal road         width, type & arrangement of ex	Renewal F6/DFS/MS/EH/20 Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Re MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	D20/SZ/37 dated 07/0 O (BCP) unning at Ground Flo 2122821937 dated	por only 13/01/202
Previous NOC y Directives Letter No spection the Inspecting Officers Designation of Officers Duilding side Distruction letter No. <b>a standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width //idth of internal road width, type & arrangement of ex	F6/DFS/MS/EH/20 Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ra MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	O (BCP) unning at Ground Flo 2122821937 dated	por only 13/01/202
y Directives Letter No ispection the Inspecting Officers Designation of Officers Duilding side Donstruction letter No. <b>a standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width vidth of internal road <b>width, type &amp; arrangement of ex</b>	Nil 23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ru MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	O (BCP) unning at Ground Flo 2122821937 dated	por only 13/01/202
Ispection the Inspecting Officers Designation of Officers Duilding side Dustruction letter No. <b>n standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width /idth of internal road width, type & arrangement of ex	23/01/2023 DO (South) & AD Mr. Barish Uddin 2007 Restt. Ru MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	unning at Ground Flo 2122821937 dated	13/01/202
the Inspecting Officers Designation of Officers Duilding side Instruction I etter No. In standards on Fire Prevention Safety U/R 33 Building. Oad width ate width /idth of internal road width, type & arrangement of ex	DO (South) & AD Mr. Barish Uddin 2007 Restt. Re MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	unning at Ground Flo 2122821937 dated	13/01/202
Designation of Officers Duilding side Onstruction letter No. <b>a standards on Fire Prevention</b> <b>Safety U/R 33</b> <b>Building.</b> oad width ate width /idth of internal road width, type & arrangement of ex	Mr. Barish Uddin 2007 Restt. Ru MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	unning at Ground Flo 2122821937 dated	13/01/202
building side construction letter No. a standards on Fire Prevention Safety U/R 33 Building. oad width ate width /idth of internal road width, type & arrangement of ex	2007     Restt. Rest.       MHA Portal 2022       As per Old Noc       Requirements	2122821937 dated	13/01/202
Instruction Ietter No. In standards on Fire Prevention Safety U/R 33 Building. Oad width ate width Yidth of internal road width, type & arrangement of ex	MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	2122821937 dated	13/01/202
a standards on Fire Prevention Safety U/R 33 Building. oad width ate width /idth of internal road width, type & arrangement of ex	MHA Portal 2022 As per Old Noc Requirements As per MPD-2021	2122821937 dated	13/01/202
a standards on Fire Prevention Safety U/R 33 Building. oad width ate width /idth of internal road width, type & arrangement of ex	As per Old Noc Requirements As per MPD-2021		
Safety U/R 33 Building. oad width ate width /idth of internal road width, type & arrangement of ex	Requirements As per MPD-2021	Provided at Site	Remark
Building. oad width ate width /idth of internal road width, type & arrangement of ex	As per MPD-2021		
oad width ate width /idth of internal road width, type & arrangement of ex			MR/NM
ate width /idth of internal road width, type & arrangement of ex			
/idth of internal road width, type & arrangement of ex	N/A	06 mtr	MR
width, type & arrangement of ex		N/A	N/A
	N/A	N/A	N/A
	its.		
ber of Staircase			
pper floors.	N/A	N/A	N/A
asement floor.	N/A	N/A	N/A
h of Staircase		IWA	. IN/A
pper floors	NA	2 0 1 50	
asement floor		2m & 1.50 m	MR
ction of exits	N/A	N/A	N/A
ire check door			
ressurization	N/A	N/A	N/A
f continuous staircase to terrace	N/A	N/A	N/A
h of corridor	N/A N/A	Provided	N/A
size	02 m & 1.50 mtr	N/A	N/A
mentation.	02 m & 1.50 mm	Provided	MR
re check door.	Required	Provided	MR
ealing of electrical shafts.	N/A	N/A	N/A
re rating of shaft door.	N/A	N/A	N/A
vater curtain	N/A	N/A	N/A
re dampers.	N/A	N/A	N/A
anagement system.			
asement	NA	N/A	N/A
pper floors	12 ACPH	Provided	
nguishers.			MR
otal numbers	Required	06 21	
/pes			MR
r			MR
	151 marked	Provided	MR
I Marking			
I Marking Hose Reels.	One near Restt.	Provided	MR
ota	l numbers rs Marking	uishers.     Required       I numbers     Required       vs     ABC/CO2       Marking     ISI marked       ose Reels.     ISI marked	aishers.     Required     06 Nos       I numbers     Required     06 Nos       rss     ABC/CO2     ABC- & CO2       Marking     ISI marked     Provided       ose Reels.     One near Restt.     Image: Control of the second secon

R

	• Length of hose-reel hose.	30m	Provided	MR
	Nozzle Diameter	5mm	Provided	MR
7		ystem.		
/	Type of detectors	N/A	N/A	N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A
	<ul> <li>Hooter's location</li> </ul>	N/A	N/A	N/A
0		Required	Provided	MR
8	MOEFA	N/A	N/A	N/A
9	Public Address System			10/1
10	Automatic Sprinkler System		N/A	N/A
	• Basement	N/A	N/A N/A	
	• Ground/ upper floors.	N/A		N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	• Number of Hydrant per floor	One	Provided	MR
	• Hose box.	One	Provided	MR
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level			
	<ul> <li>Discharge of main pump.</li> </ul>	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	<ul> <li>Discharge of pump.</li> </ul>	450 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	<ul> <li>Fireman's switch.</li> <li>Lift signage.</li> </ul>	N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR

NIT

20

MP tha

2

N/8



18	Refuge Area			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room.			
	• Detector system panel.	N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A
	• PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	<ul> <li>Building floor plan.</li> </ul>	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2020/SZ/37 dated 07/02/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

mil

Jul 2023

Signature of the Inspection Officer Name Sh. Manoj Kumar Sharma Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

Dy. CFO (SZ)

महोत्र

7.1

s approved, F.T. tettel il pontup ner signature Pl.

Fol

M.S.ll ylaadud ylaa